

## SSO Notification List

August 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	8/1/2016	1901 Falls Rd	21211	Rags, Rain, Trash, Sand, Gravel, Rocks	WVO	Jones Falls	N/A	Gray Debris	500	Cleaned and removed debris from manhole and stream	Unable to CCTV	326782
2	8/2/2016	38 N Bentalou St	21223	Rags	WVO	N/A	117	Paper and muck overflowing	234	Relieved house connection choke with 4 ft of electric machine on 6" line	CCTV	327071
3	8/2/2016	2248 Brookfield Ave	21217	Rags, Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	N/A	Gray water and debris	Evidence of Overflow	Ran 60 ft of electric machine to relieve house connection choke	CCTV	327365
4	8/2/2016	4000 Belair Rd	21213	Rain, I/I	WVO	N/A	N/A	Toilet paper and debris	250	Cleaned affected area and replace manhole cover	Will monitor location during heavy rain events	327198
5	8/2/2016	6205 Green Meadow Way	21209	Rain, I/I, Trash, Sand, Gravel, Rocks	WVO	N/A	N/A	Paper and evidence	150	Pressure truck flushed mainline and cleaned area	CCTV	327240
6	8/2/2016	N Pine St and W Saratoga St	21201	Rain	WVO	Middle Branch	180	Sewage discharging from manhole	54,000	Waited for rain event to subside	No CCTV, will monitor location during rain events	327121
7	8/3/2016	1326 N Broadway	21213	Rags, Trash, Sand, Gravel, Rocks	WVO	Inner Harbor	781	Sewer water overflowing	3,905	Cleaned line with 214 ft of pressure hose	CCTV	327527
8	8/3/2016	Manhattan Ave and Park Heights Ave	21215	Rags, Grease	WVO	N/A	77	Gray water overflowing	154	Relieved mainline choke with 400 ft of pressure truck on 10" line	CCTV	327615
9	8/3/2016	1700 Ruxton Ave	21216	Pipe Break	DWO	Gwynns Falls	8,765	Clear water with sewer smell	4,383	Intermittent issue which was identified and repaired	Source of leak identified and resolved	327560
10	8/8/2016	1222 Shellbanks Rd	21225	Rags, Grease	DWO	N/A	518	Murky water and wet paper	1,554	Sewer water coming from the house connection on the side of the building, turned over to housing authority.	Clean out was repaired and replaced.	328778
11	8/8/2016	1661 Gwynns Falls Pkwy	21217	Roots, Grease	DWO	N/A	84	Gray water overflowing	336	Relieved mainline choke with 250 ft of pressure hose	Mainline CCTV	328990
12	8/8/2016	1911 W Mulberry St	21223	Rags, Grease	DWO	N/A	N/A	Evidence and debris	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6 in line	House lateral CCTV	328671
13	8/9/2016	1700 Moreland Ave	21216	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	99	Clear water that smells like sewage	297	Relieved mainline choke with 50 ft of pressure truck on 8 in line	CCTV	329218
14	8/10/2016	1900 Eagle Dr	21207	Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	N/A	Gray water and debris	Evidence of Overflow	Relieved mainline choke with 100 ft of pressure machine hose	CCTV	329934
15	8/14/2016	6301 Park Heights Ave	21215	Trash, Sand, Gravel, Rocks	DWO	N/A	N/A	Gray water and debris	Evidence of Overflow	Relieved house connection choke with 250 ft of electric machine	Lateral CCTV	330614
16	8/15/2016	3000 Chestnut Ave	21211	Rags, Roots, Grease	WVO	N/A	125	Sewage running out of wooded area	625	Relieved mainline choke with 300 ft of pressure truck on 8" line	Cleaned mainline and removed roots	330755

## SSO Notification List

August 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	8/15/2016	SSO #152-N Charles St and W Lanvale St	21201	Rain	WWO	Jones Falls	30	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	38,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project	
18	8/16/2016	2207 S Newkirk St	21224	Other	DWO	Patapsco River	88	Sewer bypass hose leaking onto street	8.8	Contractor repaired hole in leaking pump hose.	Leaking hose was repaired	
19	8/17/2016	1013 W 37th St	21211	Rags, Roots	WWO	N/A	N/A	Wet around clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	Lateral CCTV	331607
20	8/17/2016	SSO #67-1901 Falls Rd	21217	Rain	WWO	Jones Falls	120	Structure monitored by metering equipment in the pipe	253,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project	
21	8/17/2016	SSO #72-428 E Preston St	21202	Rain	WWO	Jones Falls	185	Structure monitored by metering equipment in the pipe. Not visually observed.	833,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project	
22	8/17/2016	SSO #152-N Charles St and W Lanvale St	21202	Rain	WWO	Jones Falls	95	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	134,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project	
23	8/17/2016	SSO #154-N Charles St and W Lafayette Ave	21201	Rain	WWO	Jones Falls	30	Structure monitored by metering equipment in the pipe. Not visually observed.	130,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project	
24	8/17/2016	W Saratoga St and Martin Luther King Blvd	21201	Pipe Break	WWO	Inner Harbor	318	Sewage overflowing from manhole due to heavy rain and broken sewer main	222,600	Heavy rain event subsided, sewage no longer overflowing	Contractor is working on repairing broken lines in the area	
25	8/18/2016	1102 Bethlehem Ave	21224	Grease, Trash, Sand, Gravel, Rocks	WWO	Northwest Harbor	N/A	Paper and debris	Evidence of Overflow	line with 30 ft of electric machine, used cutter to removed roots	Lateral CCTV inspection	331800
26	8/18/2016	1500 N Chapel St	21213	Pipe Break	WWO	Inner Harbor	8,399	Waste water leaving this asset and entering storm drain. Confirmed with dye test. Found by OCAL during routine sampling	83,990	Overflow has been abated. Leaking pipe was repaired by on call contractor	On call contractor CCTV'd and repaired leaking sewer line.	332062
27	8/20/2016	4302 Maine Ave	21207	Roots	DWO	N/A	N/A	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 30 ft of pressure hose	Lateral CCTV inspection	332371
28	8/21/2016	838 Herndon Ct	21225	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Curtis Bay	76	Heavy paper and debris	1,140	Jetted line with 70 ft of pressure truck to relieve mainline choke	Mainline CCTV inspection	332436
29	8/21/2016	SSO #152-N Charles St and W Lanvale St	21201	Rain	WWO	Jones Falls	25	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	21,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project	
30	8/21/2016	W Saratoga St and N Pine St	21201	Rain, Pipe Break	WWO	Inner Harbor	31	Sewage flowing out of eyes of manhole	1,550	Sewage overflowing from manhole due to heavy rain and broken sewer main	Heavy rain event subsided, sewage no longer overflowing	
31	8/22/2016	2011 Linden Ave	21217	Rags, Grease, Pipe Break	WWO	Jones Falls	112	Gray water overflowing from manhole	560	Relieved mainline choke with 100 ft of pressure hose on 8" line	Mainline CCTV inspection	332669

