

SSO Notification List

December 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	12/1/2016	2518 Druid Park Ave	21215	Rags, Trash, Structural	WWO	Jones Falls	45	Gray water overflowing.	675	Relieved mainline choke with 100 ft of pressure truck on 8 in line.	Turned over to construction.	369479
2	12/2/2016	3700 Bayonne Ave	21206	Rags	WWO		0	Paper and gray water	10	Relieved house connection choke with 60 ft of electric machine	House lateral CCTV inspection.	396758
3	12/2/2016	401 Overhill Rd	21210	Rags, Roots	WWO		94	Gray water overflowing.	470	Relieved mainline choke with 95 ft of pressure truck on 6 in line.	Mainline CCTV inspection.	369896
4	12/3/2016	4707 Fredrick Ave	21229	Rags, Grease	WWO		0	Sewage and toilet paper visible.	10	Relieved choked clean out 55 ft of electric cable.	House lateral CCTV inspection.	370114
5	12/4/2016	2014 Breitwert Ave	21230	Rags, Roots	WWO		0	Toilet paper and roots	5	Relieved house connection choke with 45 ft of electric cable.	House lateral CCTV inspection.	370196
6	12/6/2016	312 N Martin Luther King Jr Blvd	21201	Rags, Trash	WWO		0	Toilet paper	20	Relieved house connection choke with 45 ft of electric machine	House lateral CCTV inspection.	307793
7	12/7/2016	619 Lucia Ave	21229	Rags, Roots	WWO		0	Gray water and debris.	20	Relieved house connection choke with 60 ft of electric machine.	House lateral CCTV inspection.	371288
8	12/8/2016	York Rd and E Coldspring Ln	21212	Rags, Trash	WWO	Tiffany Run	60	Mainline choke causing subsurface wastewater infiltration into storm drain. This was found during OCAL routine monitoring.	1,369	Relieved mainline choke with 400 ft of pressure machine.	Mainline CCTV inspection at this location.	371711
9	12/8/2016	245 N Monastery Ave	21229	Rags, Grease, Trash	WWO	Gwynns Falls	147	Gray water overflowing	294	Relieved mainline choke with 300 ft of pressure truck on 8 in and 10 in lines.	Mainline CCTV inspection.	371489
10	12/8/2016	5024 Denview Way	21206	Rags, Grease	WWO		0	Gray water and debris visible.	250	Relieved mainline choke with 400 ft of pressure machine hose, mainline clear.	Mainline CCTV inspection.	371497
11	12/8/2016	1300 Ramblewood Rd	21239	Rags, Roots	WWO		87	Gray water overflowing from clean out.	87	Relieved house connection choke with 30 ft of electric machine.	Mainline cleaning and mainline CCTV inspection.	371763
12	12/9/2016	4100 Windsor Mill Rd	21216	Rags, Roots	WWO		84	Sewer water overflowing from manhole.	168	Relieved mainline choke with 40 ft of pressure truck on 10 in line	Mainline CCTV inspection.	371891
13	12/9/2016	6541 Eastern Ave	21224	Rags, Grease, Trash	WWO		215	Gray water and grease	1,075	Relieved mainline choke with 300' of pressure hose.	Mainline CCTV inspection.	371972
14	12/12/2016	1800 Park Ave	21217	Rags, Roots, Trash	WWO		211	Gray water overflowing from side of manhole.	2,110	Relieved mainline choke with 10 ft of pressure truck on 10 in line.	Mainline CCTV inspection.	372507
15	12/12/2016	620 S Newkirk Ave	21224	Rags, Roots, Trash	WWO		0	Gray water and debris.	10	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV inspection.	372630
16	12/13/2016	2563 Marbourne Ave	21230	Rags, Roots	WWO		0	Gray water and debris	8	Relieved house connection choke with 30 ft of electric machine on 6" line.	House lateral CCTV inspection.	372697
17	12/14/2016	2781 Wilkens Ave	21223	Rags, Trash	WWO		0	Gray wastewater and debris around manhole.	50	Cleaned mainline and removed debris from manhole cover.	Mainline CCTV inspection.	373060
18	12/14/2016	2801 Frederick Ave	21223	Rags, Trash	WWO		0	Gray sewage and debris on and around the manhole.	60	Cleaned mainline and removed debris from the manhole cover.	Mainline CCTV inspection.	373063

SSO Notification List

December 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
19	12/14/2016	5621 Belair Rd	21206	Rags, Grease, Trash	WWO		0	Gray water and grease.	20	Relieved house connection choke with 45 ft of electric machine.	Lateral CCTV inspection.	373051
20	12/16/2016	W Patapsco Ave and Potee St	21225	Rags, Grease, Trash	DWO		132	Sewer water overflowing.	264	Relieved mainline choke with 100 ft of pressure machine hose.	Mainline CCTV inspection.	373632
21	12/18/2016	2700 Boston St	21224	Rags, Grease, Trash	WWO	Harbor	258	Gray water overflowing from manhole.	1,290	Relieved mainline choke with 200 ft of pressure machine hose.	Mainline CCTV inspection.	373781
22	12/19/2016	401 Overhill Rd	21210	Rags, Roots	WWO		128	Gray water overflowing from eyes of manhole.	640	Relieved mainline choke with 300 ft of pressure truck on 6 in line.	Mainline CCTV inspection.	373850
23	12/19/2016	5111 N Charles St	21210	Roots	WWO	Jones Falls	107	Murky colored water overflowing from manhole.	535	Relieve mainline choke with pressure truck, no longer overflowing.	Mainline CCTV inspection.	373875
24	12/19/2016	10 E 22nd St	21218	Sand, Gravel, Rocks, Structural	WWO		0	Gray water and rocks.	0	Ran 60 ft of electric machine, washed down area with pressure hose.	Refer to construction for repairs.	373703
25	12/20/2016	Colvin St and E Lexington St	21202	Grease, Trash	WWO	Harbor	194	Found manhole overflowing	1,940	Relieved mainline choke with 400' of pressure machine hose.	Mainline CCTV inspection.	374282
26	12/22/2016	334 S Calhoun St	21223	Rags, Grease, Trash	DWO		201	Heavy gray water overflowing from manhole.	1,005	Relieved mainline choke with 300 ft of pressure truck on 8 in line.	Mainline CCTV inspection.	374592
27	12/22/2016	6303 Lincoln Ave	21209	Rags, Roots	DWO		0	Sewage and signs of overflow.	3	Relieved house connection choke with 45 ft of electric machine on 6 in line.	Mainline CCTV inspection.	374742
28	12/22/2016	4000 Groveland Ave	21215	Rags, Roots, Trash	DWO		793	Gray water overflowing from clean out	793	Relieved house connection choke with 75 ft of electric machine.	House lateral CCTV inspection.	374892
29	12/26/2016	1308 Asbury Rd	21209	Rags, Trash	WWO		0	Dampness, signs of an overflow.	10	Private plumber relieved choke with 60 ft of electric machine.	House lateral CCTV inspection.	375229
30	12/27/2016	4000 Groveland Ave	21215	Rags	WWO		0	Gray water and debris	5	Relieved house connection choke with 60 ft of electric machine on 6" line	House lateral CCTV inspection	375284
31	12/28/2016	2700 Frederick Ave	21223	Rags, Roots, Trash	WWO		91	Gray water overflowing.	1,365	Relieved mainline choke with 200 ft of pressure truck on 8 in line.	Mainline CCTV inspection.	375506
32	12/29/2016	2257 Cedley St	21230	Rags, Trash	WWO		142	Toilet paper and debris.	284	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV inspection.	375902
				# WWO	28			TOTAL	14,845	UNDER 100 GALLONS	15	