

SSO Notification List

January 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2017	1011 W 37th St	21211	Rags	WWO		0	Gray water and debris in alley.	15	Relieved house connection choke with 45 ft of electric machine on 6 in line.	House lateral CCTV inspection.	376325
2	1/1/2017	4707 Frederick Ave	21229	Rags	WWO		0	Gray water and debris visible around clean out.	8	Relieved house connection choke with 35 ft of electric machine on 6 in line.	House lateral CCTV inspection.	376333
3	1/1/2017	200 East St (Private)	21202	Rags, Grease, Trash	WWO		0	Sewage and debris.	30	Relieved mainline choke with 100 ft of pressure truck on 12 inch line.	Mainline CCTV inspection.	376322
4	1/2/2017	Belair Rd and Shannon Dr	21213	Rags, Roots, Trash	WWO	Herring Run	197	Gray water overflowing in park.	1,970	Relieved mainline choke with 150 ft of pressure truck on 8 inch.	Mainline CCTV inspection.	376400
5	1/2/2017	839 W Ramsay St	21230	Rags, Roots, Trash	WWO		0	Toilet Paper	5	Relieved house connection choke with 45 ft of electric machine.	House lateral CCTV inspection.	376429
6	1/3/2017	510 S Kenwood Ave	21224	Rags, Trash	WWO		0	Toilet paper and debris	10	Relieved house connection choke with 7 ft of electric machine.	House lateral CCTV inspection.	376707
7	1/3/2017	2610 Oswego Ave	21215	Rags, Roots, Trash	WWO		0	Toilet paper and sewage around the house connection.	8	Relieved house connection choke with 30 ft of electric machine.	Mainline CCTV inspection.	376723
8	1/4/2017	421 Westgate Rd	21229	Rags, Roots, Trash	WWO		78	Dampness	78	Relieved house connection choke with 30 ft of electric machine.	House lateral CCTV inspection.	376934
9	1/6/2017	5800 Greenspring Ave	21209	Rags, Roots, Trash	WWO		96	Heavy gray water coming out of manhole.	480	Relieved mainline choke with 100 ft of pressure truck on 8 in line.	Mainline CCTV inspection.	377171
10	1/6/2017	2565 Marbourne Ave	21230	Rags	WWO		0	Gray water and evidence around the clean out.	7	Relieved house connection choke with 30 ft of electric machine on 6 inch	House lateral CCTV inspection	377216
11	1/6/2017	1425 Townway	21202	Roots, Other	WWO		0	Toilet paper and debris	8	Relieved house connection choke with 45 ft of electric cable.	House lateral CCTV inspection	377258
12	1/6/2017	351 Gwynn Ave	21229	Roots	WWO		0	Evidence visible around the clean out	5	Relieved house connection choke with 60 ft of electric cable on 6 inch line	House lateral CCTV inspection	377374
13	1/9/2017	2325 Hollins St	21223	Rags	DWO		108	Gray water coming from the clean out.	216	Relieved house connection choke with 40 ft of electric machine.	House lateral CCTV inspection.	377785
14	1/9/2017	Lipps Ln and S Warwick Ave	21223	Rags, Grease, Trash	DWO	Gwynns Falls	134	Heavy gray water overflowing from manhole.	670	Relieved mainline choke with 150 ft of pressure truck on 10 in line.	Mainline CCTV inspection.	377898
15	1/10/2017	4120 Mariban Ct (Private)	21225	Grease, Trash	WWO		0	Gray water overflowing	100	Relieved mainline choke with 300 ft of pressure truck on 8 in.	Mainline CCTV inspection.	378243
16	1/11/2017	4722 York Rd	21212	Rags, Grease, Trash	WWO	Tiffany Run	80	Subsurface overflow, sewage from choked sanitary is getting into nearby storm drain system.	400	Jetted line with 100 ft of pressure hose to relieve mainline choke.	Mainline CCTV inspection.	378520
17	1/12/2017	125 N Ann St	21231	Rags, Trash	WWO	Harbor	305	Paper, rags and debris	3,050	Jetted 8 inch sanitary line with 300 ft of pressure hose to relieve mainline choke.	Mainline CCTV inspection.	378861
18	1/12/2017	4122 Marx Ave	21206	Rags, Grease, Trash	WWO	Herring Run	48	OCAL through routine sampling and pollution tracking programs found a choked sanitary. The choked sanitary is causing a subsurface sanitary sewer overflow to nearby storm drain system.	48	Jetted line with 150 ft of vactor truck	Mainline CCTV inspection	378833
19	1/12/2017	2508 Druid Park Dr	21215	Rags, Roots	WWO		0	Gray water and debris	5	House connection choke not relieved, cable is caught up in line. Turned over this location to construction.	Sanitary connection will be repaired.	378901

SSO Notification List

January 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	1/12/2017	2002 Brunt St (Private)	21217	Sand, Gravel, Rocks, Structural	WWO		229	Gray Water overflowing from house connection	229	Ran 30 ft of electric cable with H-Cutter to try and relieve house connection choke.	Plumber has been contacted to fix improperly installed house connection.	378932
21	1/13/2017	York Rd and E Coldspring Ln	21212	Rags, Trash, Other	WWO	Tiffany Run	109	Manhole at E. Coldspring & York Rd is holding causing a subsurface overflow found by OCAL during routine monitoring. Call OCAL Mike 443-826-2964 for any questions.	2,725	Used 250 ft of pressure jet to relieve the mainline choke.	Mainline CCTV inspection.	379071
22	1/13/2017	4104 Norfolk Ave	21216	Rags	WWO		0	Gray water and debris around the clean out.	10	Relieved house connection choke with 30 ft of electric machine on 6 in line.	External clean out needs to be installed.	379067
23	1/15/2017	3705 W Belvedere Ave	21215	Rags, Roots	WWO		0	Toilet paper and rags.	15	Relieved house connection choke with 45 ft of electric cable.	House lateral CCTV inspection.	379289
24	1/15/2017	3700 Echodale Ave	21206	Rags, Trash	WWO		0	Rags and debris with toilet paper	8	Relieved house connection choke with 30 ft of electric cable.	House lateral CCTV inspection.	379303
25	1/16/2017	Edgewood Rd and Wabash Ave	21216	Rags, Grease, Sand, Gravel, Rocks, Structural	WWO		412	Overflowing out of eye of sewer manhole cover	1,648	Manhole is still holding water, no longer overflowing. Bypass pumping is needed at this location.	Bypass pumping initiated.	379416
26	1/16/2017	3700 E Baltimore St	21224	Rags, Grease, Trash	WWO		227	Gray water and sewage overflowing.	454	Partially relieved mainline choke turned over to vac truck.	Cleaned mainline to help prevent overflows.	379460
27	1/17/2017	2116 N Wolfe St	21213	Rags, Grease, Trash	WWO		102	Gray water and debris overflowing from manhole.	204	Used 200 ft of pressure machine to relieve mainline choke.	Cleaned 8 in. sanitary line and performed mainline CCTV inspection.	379712
28	1/18/2017	Benninghaus Rd and Ready Ave	21212	Rags, Grease, Infiltration, Trash	WWO		207	A choked sanitary mainline is causing a subsurface sewer overflow into the storm drain system. Found during OCAL routine sampling.	1,035	Flushed and cleaned 8" mainline with 120' of pressure hose.	Mainline CCTV inspection	379977
29	1/20/2017	247 N Bruce St	21223	Rags, Trash	WWO		0	Toilet paper and sewage	10	Relieved choke with 45 ft of electric machine on 6 in line	Cleaned the mainline at this location.	380340
30	1/20/2017	2042 E Baltimore St	21231	Rags, Trash	WWO	Harbor	0	Toilet paper and debris.	10	Relieved house connection choke with 30 ft of electric cables and H-Cutter	Cleaned line to prevent future overflows.	380415
31	1/21/2017	1400 Eastern Ave	21231	Grease	WWO		91	Heavy gray water	455	Relieved mainline choke with 300 ft of pressure truck on 8 in line.	Cleaned the mainline to prevent future overflows.	380722
32	1/23/2017	212 N Streeper St	21224	Infiltration, Sand, Gravel, Rocks, Structural	WWO		110	Gray water overflowing	220	Relieved mainline choke with 85 ft of pressure truck on 8 inch line.	Mainline cleaning and CCTV inspection.	380988
33	1/23/2017	1910 Cecil Ave	21218	Infiltration, Sand, Gravel, Rocks, Structural	WWO		0	Gray Water and debris visible	0	Left plumbers notice to repair cracked pipe inside property line. Ran 30' electric machine to try and relieve choke.	Notified consumer of cracked pipe. Plumber will repair.	381087
34	1/25/2017	Cedonia Ave and Radecke Ave	21206	Rags, Roots, Grease	WWO	Herring Run	35	Murky colored water overflowing from manhole.	350	Relieved 8" mainline choke with 350 ft of pressure hose and removed roots, rags, and debris.	Cleaned mainline and performed a CCTV inspection.	381669
35	1/25/2017	5514 Fernpark Ave	21207	Rags, Roots, Trash	WWO		0	Heavy gray water discharge near house connection in front of house.	18	Relieved house connection choke with 45 feet of electric machine cable.	Performed a mainline cleaning and CCTV inspection.	381518
36	1/26/2017	1918 W Lafayette Ave	21217	Rags, Trash	DWO		0	Evidence and sewage around house connection.	10	Relieve house connection choke with 7 ft of electric cable and small saw tooth.	Cleaned house connection to prevent future overflows	381769
37	1/26/2017	1007 Woodson Rd	21212	Rags, Roots, Trash	WWO		0	Gray water and debris around the cleanout	7	Relieved house connection choke with 45 feet of electric cable and used H-cutter to remove rags and debris.	Cleaned mainline and initiated house lateral CCTV inspection.	381925
38	1/28/2017	3624 Roland Ave	21211	Trash	DWO		54	Paper and debris overflowing	270	Relieved house connection choke with 30 ft of electric cable and H-Cutter.	Cleaned house connection to prevent future overflows.	382453
39	1/29/2017	340 S Augusta Ave	21229	Rags, Roots, Trash	DWO		0	Gray water and sewage.	8	Relieved the house connection choke with 30 ft of electric cable and H-Cutter.	Used H-Cutter to remove heavy roots from house connection.	382553

SSO Notification List

January 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
40	1/30/2017	1946 Hollins Ferry Rd	21230	Rags, Grease, Trash	WWO		0	Gray water and debris	70	Relieved mainline choke with 150 ft of pressure truck on 8 in line	Mainline cleaning and CCTV inspection.	382595
41	1/31/2017	2800 Round Rd (Private)	21225	Rags, Grease	WWO		952	Heavy gray water coming from manhole	2,856	Relieved 8" mainline choke with 150 ft of pressure hose.	Cleaned mainline and performed CCTV inspection.	383136
42	1/31/2017	2929 Rayshire Rd	21230	Rags, Roots, Trash	WWO		0	Sewage debris around clean out in front of property	17	Relieved 6" house connection choke with 25 ft of pressure hose.	Cleaned pipe to prepare for CCTV inspection.	383465
				# WWO	33			TOTAL	14,527	UNDER 100 GALLONS	23	