

## SSO Notification List

June 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/3/2016	3446 Spelman Rd	21225	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	65	Grease and rags overflowing from manhole in alley	650	Relieved mainline choke with 50ft of pressure hose	CCTV	309907
2	6/6/2016	803 E 22nd St	21218	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Paper and debris	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	310168
3	6/7/2016	947 Montpelier St	21218	Roots	WWO	N/A	Not Witnessed	Light paper and debris around clean out	Evidence of Overflow	Relived house connection choke with 75 ft of pressure truck	CCTV	310238
4	6/7/2016	224 N Milton Ave	21224	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Sewage and debris by curb	Evidence of Overflow	Flushed mainline with 300 ft of pressure machine hose	CCTV	310404
5	6/8/2016	3923 Boarman Ave	21215	Rags, Roots	WWO	N/A	Not Witnessed	Paper and debris	Evidence of Overflow	Used 45 ft electric machine to relieve house connection	CCTV	310551
6	6/9/2016	2028 W Eagle St	21223	Grease	WWO	N/A	Not Witnessed	Murky colored water	Evidence of Overflow	Used 300 ft of pressure hose to flush mainline	CCTV	310749
7	6/9/2016	224 N Milton Ave	21224	Trash, Sand, Gravel, Rocks, Pipe Break	WWO	N/A	Not Witnessed	Small amount of paper and gray water in street	Evidence of Overflow	Cleaned mainline with pressure truck	CCTV	310758
8	6/9/2016	2905 Christopher Ave	21214	Pipe Break	WWO	Herring Run	1,169	Choked sanitary manhole causing sewage to flow into adjacent storm drain pipe. found during routine sampling	1,169	Turned over to contractor for repair	Will have line recctv'd	310745
9	6/10/2016	2924 Mallview Rd	21230	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Toilet paper and debris	Evidence of Overflow	Relieved house connection choke with 10 ft of electric machine	CCTV	310892
10	6/13/2016	2905 Christopher Ave	21214	Pipe Break	DWO	Herring Run	1,250	Sanitary pipe discharging into adjacent storm drain pipe. Contractor onsite doing sewer repair	6,250	Contractor repaired collapsed pipe	Collapsed pipe was repaired and CCTV'd	
11	6/14/2016	1425 Poplar Grove St	21216	Rags, Grease	DWO	N/A	131	Gray water overflowing from manhole	131	Relieved mainline choke with 200 ft press truck on 8" line	CCTV	311400
12	6/14/2016	336 S Calhoun St	21223	Rags, Grease	DWO	N/A	1,015	Heavy gray water overflowing	3,045	Relieved mainline choke with 200 ft of pressure truck on 8" line	CCTV	311290
13	6/16/2016	200 N Milton Ave	21224	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Didn't see or witness an overflow, found debris, also found the street in front of location cracked and sunken	Evidence of Overflow	Flushed mainline to relieve choke	CCTV immediately	311857
14	6/16/2016	2805 Overland Ave	21214	Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Toilet paper and sewage found	Evidence of Overflow	Relieved house connection choke with 30' of electric machine.	CCTV	311804
15	6/17/2016	Round Rd & Bridgeview Rd	21225	Rags, Grease	WWO	N/A	Not Witnessed	Sewer water and debris	Evidence of Overflow	Relieved mainline choke with 200 ft press truck on 8 inch line	CCTV	311987
16	6/17/2016	947 Montpelier St	21218	Roots	DWO	Inner Harbor	179	Sewer water and debris overflowing	179	Cleaned line with elec machine and h-cutter	CCTV	310238

## SSO Notification List

June 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	6/18/2016	2049 Whistler Ave	21230	Pipe Break	WWO	N/A	Not Witnessed	Toilet paper and grease	Evidence of Overflow	Set up for bypass pumping	Turned over to construction for repairs	312143
18	6/19/2016	220 N Milton Ave	21224	Trash, Sand, Gravel, Rocks	WWO	Inner Harbor	125	Sewage overflowing from cracks in street	375	Jetted line with vactor truck to relieve choke	CCTV	312243
19	6/20/2016	948 Bennett Pl	21223	Rags, Roots, Grease	DWO	N/A	Not Witnessed	Wet around clean out	Evidence of Overflow	Used 30 ft of electric machine to relieve house connection choke	CCTV	311676
20	6/21/2016	3915 Stokes Dr	21229	Rags, Roots	WWO	Gwynns Falls	149	Cloudy water overflowing	745	Relieved mainline choke with 250 ft of pressure truck on 8" line	CCTV	312535
21	6/21/2016	1901 Falls Rd	21211	Rain	WWO	Jones Falls	15	Structure monitored by metering equipment in the pipe. Not visually observed.	15,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project	
22	6/22/2016	917 Seagull Ave	21225	Rags, Grease, Roots	DWO	N/A	164	Cloudy water overflowing	820	Relieved mainline choke with 300 ft of pressure truck on 8" line	CCTV	312952
23	6/22/2016	2040 Linden Ave	21217	Rags, Grease	WWO	N/A	60	Heavy gray water overflowing from the clean out	180	Relieved house connection choke with 30 ft of electric machine on 6" line	Used H-Cutter to remove rags and roots and help prevent future chokes	312979
24	6/22/2016	201 Deepdene Rd	21210	Roots	WWO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Used 60 ft of electric machine to relieve house connection choke	CCTV	313019
25	6/23/2016	838 Herndon Ct	21225	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Inner Harbor	119	Sewage discharging from the eye of manhole cover going into storm drain	595	Relieved mainline choke with 75 ft of pressure truck on 8" line	Flushed and cleaned mainline to prevent future overflows	313218
26	6/23/2016	1721 N Register St	21213	Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Gray water and toilet paper	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	Cleaned/flushed mainline to try and prevent future overflows.	313175
27	6/23/2016	5200 Beaufort Ave	21215	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Gray water and toilet paper visible	Evidence of Overflow	Relieved house connection choke with 14' of electric machine.	CCTV	313352
28	6/24/2016	2257 Cedley St	21230	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Gray water and debris	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	Used H-Cutter to remove roots from house connection	313565
29	6/24/2016	5713 Belair Rd	21206	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	66	Grease and sewage overflowing	132	Relieved house connection choke with 30' of pressure machine hose	CCTV	313742
30	6/27/2016	5200 Beaufort Ave	21215	Rags, Roots	WWO	N/A	Not Witnessed	Wet around clean out, sewage present	Evidence of Overflow	Relieved mainline choke with H-Cutter and 30 ft of electric machine	CCTV'd connection	314240
31	6/27/2016	614 Hollen Rd	21212	Rags, Roots	WWO	N/A	Not Witnessed	Wet, toilet paper around clean out	Evidence of Overflow	Relieved house connection choke with 40 ft of electric machine.	Removed roots with H-Cutter to prevent future overflows.	314244
32	6/27/2016	3903 Mayberry Ave	21206	Roots	WWO	N/A	Not Witnessed	Sewage visible around clean out in rear	Evidence of Overflow	Relieved house connection choke with 65ft of electric cable and expander.	CCTV	314253
33	6/27/2016	315 E 23rd St	21218	Roots, Grease	WWO	N/A	Not Witnessed	Area wet around clean out	Evidence of Overflow	Relieved house connection choke with 35ft of electric machine	Used H-Cutter to bring back rags and prevent future overflows	314261

## SSO Notification List

June 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
34	6/28/2016	1200 Evesham Ave	21239	Rags, Roots, Grease	WWO	N/A	25	Water coming from manhole	75	Relieve mainline choke with 350 ft of sewer jet	Removed rags and debris from mainline to prevent future overflows	314624
35	6/28/2016	821 S Dean St	21224	Rags, Grease	WWO	N/A	Not Witnessed	Paper and sewage	Evidence of Overflow	Relieved house connection choke with 30ft of electric machine	Used H-Cutter to remove rags and roots from pipe	314650
36	6/29/2016	4100 Keswick Rd	21210	Rags, Roots	WWO	Jones Falls	195	Cloudy water overflowing	390	Relieved mainline choke with 200 ft of pressure truck on 6" line	CCTV	314770
37	6/30/2016	6307 Western Run Dr	21209	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	49	Cloudy water overflowing	147	Relieved mainline choke with 300 ft of pressure machine hose.	Flushed and cleaned mainline to prevent future overflows.	315427
				# WWO	29			TOTAL	29,883	EVIDENCE ONLY	21	