

SSO Notification List

March 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/1/2017	1740 E Lanvale St	21213	Roots, Trash	WWO	N/A	0	Signs of an overflow found near the clean-out at the rear of the house.	8	Relieved house connection choke with 30 ft of electric machine cable.	Performed CCTV inspection and cleaned the mainline.	391734
2	3/2/2017	4210 Parkwood Ave	21206	Rags, Trash	WWO	N/A	0	Water around the clean-out at the front of the house.	8	Relieved front house connection choke with electric cables and auger.	Performed CCTV inspection.	391982
3	3/2/2017	2315 Maryland Ave	21218	Rags, Roots	WWO	N/A	0	Water observed near the clean-out at the rear of the property.	8	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Performed CCTV inspection.	392096
4	3/3/2017	2500 W North Ave	21216	Rags, Roots, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	142	Heavy gray water coming out of the manhole.	710	Relieved 8" mainline choke with 50 ft of pressure hose.	Performed CCTV inspection.	392253
5	3/8/2017	5407 Purlington Way	21212	Structural	WWO	N/A	59,084	House connection leaking into storm drain main. Connection has a hole and break. Discharge estimate based on household water consumption and 60% leaving the pipe.	1,773	Referred to contractor for inspection and repair.	Performed CCTV inspection.	393600
6	3/8/2017	5415 Purlington Way	21212	Structural	WWO	N/A	59163	House connection leaking into storm drain main. Discharge based on household water consumption and 20% leaving the pipe.	1,479	Performed CCTV inspection and turned over for repair.	Overflow is currently ongoing. Estimated quantity, duration, and stop time will be updated when overflow is abated.	393601
7	3/9/2017	2924 Woodland Ave	21215	Infiltration, Structural	WWO	Jones Falls	56,580	House connection leak underground is infiltrating storm drain. Confirmed by dye test.	566	Referred to contractor for inspection and repair.	Flushed and cleaned the 8" mainline with 45 ft of electric cable, and performed CCTV inspection.	393774
8	3/9/2017	3825 Copley Rd	21215	Rags, Grease	WWO	N/A	22	Gray water around the manhole.	44	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed CCTV inspection.	393821
9	3/9/2017	1908 Ramblewood Rd	21239	Grease, Trash	WWO	N/A	52	Gray water coming out of the clean-out at the front of the house.	52	Relieved house connection choke with 45 ft of electric cables.	Performed CCTV inspection.	393913
10	3/9/2017	1412 Darley Ave	21218	Rags, Trash	WWO	N/A	0	Water observed around the clean-out at the rear of the property.	6	Relieved house connection choke with 30 ft of electric cables with H-cutters.	Performed CCTV inspection and cleaned the mainline.	393895
11	3/10/2017	3400 Benson Ave	21227	Rags, Trash	WWO	N/A	0	Gray water observed around the manhole.	10	Flushed and cleaned 8" mainline.	Performed CCTV inspection.	394020
12	3/10/2017	312 S Broadway	21231	Trash	WWO	N/A	0	Gray water around the clean-out at the rear of the house.	8	Relieved house connection choke with 15 ft of electric cables and expander cutters.	Performed CCTV inspection and cleaned the mainline.	394022
13	3/11/2017	820 Bridgeview Rd	21225	Rags, Grease	WWO	N/A	85	Heavy gray water around a manhole.	170	Relieved 8" mainline choke with 175 ft of pressure hose.	Performed CCTV inspection.	394117
14	3/11/2017	1120 Gorsuch Ave	21218	Roots	WWO	N/A	0	Heavy gray water around the clean-out at the front of the property.	5	Relieved 6" house connection choke with 45 ft of electric machine.	Performed CCTV inspection.	394138
15	3/13/2017	2202 E Fairmount Ave	21213	Rags, Roots, Trash	WWO	N/A	0	Grey water near the clean-out at the front of the house.	14	Relieved house connection choke with 45 ft of electric machine cable.	Performed CCTV inspection.	394403
16	3/15/2017	4210 Parkwood Ave	21206	Trash	WWO	N/A	0	Gray water observed near the clean-out at the front of the house.	8	Relieved house connection choke with 80 ft of electric cable and saw tooth cutter.	Performed CCTV inspection.	394621
17	3/17/2017	5332 Nelson Ave	21215	Rags	DWO	N/A	0	Heavy gray water near the cleanout.	5	Relieved 6" house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	395054
18	3/18/2017	703 Reservoir St (Private)	21217	Rags, Structural	WWO	N/A	0	Heavy gray water around the cleanout at the rear of the property.	12	Ran 3 ft of electric cables and brought back mud. The connection was not relieved because of a break on the consumer side.	Performed CCTV inspection.	395208
19	3/20/2017	1120 Riverside Ave	21230	Rags, Trash	WWO	N/A	0	Dampness around the clean out, evidence of an overflow.	3	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection at this location.	395507

SSO Notification List

March 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	3/20/2017	1806 Baker St	21217	Rags, Grease	WWO	N/A	0	Heavy gray water observed near the cleanout at the rear of the property.	11	Relieved 6" house connection choke with 30 ft of electric machine.	Performed house lateral CCTV inspection.	395365
21	3/20/2017	6300 Boston St (Private)	21224	Rags, Grease	DWO	N/A	69	Gray water overflowing from manhole.	207	Relieved mainline choke with 250 ft of pressure hose.	Mainline CCTV inspection.	395389
22	3/20/2017	5038 Queensberry Ave	21215	Rags, Grease, Trash	WWO	N/A	110	Heavy gray water running from cracks at the curb.	220	Relieved 8" mainline choke with 400 ft of pressure hose.	Cleaned the mainline and performed a CCTV inspection.	395434
23	3/20/2017	1912 Fairbank Rd	21209	Roots	WWO	N/A	0	Gray water around the cleanout at the front of the house.	10	Relieved 6" house connection choke with 60 ft of electric expander cutter.	Performed CCTV inspection.	395377
24	3/20/2017	2007 Robb St	21218	Unknown	WWO	N/A	0	Water observed around the cleanout.	2	Attempted to relieve house connection choke with electric machine, unable to relieve choke.	Spoke with consumer and left door hanger.	395519
25	3/20/2017	5901 Radecke Ave	21206	Grease, Trash	WWO	N/A	0	Gray water observed in the street.	40	Relieved 8" mainline choke with 200 ft of electric machine.	Performed mainline CCTV inspection.	395538
26	3/20/2017	3132 Guilford Ave	21218	Rags	WWO	N/A	0	Gray water observed near the cleanout at the rear of the property.	7	Relieved house connection choke with 30 ft of electric cables.	Performed house lateral CCTV inspection.	395554
27	3/21/2017	Frederick Ave & Stonecroft Rd (Private)	21229	Rags, Roots, Trash	WWO	N/A	282	Sewage overflowing from manhole in the woods.	7,050	Relieved 10" mainline choke with 250 ft of pressure truck.	Performed mainline CCTV inspection.	395602
28	3/21/2017	3017 Wayne Ave	21207	Rags	WWO	N/A	0	Gray water observed near the cleanout at the front of the house.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	395695
29	3/23/2017	6903 Eunice Ave	21214	Roots, Sand, Gravel, Rocks	DWO	N/A	0	Gray water observed near the cleanout.	12	Removed obstructions in house connection with 9 ft of electric cable and turned over for bypass pumping.	Performed CCTV inspection.	396238
30	3/23/2017	4300 Hayward Ave	21215	Rags, Trash	DWO	N/A	180	Sewage observed flowing out of the manhole.	900	Relieved 6" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	396366
31	3/24/2017	29 Merrymount Rd	21210	Roots	DWO	N/A	0	Heavy gray water near the cleanout at the front of the house.	11	Relieved 6" house connection choke with 45 ft of electric cables.	Performed house lateral CCTV inspection.	396537
32	3/24/2017	539 N Luzerne Ave	21205	Trash	DWO	N/A	0	Water observed in the alleyway.	8	Problem is on the customer side. Advised contacting a plumber for removal of an old-style trap.	Notice was left.	396594
33	3/24/2017	259 Robert St	21217	Roots	DWO	N/A	0	Heavy water near the cleanout at the rear of the property.	9	Relieved 6" house connection choke with 30 ft of electric cables.	Performed house lateral CCTV inspection.	396549
34	3/24/2017	906 McKean Ave	21217	Rags, Roots	DWO	N/A	0	Heavy gray water near the cleanout at the rear of the property.	15	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house connection and mainline CCTV inspections.	396654
35	3/25/2017	2603 Boone St	21218	Rags, Grease, Trash	DWO	N/A	0	Water observed near the cleanout at the rear of the property.	5	Relieved 6" house connection choke with 30 ft of electric cables.	Cleaned house lateral and performed CCTV inspection.	396862
36	3/25/2017	717 Roundview Road	21225	Rags, Trash	DWO	N/A	0	Heavy gray water near the cleanout at the front of the property.	5	Relieved 6" house connection choke with 30 ft of electric cables.	Flushed and cleaned the mainline, and performed CCTV inspections.	396909
37	3/27/2017	2825 Windsor Ave	21216	Roots	WWO	N/A	0	Gray water around the cleanout at the rear of the property.	4	Relieved 6" house connection choke with 30 ft of electric cables.	Performed CCTV inspection.	397091
38	3/27/2017	2304 N Forest Park Ave	21207	Rags, Roots	WWO	N/A	0	Murky water observed at the cleanout in the rear of the property.	12	Relieved 6" house connection choke with 60 ft of electric cable.	House lateral CCTV inspection performed.	397091
39	3/28/2017	E Belvedere Ave & Chinquapin Pkwy	21239	Rags, Roots, Trash	WWO	N/A	112	Gray water coming out of the manhole.	224	Relieved mainline choke with 50 ft of pressure machine.	Performed mainline CCTV inspection.	397436
40	3/29/2017	2403 Talbot Rd	21216	Structural	WWO	N/A	178	Water in the street coming from manhole.	89	Flushed 6" mainline.	Performed CCTV inspection.	397843

SSO Notification List

March 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
41	3/29/2017	340 S Augusta Ave	21229	Rags	WWO	Maidens Choice	79	Water overflowing from the cleanout.	158	Relieved 6" house connection choke with 30 ft of electric cables.	Performed CCTV inspection.	397944
42	3/29/2017	516 Orkney Rd	21212	Roots, Trash	WWO	N/A	0	Water observed around the cleanout.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and cleaned the mainline.	398046
43	3/29/2017	6012 Alta Ave	21206	Rags, Roots, Trash	WWO	N/A	0	Dampness observed around the cleanout at the front of the property.	11	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	398077
44	3/29/2017	429 E 29th St	21218	Rags, Trash	WWO	N/A	0	Gray water observed near the cleanout at the rear of the property.	10	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection and cleaned the 8" mainline.	398118
45	3/30/2017	312 S Broadway	21231	Trash, Sand, Gravel, Rocks	WWO	N/A	0	Gray water around the cleanout at the rear of the property.	5	Ran 15 ft of electric cables with auger; investigation revealed need for bypass pump.	Performed CCTV inspection and cleaned the mainline.	398159
46	3/31/2017	1901 Falls Rd - SSO #67	21217	Rain	WWO	Jones Falls	230	Structure monitored by metering equipment in the pipe.	421,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project	
47	3/31/2017	428 E Preston St - SSO #72	21202	Rain	WWO	Jones Falls	395	Structure monitored by metering equipment in the pipe, not visually observed.	2,234,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project.	
48	3/31/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WWO	Jones Falls	90	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed	34,000	SSO structure. Not applicable	The SSO structure will be closed upon completion of necessary capital project.	
				# WWO	37			TOTAL	2,695,655	UNDER 100 GALLONS	33	