

SSO Notification List

April 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/1/2020	617 E 35th St	21218	Rags, Trash	Dry	N/A	0	Gray water and paper observed at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	857012
2	4/1/2020	1248 N Gay St	21213	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	857033
3	4/1/2020	1011 N Arlington Ave	21217	Rags, Grease	Dry	Gwynns Falls	645	Gray water escaping the cleanout at the rear of the property.	129	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	857072
4	4/3/2020	2001 W Saratoga St	21223	Rags, Grease, Trash	Dry	Inner Harbor	432	Gray water escaping the manhole in the street.	432	Relieved 8" mainline choke with 250 ft of pressure hose.	Confirmed mainline is clear.	857274
5	4/3/2020	1248 N Gay St	21213	Rags, Grease, Trash	Dry	N/A	0	Gray water observed at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	857241
6	4/4/2020	5703 Norwood Ave	21207	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear.	857291
7	4/4/2020	3309 Saint Ambrose Ave	21215	Rags, Structural	Dry	N/A	0	Gray water and paper observed at the front of the property.	1	Left notice to contact plumber due to structural issues on consumer's side.	Flushed and cleaned 8" mainline.	857301
8	4/5/2020	131 W Randall St	21230	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 15 ft of electric cable.	Confirmed lateral is clear.	857374
9	4/6/2020	2733 Prospect St	21216	Roots, Trash, Sand, Gravel, Rocks	Dry	N/A	0	Heavy gray water observed at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	857511
10	4/6/2020	6407 Brook Ave	21206	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	5	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	857509
11	4/6/2020	1222 N Broadway	21213	Rags, Grease, Trash	Dry	Inner Harbor	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	857553
12	4/6/2020	1524 Lester Morton Ct	21205	Rags, Grease, Trash	Dry	N/A	0	Gray water and paper observed at the rear of the property.	8	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	857567
13	4/7/2020	825 Wellington St	21211	Trash, Structural, Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	8	Ran 30 ft of electric cable, blockage remained due to structural issues. Lateral launch and repair will place.	Bypass pump was set up while further work and investigation occurs.	857632
14	4/7/2020	1214 Homewood Ave	21202	Grease, Trash, Sand, Gravel, Rocks	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 15 ft of electric cable.	Confirmed line is clear. Further investigation will take place.	857712
15	4/8/2020	2648 Guilford Ave - (Private)	21218	Grease, Structural	Dry	N/A	0	Sewage observed at the side of the property.	5	Choke occurred internally on consumer-owned pipe. Advised homeowner to contact private plumber.	Referred location to Housing Authority to have external cleanout installed. Confirmed mainline is clear.	857746
16	4/9/2020	616 Woodbourne Ave	21212	Rags, Grease, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Confirmed line is clear.	857950
17	4/9/2020	N Hilton St & Edmondson Ave	21216	Rags, Roots, Trash	Wet	Gwynns Falls	823	Gray water actively overflowing from manhole.	4,115	Relieved mainline choke with 45 ft of pressure hose.	Confirmed line is clear.	857960
18	4/12/2020	3721 Roland Ave	21211	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 21 ft of electric cable through the lateral.	Advised consumer to have plumber investigate their side of the connection.	858069
19	4/13/2020	3605 Clarinth Rd	21215	Rags, Rain, Grease	Wet	Jones Falls	46	Water discharging from manholes at the rear of the property.	4,600	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	858119
20	4/13/2020	1901 Falls Rd	21218	Rain	Wet	Jones Falls	220	Heavy gray water escaping the manhole.	22,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	858117
21	4/13/2020	1731 E Chase St	21213	Rain	Wet	Inner Harbor	75	Manhole surcharging due to heavy rain.	40,000	Flow returned to normal following heavy rain event.	Location is equipped with an Event Notification System meter.	858127

SSO Notification List

April 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	4/13/2020	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	620	Structure monitored by metering equipment in the pipe. Not visually observed.	1,339,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
23	4/13/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1085	Structure monitored by metering equipment in the pipe. Not visually observed.	7,641,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
24	4/13/2020	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	50	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe.	19,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
25	4/13/2020	1800 E Eager St	21205	Rain	Wet	Inner Harbor	80	Manhole surcharging due to heavy rain.	500	Flow returned to normal following heavy rain event.	Location is equipped with an Event Notification System meter.	858125
26	4/13/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	275	Manhole adjacent to creek overflowed due to heavy rain.	6,848,000	Overflow subsided following heavy rain event.	Eventual capital improvement projects will upsize the system.	
27	4/13/2020	1901 Falls Rd	21218	Rain	Wet	Jones Falls	160	Heavy gray water escaping the manhole in the street.	549,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
28	4/14/2020	810 N Hilton St	21229	Rags, Grease, Trash	Wet	Gwynns Falls	327	Gray water escaping the manhole in the rear alley.	8,175	Relieved mainline choke with 110 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	858300
29	4/14/2020	4701 Amberley Ave	21229	Structural	Wet	N/A	0	Gray water observed around the cleanout at the side of the property.	10	Ran 26 ft of electric cable through the lateral, determined structural issues exist.	Location has been turned over for repair. Bypass pumping may be needed while repairs take place.	858327
30	4/14/2020	4309 Liberty Heights Ave	21207	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	858394
31	4/14/2020	2509 Wetherburn Rd	21209	Rags, Trash	Wet	N/A	150	Gray water escaping the manhole.	75	Relieved 8" mainline choke with pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	858413
32	4/15/2020	2821 Beechland Ave	21214	Roots, Grease	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	858470
33	4/15/2020	105 Deepdene Rd	21210	Roots	Wet	N/A	253	Gray water slowly escaping the cleanout at the front of the property.	25	Relieved house connection choke with 75 ft of pressure hose.	Performed CCTV inspection; confirmed lines are clear.	858621
34	4/16/2020	5100 Falls Rd	21210	Rags, Roots, Trash	Wet	Jones Falls	66	Gray water escaping from the manhole and entering nearby storm drain.	1,650	Relieved 15" mainline choke with 150 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	858668
35	4/17/2020	1248 N Gay St	21213	Rags, Trash	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the mainline.	858870
36	4/18/2020	8201 Eastern Ave (Back River WWTP)	21224	Other	Dry	N/A	0	Scum well discharging	5,000	Flow to the well was stopped, cleaned and limed the area, repaired the valve.	Valve functionality restored.	
37	4/22/2020	1911 Penrose Ave	21223	Rags	Dry	N/A	0	Heavy gray water observed at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	859437
38	4/22/2020	3024 Walbrook Ave	21216	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 65 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	859466
39	4/23/2020	4701 Amberley Ave	21229	Structural	Dry	Gwynns Falls	1636	Gray water leaking from the rear of the property.	491	Repairs were made to the line to address structural damage and restore it to regular functionality.	Confirmed lateral is no longer leaking.	857830
40	4/24/2020	1528 N Caroline St	21213	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	859674
41	4/27/2020	1633 N Milton Ave	21213	Rags, Grease, Trash	Wet	N/A	0	Gray water and paper observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	859924
42	4/27/2020	2817 W Lafayette Ave	21216	Rags, Roots, Grease, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	859915

SSO Notification List

April 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
43	4/28/2020	5703 Norwood Ave	21207	Rags, Roots	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	859962
44	4/28/2020	810 N Hilton St	21229	Rags, Grease, Trash	Wet	Gwynns Falls	160	Heavy gray water escaping the manhole.	4,000	Relieved mainline choke with 105 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	860028
45	4/29/2020	Fords Ln & Park Heights Ave	21215	Rags, Grease, Trash	Wet	Jones Falls	310	Gray water escaping the manhole and entering nearby storm drain.	12,400	Relieved mainline choke with 25 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	860234
46	4/29/2020	6108 Ridgeview Ave	21206	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	860156
47	4/30/2020	1817 Penrose Ave	21223	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 15 ft of electric cable.	CCTV inspection will be performed. Left notice advising consumer to contact private plumber.	860270
48	4/30/2020	1251 E Northern Pkwy	21239	Rags, Roots, Trash	Wet	N/A	90	Gray water escaping the manhole.	360	Relieved mainline choke with 250 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	860332
49	4/30/2020	105 Deepdene Rd	21210	Rags, Roots	Wet	N/A	155	Gray water escaping the manhole at the front of the property.	310	Relieved mainline choke with 450 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	850312
50	4/30/2020	1800 E Eager St	21205	Rags, Rain, Grease, Trash	Wet	Inner Harbor	125	Gray water escaping the manhole.	700	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	860322
51	4/30/2020	1731 E Chase St	21213	Rags, Rain	Wet	Inner Harbor	320	Heavy gray water escaping the manhole in the street.	720,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	860323
52	4/30/2020	1901 Falls Rd	21211	Rain	Wet	Jones Falls	180	Heavy gray water escaping the manhole.	18,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	860320
53	4/30/2020	3405 Holmes Ave	21217	Rags, Trash, Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with electric cable and pressure hose.	Confirmed lateral is clear.	860354
54	4/30/2020	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	430	Structure monitored by metering equipment in the pipe. Not visually observed.	1,455,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
55	4/30/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	690	Structure monitored by metering equipment in the pipe. Not visually observed.	6,600,000	SSO structure; not applicable.	The structure is monitored by a meter and will be closed upon completion of capital project.	
56	4/30/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	275	Manhole adjacent to creek overflowed due to heavy rain.	5,427,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
57	4/30/2020	1901 Falls Rd	21218	Rain	Wet	Jones Falls	180	Manhole surcharging due to heavy rain.	22,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	860320
				# WWO	38			TOTAL	30,743,038	UNDER 100 GALLONS	29	