

SSO Notification List

April 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/2/2022	3602 Keystone Ave	21211	Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection showed the lateral to be clear.	1031748
2	4/4/2022	3307 Henry G Parks Jr Cir	21215	Rags, Trash	Dry	Jones Falls	227	Gray water escaping the manhole.	1,135	Relieved mainline choke with 125 ft of pressure hose.	Confirmed the line is clear; CCTV inspection will be performed.	1031835
3	4/4/2022	2610 Oswego Ave	21215	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are clear.	1031828
4	4/4/2022	1011 W 37th St	21211	Rags, Roots	Dry	N/A		Gray water and rags around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	1032046
5	4/5/2022	Hollins St & S Warwick Ave	21223	Rags, Grease, Trash	Dry	Gwynns Falls	66	Choked sanitary mainline causing wastewater to infiltrate the storm drain subsurface.	660	Relieved 10" mainline choke with 200 ft of pressure hose.	Confirmed mainline is now clear; CCTV will be performed.	1032280
6	4/6/2022	4128 Westchester Rd	21216	Rags, Grease, Sand, Gravel, Rocks	Wet	Gwynns Falls	56	Surcharging manhole in the street.	1,680	Relieved mainline choke with 225 ft of pressure hose.	Confirmed mainline is clear at this time; CCTV will be performed.	1032658
7	4/8/2022	800 N Hilton St	21229	Rags, Roots, Grease	Wet	Gwynns Falls	140	Gray water escaping the manhole in the street.	700	Relieved mainline choke with 125 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1033311
8	4/8/2022	3910 Wabash Ave	21215	Rags, Grease, Trash	Wet	Gwynns Falls		Heavy gray water observed around the manhole.	10	Relieved mainline choke with 150 ft of pressure hose.	CCTV inspection will be performed.	1033364
9	4/8/2022	4722 York Rd	21212	Sand, Gravel, Rocks	Wet	Tiffany Run	136	Gray water escaping the manhole and entering nearby storm drain.	4,080	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the line is clear; CCTV inspection will be performed.	1033405
10	4/10/2022	701 S Glover St	21224	Rags	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	1034068
11	4/11/2022	1107 Slater Rd	21225	Rags, Grease	Wet	N/A		Gray water observed around the manhole and storm drain.	8	Relieved mainline choke with 100 ft of pressure hose.	CCTV inspection and storm inlet cleaning will be performed.	1034311
12	4/12/2022	403 Lyndhurst St	21229	Rags	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; mainline will be cleaned.	1034585
13	4/12/2022	3411 Crossland Ave	21213	Structural	Dry	N/A		Gas company struck mainline while digging in the area.	3	Construction crew will repair damage to mainline.	Line will be restored to regular functionality.	1034650
14	4/12/2022	319 E 22nd St	21218	Roots	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Confirmed the lateral is clear at this time.	1034753
15	4/14/2022	Tompkins St & West Bay Ave	21225	Rags, Grease, Sand, Gravel, Rocks	Dry	N/A	685	Gray water escaping the manhole in the street.	2,055	Relieved mainline choke with 30 ft of pressure hose.	CCTV inspection will be performed to determine if further action is needed.	1035046
16	4/14/2022	222 S Monastery Ave	21229	Rags, Roots, Structural	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed to determine if structural damage is present.	1035198
17	4/15/2022	1520 Clipper Rd	21211	Rags, Roots, Trash	Dry	N/A	173	Gray water escaping the cleanout.	87	Relieved choke with 50 ft of electric cable and pressure hose.	Confirmed lateral and mainline are flowing freely.	1041489
18	4/15/2022	2703 W Belvedere Ave	21215	Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	CCTV inspection will be performed.	1041620
19	4/16/2022	2508 Queen Anne Rd	21216	Rags, Roots, Grease, Trash	Dry	Gwynns Falls	1157	Gray water escaping the cleanout.	579	Relieved mainline choke with 175 ft of pressure hose.	CCTV inspection will be performed.	0
20	4/18/2022	1811 N Fulton Ave	21217	Rags, Roots, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed the lateral and mainline are clear.	1045862

SSO Notification List

April 2022

21	4/18/2022	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	65	Structure monitored by metering equipment in the pipe. Not visually observed.	2,990	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	0
22	4/18/2022	3900 Belair Rd	21206	Rain	Wet	Herring Run	45	Manhole adjacent to creek overflowed due to heavy rain.	74,970	Overflow subsided following heavy rain event.	SSOs will be prevented at this location after completion of capital improvement projects.	0
23	4/19/2022	426 Calvin Ave	21218	Rags, Roots, Sand, Gravel, Rocks	Wet	N/A		Gray water observed around the cleanout.	1	Ran 20 ft of electric cable through the lateral; blockage remained.	Bypass pumping will be initiated while further investigation takes place.	1046733
24	4/19/2022	5908 The Alameda	21239	Roots, Grease, Trash	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 32 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1046736
25	4/20/2022	6400 Pulaski Hwy	21205	Rags, Trash	Wet	N/A	412	Gray water escaping the manhole.	412	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to confirm the line is clear.	1046969
26	4/20/2022	2416 Loyola Northway	21215	Rags, Roots, Grease	Wet	Jones Falls	983	Gray water escaping the manhole and entering nearby storm drain.	4,915	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the mainline is clear at this time.	1047041
27	4/22/2022	400 W Cold Spring Ln	21210	Rags, Roots, Grease, Trash	Dry	N/A	86	Gray water escaping the manhole and entering nearby storm drain.	258	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is clear at this time.	1047386
28	4/22/2022	7 W Preston St	21201	Rags, Grease	Dry	Jones Falls	206	Sewage escaping the manhole in the street.	1,030	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear; CCTV inspection will be performed.	1047885
29	4/22/2022	3204 Juneau Pl	21214	Rags, Roots	Dry	N/A		Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1049144
30	4/24/2022	3025 Mary Ave	21214	Rags, Roots, Trash	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; line is clear.	1057636
31	4/24/2022	Chinquapin Pkwy & Harwood Ave	21239	Rags, Trash	Dry	Chinquapin Run	237	Gray water escaping the manhole and reaching storm drain.	237	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV will be performed.	1057651
32	4/25/2022	301 Edgevale Rd	21210	Rags, Roots	Dry	Jones Falls		Gray water observed around manhole and storm drain.	10	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	1065317
33	4/26/2022	1608 Aisquith St	21202	Sand, Gravel, Rocks, Unknown	Dry	N/A		Gray water observed at the front of the property.	1	Ran 20 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will take place.	1069380
34	4/27/2022	2311 Koko Ln	21216	Rags, Sand, Gravel, Rocks	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 75 ft of pressure hose.	CCTV confirmed the lateral and mainline are now clear.	1073617
35	4/27/2022	1307 W Northern Pkwy	21209	Rags, Roots, Grease	Wet	Biddison Run	2364	Gray water escaping the manhole.	1,182	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is now clear; CCTV will be performed.	1073810
36	4/29/2022	5704 Falls Rd	21209	Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed the lateral and mainline are clear.	1082701
37	4/30/2022	4403 Frederick Ave - Private	21229	Rags, Grease	Dry	N/A	85	Gray water escaping private manhole.	170	DPW assisted by relieving mainline choke.	Confirmed line is clear; spoke to owner.	1084484
				# WWO	14			TOTAL	97,016	UNDER 100 GALLONS	21	