

SSO Notification List

April 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/1/2024	3605 Clarinth Rd	21215	Rags, Grease	Wet	Western Run	180	Gray water escaping the manhole.	540	Relieved mainline choke with 100 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1325233
2	4/2/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	130	Manhole adjacent to creek overflowed due to heavy rain.	222040	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
3	4/2/2024	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	90	Structure monitored by metered equipment in the pipe. Not visually observed.	8010	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
4	4/2/2024	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	195	Structure monitored by metering equipment in the pipe. Not visually observed.	896025	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
5	4/2/2024	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	230	Structure monitored by metering equipment in the pipe. Not visually observed.	871930	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
6	4/2/2024	5007 W Forest Park Ave	21207	Rain	Wet	Gwynns Falls	2881	Manhole surcharging in the street.	14405	Overflow subsided following rain event.	CCTV inspection will be performed.	1325733
7	4/2/2024	1500 N Charles St	21201	Rain, Unknown	Wet	—	—	Rain caused manhole to surcharge and parking garage to flood.	15	Overflow subsided following heavy rain event.	CCTV will be performed.	1325741
8	4/2/2024	1700 E Patapsco Ave	21226	Rain, Unknown	Wet	—	—	Manhole surcharged due to heavy rain event.	20	Overflow subsided following heavy rain event.	CCTV will be performed.	1325769
9	4/3/2024	1200 N Franklinton Rd	21216	Rain	Wet	Gwynns Falls	500	Gray water escaping the manhole.	59000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
10	4/3/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	450	Manhole adjacent to creek overflowed due to heavy rain.	1336050	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
11	4/3/2024	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	90	Structure monitored by metered equipment in the pipe. Not visually observed.	11970	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
12	4/3/2024	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	610	Structure monitored by metering equipment in the pipe. Not visually observed.	4618005	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
13	4/3/2024	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	690	Structure monitored by metering equipment in the pipe. Not visually observed.	3305100	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
14	4/3/2024	N Longwood St & Gwynns Falls Pkwy	21216	Rain	Wet	Gwynns Falls	—	Heavy gray water observed near the manhole.	7	Mainline surcharged during heavy rain event.	CCTV will be performed.	1328767
15	4/4/2024	903 Ellicott Driveway	21216	Rags, Grease, Trash, Unknown	Wet	Gwynns Falls	1398	Overflowing sanitary sewer main reaching waterway.	13980	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is now clear; CCTV will be performed.	1329261
16	4/5/2024	320 E 26th St	21218	Roots	Wet	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke for 30 ft of electric cable.	CCTV inspection confirmed lateral is now clear.	1329913
17	4/7/2024	5713 Edgepark Rd	21239	Rags, Trash	Dry	Herring Run	—	Gray water observed near manhole and storm drain.	5	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is now clear; CCTV will be performed.	1330270
18	4/7/2024	3025 Mary Ave	21214	Rags, Roots, Grease	Dry	—	—	Gray water and debris observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	1330285
19	4/8/2024	4901 Frankford Ave - (Private)	21206	Unknown	Dry	Biddison Run	2916	Overflowing cleanout flowing into storm inlet.	2916	Performed lateral launch to determine issue exists on consumer's side of pipe.	OREP will handle enforcement to provide a solution.	1330554
20	4/8/2024	708 Edmondson Ave	21201	Rags, Trash	Dry	—	—	Gray water observed near cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are both clear at this time.	1330733

SSO Notification List

April 2024

21	4/9/2024	508 Old Orchard Rd	21229	Trash, Unknown	Dry	—	—	Gray water observed at the front of the property.	1	Ran 60 ft of electric cable through the lateral.	CCTV showed the pipe to be clear.	1330786
22	4/9/2024	3637 Greenmount Ave	21218	Rags, Grease	Dry	—	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	1330843
23	4/9/2024	4401 Frankford Ave	21206	Rags, Grease, Trash	Dry	Biddison Run	141	Choked sanitary sewer overflowing into adjacent storm drain.	141	Relieved mainline choke with 350 ft of pressure hose.	Confirmed mainline is clear; CCTV will be performed.	1331424
24	4/10/2024	3600 Labyrinth Rd	21215	Rags	Dry	Western Run	40	Choked house connection overflowing into adjacent storm drain pipe.	200	Used electric machine to clear blockage causing SSO.	Pipe will need to be repaired to restore to regular functionality.	1331750
25	4/11/2024	807 N Madeira St	21205	Rags, Roots	Dry	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is now clear.	1331906
26	4/14/2024	3301 Abell Ave	21218	Unknown	Wet	Jones Falls	3110	Gray water escaping the cleanout.	311	Installed bypass pumping to stop the overflow.	Lateral will be repaired to restore line to regular functionality.	1332826
27	4/15/2024	500 North Point Rd	21224	Other	Dry	Herring Run	1500	Force main valve chamber overflowing.	15000	Closed blow-off valve goose neck to stop the SSO.	More frequent preventative maintenance measures.	—
28	4/16/2024	5304 Nuth Ave	21206	Structural	Wet	Biddison Run	2645	House connection leaking into adjacent storm pipe.	TBD*	Contractor will need to repair pipe.	Future repair should solve leak issue.	—
29	4/16/2024	4637 Briarclift Rd	21229	Rags, Roots	Wet	—	—	Gray water and debris observed near the manhole.	6	Relieved mainline choke with 350 ft of pressure hose.	Confirmed line is now clear; CCTV will be performed.	1333636
30	4/17/2024	432 N Hilton St	21229	Rags, Grease, Trash	Wet	Gwynns Falls	75	Choked sanitary sewer overflowing into adjacent storm pipe.	375	Temporarily relieved mainline choke with 100 ft of pressure hose.	Further investigation and work will resolve situation.	1333876
31	4/18/2024	432 N Hilton St	21229	Rags, Grease, Trash	Dry	Gwynns Falls	180	Choked sanitary sewer overflowing into adjacent storm drain pipe.	900	Relieved mainline choke with 150 ft of pressure hose.	Confirmed choke was fully relieved. CCTV will be performed.	1334145
32	4/18/2024	2300 Cylburn Ave	21209	Rags, Trash, Unknown	Dry	—	—	Gray water observed near the manhole.	5	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	1056530
33	4/19/2024	2113 E Chase St	21205	Structural	Dry	—	—	Gray water observed at the rear of the property.	3	Ran 8 ft electric cable through the lateral; determined additional issue exists.	Further investigation will take place; bypass pump will prevent another SSO.	1334499
34	4/20/2024	1631 Gwynns Falls Pkwy	21217	Rags, Trash	Dry	—	—	Gray water and paper observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection was performed to confirm the lateral is clear.	1334548
35	4/21/2024	3611 Callaway Ave	21215	Rags, Trash	Dry	—	710	Mainline choke causing cleanout to overflow.	71	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection confirmed mainline and lateral are clear.	1334581
36	4/22/2024	2391 Frederick Ave	21223	Rags, Trash	Dry	—	—	Gray water observed near the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is clear.	1334912
37	4/22/2024	432 N Hilton St	21229	Rags, Other	Dry	Gwynns Falls	75	Choked sanitary sewer overflowing into adjacent storm drain pipe.	375	Relieved choke with 200 ft of pressure hose.	CCTV will determine if further obstructions exist in the pipe.	1334746
38	4/23/2024	1618 Edmondson Ave	21217	Rags, Trash, Unknown	Dry	—	—	Gray water observed around the manhole in the alley.	3	Ran 65 ft of pressure hose through the line to partially relieve choke.	CCTV will be performed to determine if further action is needed.	1335235
39	4/23/2024	3501 Taylor Ave	21234	Rags, Roots, Trash	Dry	Moores Run	90	Manhole overflowing into adjacent stream.	900	Relieved mainline choke with 480 ft of pressure hose.	CCTV will be performed to ensure all obstructions were removed.	1335262
40	4/24/2024	2105 Hollins Ferry Rd	21230	Rags, Roots	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is now clear.	1335707
41	4/25/2024	2415 W Franklin St	21223	Rags, Trash	Dry	—	—	Gray water observed near cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	1335904

SSO Notification List

April 2024

42	4/25/2024	300 Pontiac Ave	21225	Trash	Dry	—	400	Gray water escaping the cleanout.	4	Relieved choke with 75 ft of electric cable and pressure hose.	CCTV inspection will be performed.	1335951
43	4/26/2024	2438 Harriet Ave	21230	Grease	Dry	Gwynns Falls	213	Wastewater escaping the manhole and entering nearby storm drain.	1,065	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1336218
44	4/26/2024	213 Wilson St	21217	Rags	Dry	—	—	Water and paper observed near cleanout.	1	Ran electric cable through lateral; determined further obstruction(s) present.	CCTV will be performed to determine further steps.	1336393
45	4/29/2024	3500 Gough St	21224	Rags	Dry	—	—	Water and paper observed near cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection; line is now clear.	1336785
46	4/30/2024	2808 Parkwood Ave	21217	Structural	Dry	—	—	Water and paper observed at the rear of the property.	1	Determined structural damage exists on the lateral.	Line will be repaired. Consumer and hosing authority are involved.	—
				# WWO	20			TOTAL	11,376,475	UNDER 100 GALLONS	23	