SSO Notification List

April 2025

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet- Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|-----------------------|--------------------------|----------|---------------------|-------------------------------------|------------------|-------------------|--|--|--|--|--------------|
| 1 | 4/1/2025 | 2415 W Franklin St | 21223 | Rags | Wet | - | - | Observed wastewater at front house connection | 3 | Relieved house connection choke with 60 ft electric cable | Confirmed house connectiion is clear at this time. CCTV will be performed | 1431869 |
| 2 | 4/1/2025 | 3102 Presbury St | 21216 | Roots, Trash | Wet | - | - | Wastewater with roots and debris | 1 | Relieved choke using electric cable with saw teeth | CCTV Inspection will be performed | 1431970 |
| 3 | 4/2/2025 | 2014 Fleet St | 21231 | Rags, Roots | Wet | - | - | Observed wastewater at front house connection | 1 | Used 60 ft electric cable to relieve house connection | Confirmed removal of rags and roots from the connection. CCTV will be performed | 1432122 |
| 4 | 4/2/2025 | Argonne Dr and Hillen Rd | 21218 | Rags, Trash | Wet | _ | - | Wastewater with rags and debris | 25 | Relieved choke using 200 ft. of pressure hose | CCTV Inspection will be performed | 1432324 |
| 5 | 4/3/2025 | 828 Cedarcroft Rd | 21212 | Roots | Wet | Chinquapin Run | 55800 | Wastewater with roots and root ball | 5580 | Root cutting | Temporary repair made | 1433190 |
| 6 | 4/3/2025 | 1819 Appleton St | 21217 | Rags | Wet | - | - | Wastewater with rags | 2 | Relieved choke using electric cable with saw teeth | CCTV will be performed | 1433001 |
| 7 | 4/4/2025 | 3404 Cedardale Rd | 21215 | Rags, Roots | Wet | - | - | Wastewater observed at front house connection | 1 | Relieved house connection choke with 45 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1433234 |
| 8 | 4/5/2025 | 3917 Pascal Ave | 21226 | Trash | Wet | - | - | Wastewater with debris | 2 | Relieved mainline using electric machine | CCTV Inspection will be performed | 1433275 |
| 9 | 4/5/2025 | 2127 Boston St | 21231 | Rags, Roots, Trash | Wet | _ | - | Observed wastewater coming from side house connection | 1 | Relieved house connection choke with 60 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1433291 |
| 10 | 4/5/2025 | 2511 Seamon Ave | 21225 | Rags | Wet | _ | _ | Wastewater with rags | 10 | Relieved choke using150ft of pressure hose | CCTV Inspection will be performed | 1433304 |
| 11 | 4/6/2025 | 2402 Erdman Ave | 21213 | Rags | Wet | _ | - | Observed wastewater at rear house connection | 1 | Relieved house connection choke with 30 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1433338 |
| 12 | 4/6/2025 | 4728 Wrenwood Ave | 21212 | Rags, Grease | Wet | _ | - | Observed wastewater coming from front house connection | 1 | Relieved house connection choke with 30 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1433323 |
| 13 | 4/11/2025 | 701 N Carey St | 21217 | Rags, Roots | Dry | _ | - | Observed wastewater coming from house connection | 2 | Relieved house connection choke with 45 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1434631 |
| 14 | 4/12/2025 | 1700 Thames St | 21231 | Rags, Trash | Wet | Northwest Harbor | 509 | Wastewater with rags and debris | 1018 | Relieved choke with 200 ft of pressure hose | CCTV Inspection will be performed | 1434722 |
| 15 | 4/13/2025 | 3600 Marmon Ave | 21207 | Rags, Grease, Trash | Wet | Gwynns Falls | 290 | Observed wastewater coming from manhole | 145 | Relieved mainline choke with 300 ft pressure hose | Confirmed mainline is clear at this time. Referred for CCTV inspection | 1434771 |
| 16 | 4/15/2025 | 6214 Cross Country Blvd | 21215 | Rags, Grease, Trash | Dry | _ | - | Observed wastewater coming from manhole | 1 | Relieved mainline choke with 350 ft pressure hose | Confirmed mainline is clear at this time. CCTV will be performed | 1435311 |
| 17 | 4/15/2025 | 3920 Potee St | 21225 | Rags, Roots | Dry | _ | - | Wastewater with rags and roots | 1 | Relieved choke using an electric machine cable | CCTV Inspection will be performed | 1435462 |
| 18 | 4/16/2025 | 4517 Schenley Rd | 21210 | Roots | Dry | _ | - | Observed wastewater coming from side rear house connection | 1 | Relieved house connection choke with 90 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1435537 |
| 19 | 4/16/2025 | 4213 Moravia Rd | 21206 | Rags, Trash | Dry | Herring Run | 1384 | Subsurface mainline choke causing wastewater to infiltrate into nearby storm | 692 | Relieved mainline choke with 350 ft pressure hose | Confirmed mainline SSO abated by the Office of Research and Environmental Protection | 1435561 |
| 20 | 4/16/2025 | 5210 The Alameda | 21239 | Roots | Dry | - | - | Observed wastewater coming from front house connection | 1 | Relieved house connection choke with 30 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1435644 |

| SSO Notification List | | | | | | | | | | | | |
|-----------------------|-----------|----------------------------------|-------|---------------------|-----|------------------|------|--|------|--|---|---------|
| April 2025 | | | | | | | | | | | | |
| 21 | 4/17/2025 | 414 Key Hwy | 21230 | Rags, Grease, Trash | Dry | Northwest Harbor | 316 | Observed wastewater from manhole entering nearby storm drain | 158 | Relieved mainline choke flushed and cleaned with 200 ft pressure hose | Confirmed mainline is clear at this time. CCTV will be performed | 1436015 |
| 22 | 4/18/2025 | 3715 Liberty Heights Ave | 21216 | Rags, Trash | Dry | - | - | Observed wastewater at rear house connection | 1 | Relieved house connection choke with 45 ft electric cable | CCTV will be performed | 1436218 |
| 23 | 4/18/2025 | 410 Key Hwy | 21230 | Rags, Trash | Dry | Northwest Harbor | 132 | Observed wastewater coming from manhole | 66 | Relieved mainline choke with 200 ft pressure hose | Confirmed mainline is clear at this time. CCTV will be performed | 1436246 |
| 24 | 4/18/2025 | 311 N Fulton Ave | 21223 | Other | Dry | - | - | Wastewater with mud | 3 | Crew ran 45ft of electric machine cables and was unable to relive choke | Bypass pumping installed and crew will make repairs | 1436249 |
| 25 | 4/20/2025 | 3506 Berwyn Ave | 21207 | Roots | Dry | - | - | Wastewater with roots | 5 | Relieved choke using 40 ft. of electric cable | CCTV Inspection will be performed | 1436313 |
| 26 | 4/22/2025 | 3705 Everett St | 21226 | Rags, Trash | Dry | - | 133 | Wastewater with rags and debris | 399 | Relieved choke using pressure hose to flush and clean 8" Sewer | CCTV Inspection will be performed | 403374 |
| 27 | 4/23/2025 | 3701 Southwestern Blvd | 21229 | Rags, Grease, Trash | Dry | Maidens Choice | 1695 | Observed wastewater coming from manhole | 5085 | Relieved mainline flushed and cleaned with 400 ft pressure hose | Confirmed mainline is clear at this time. CCTV was performed | 1436966 |
| 28 | 4/23/2025 | 913 Chauncey Ave | 21217 | Rags, Trash | Dry | - | _ | Observed wastewater at rear house connection | 1 | Relieved house connection choke with 30 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1437216 |
| 29 | 4/23/2025 | 2301 Washington Blvd | 21230 | Rags, Trash | Dry | - | 179 | Wastewater with rags and debris | 1074 | Relieved choke using pressure hose to flush and clean mainline | CCTV Inspection will be performed | 1437444 |
| 30 | 4/24/2025 | 706 N Martin Luther King Jr Blvd | 21201 | Trash | Dry | - | - | Observed wastewater at rear house connection | 1 | Relieved mainline choke flushed and cleaned with 200 ft pressure hose that was causing debris in house connection. | Confirmed house connection and mainline is clear at this time. CCTV will be performed | 1437542 |
| 31 | 4/25/2025 | 1801 Sulgrave Ave | 21209 | Rags, Trash | Dry | Western Run | 612 | Observed wastewater coming from manhole | 612 | Relieved mainline choke with 200 ft pressure hose | CCTV performed confirmed mainline is clear at this time | 1438055 |
| 32 | 4/25/2025 | 2601 Woodland Ave | 21215 | Rags, Trash | Dry | Gwynns Falls | _, | Wastewater with rags and debris | 3 | Relieved choke using pressure hose to flush and clean 8" Sewer Main | CCTV Inspection will be performed | 1438372 |
| 33 | 4/26/2025 | 206 E Eager St | 21202 | Rags, Trash | Wet | - | _, | Wastewater with rags and debris | 3 | Relieved choke by flushing and cleaning 8" sewer main | CCTV Inspection will be performed | 1438372 |
| 34 | 4/28/2025 | 4719 York Rd | 21212 | Rags, Trash | Wet | Tiffany Run | 158 | Wastewater with rags/debris, and Subsurface overflow infiltrating storm drain. | 158 | Relieved choke with pressure hose | CCTV Inspection has been scheduled | 1438611 |
| 35 | 4/28/2025 | 110 E Preston St | 21202 | Rags, Trash | Wet | - | - | Observed wastewater at rear house connection | 1 | Relieved house connection choke with 30 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1438835 |
| 36 | 4/29/2025 | 2617 W Fairmount Ave | 21223 | Rags, Trash | Dry | Gwynns Falls | 74 | Choked mainline sewer with rags and debris overflowing into adjacent storm drain. | 740 | Relieved choke using pressure hose | CCTV Inspection Scheduled | 1438903 |
| 37 | 4/29/2025 | 1429 Poplar Grove St | 21216 | Rags, Trash | Dry | - | _ | Observed wastewater coming from rear house connection | 1 | Relieved house connection choke with 30 ft electric cable | Confirmed house connection is clear at this time. CCTV was performed | 1439130 |
| 38 | 4/30/2025 | 5512 Park Heights Ave | 21215 | Rags | Dry | _ | _ | Wastewater with rags | 3 | Relieved choke with electric machine cable | CCTV Inspection will be performed | 1439474 |

TOTAL

UNDER 100 GALLONS

WWO