

## SSO Notification List

August 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	8/2/2021	2932 Mosher St	21216	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed; confirmed the lateral is clear.	964513
2	8/3/2021	632 Harvey St	21230	Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 20 ft of electric cable.	Lateral and mainline CCTV inspections will be performed to ensure system is working properly.	964656
3	8/3/2021	3600 Clarks Ln	21215	Rags, Roots, Grease, Trash	Wet	Jones Falls	276	Gray water escaping the manhole.	2,760	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear at this time; CCTV inspection will be performed.	964551
4	8/3/2021	2015 N Payson St	21217	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the 8" mainline.	964690
5	8/4/2021	3623 Milford Ave	21207	Rags, Roots	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and results showed the lateral and mainline to be clear.	964958
6	8/5/2021	6701 Quad Ave	21237	Roots	Dry	N/A	0	Gray water observed at the front of the property.	3	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral is clear; flushed and cleaned the 8" mainline.	965161
7	8/7/2021	909 E Patapsco Ave	21225	Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed to ensure line is clear.	965579
8	8/7/2021	2315 Maryland Ave	21218	Rags	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed both the lateral and mainline are now flowing freely.	965632
9	8/9/2021	3912 Wabash Ave	21215	Rags, Grease	Dry	Gwynns Falls	121	Gray water escaping the manhole in the street.	1,815	Relieved mainline choke with 65 ft of pressure hose.	CCTV inspection will be performed to confirm all obstructions were removed.	965722
10	8/10/2021	3123 Elmora Ave	21213	Rags, Grease, Trash	Wet	Inner Harbor	0	Heavy gray water around the manhole in the street.	7	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed on the mainline.	966286
11	8/10/2021	789 Yale Ave	21229	Rags, Grease, Trash	Wet	Gwynns Falls	989	Gray water escaping the manhole in the alley.	1,978	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed; confirmed line is clear at this time.	966288
12	8/10/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	25	Structure monitored by metering equipment in the pipe. Not visually observed.	11,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
13	8/10/2021	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	15	Structure discharges to an outfall pipe and is monitored by metering equipment in the pipe.	2,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
14	8/11/2021	3923 Boarman Ave	21215	Roots	Wet	N/A	0	Gray water observed at the front of the property.	1	Ran 45 feet of electric cable and expander cutter to remove roots.	Performed CCTV inspection on lateral and confirmed it's clear to the mainline.	966509
15	8/12/2021	2157 Whistler Ave	21230	Structural	Wet	N/A	0	Gray water observed around the cleanout.	1	Ran 13 ft of electric cable; determined structural damage exists.	Lateral will be repaired to restore line to regular functionality.	966664
16	8/12/2021	4020 Eastern Ave	21224	Rags, Grease	Wet	N/A	0	Gray water observed on the sidewalk at the front of the property.	2	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	966722
17	8/13/2021	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	20	Structure monitored by metering equipment in pipe.	2,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital projects.	
18	8/13/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	105	Structure monitored by metering equipment in the pipe. Not visually observed.	388,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
19	8/13/2021	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	20	Structure discharges to an outfall pipe and is monitored by metering equipment in the pipe.	4,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
20	8/13/2021	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	35	Structure monitored by metering equipment in the pipe.	2,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	

## SSO Notification List

August 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	8/13/2021	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	10	Structure monitored by metered equipment in the pipe. Not visually observed.	20	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
22	8/13/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	45	Structure monitored by metering equipment in the pipe. Not visually observed.	116,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
23	8/13/2021	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	20	Heavy gray water escaping the manhole.	5,000	Overflow subsided following heavy rain event.	Capital improvement projects are being implemented to prevent this overflow from reoccurring.	
24	8/17/2021	W Cold Spring Ln & Towanda Ave	21215	Rain, Trash	Wet	Gwynns Falls	1297	Heavy gray water escaping the manhole during rain event.	32,425	Overflow subsided following heavy rain events. Traffic control was set up.	CCTV inspection and further investigation will take place.	967562
25	8/17/2021	4111 Menlo Dr	21215	Rags, Grease, Trash	Wet	Gwynns Falls	30	Heavy gray water escaping the manhole in the street.	750	Relieved mainline choke with 125 ft of pressure hose.	Confirmed the mainline is clear at this time; CCTV inspection will be performed.	967588
26	8/17/2021	232 E Medwick Garth	21228	Rags, Trash	Wet	N/A	586	Gray water escaping from the manhole.	586	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the mainline is clear at this time; CCTV inspection will be performed.	967690
27	8/19/2021	2319 McCulloh St	21217	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	968159
28	8/24/2021	1610 Elmtree St	21226	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	1	Advised consumer to grant City access to the cleanout so work can be performed.	Location will be revisited to ensure proper functionality.	968886
29	8/24/2021	2900 Belair Rd	21213	Rags, Grease, Trash	Wet	N/A	368	Gray water escaping the manhole	1,840	Relieved mainline choke with 250 ft of pressure hose.	Confirmed line is clear at this time; CCTV inspection will be performed.	968902
30	8/24/2021	3910 Wabash Ave	21215	Rags, Trash, Structural	Wet	Gwynns Falls	632	Heavy gray water escaping the manhole.	9,480	Bypass pumping was set up in order to stop the overflow.	Flushed the mainline; CCTV inspection will be performed to determine if repair is necessary.	968995
31	8/25/2021	2844 Hinsdale Dr	21230	Trash	Wet	N/A	0	Gray water and paper observed at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection and advised the consumer to install a cleanout cap.	969170
32	8/25/2021	807 S Robinson St	21224	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is clear.	969178
33	8/25/2021	1601 S Haven St	21224	Grease	Wet	N/A	0	Gray water observed around the manhole.	10	Relieved mainline choke with pressure hose.	Performed CCTV inspection and ensured there are no issues with the house connection.	969198
34	8/25/2021	1918 W Lafayette Ave	21217	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable, using various cutters.	Performed CCTV inspection and confirmed lateral is clear at this time.	969294
35	8/27/2021	3808 Midheights Rd	21215	Rags, Trash	Dry	Jones Falls	171	Gray water escaping the manhole and entering nearby storm drain.	855	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed; line is flowing freely at this time.	969678
36	8/27/2021	3401 Roland Ave	21211	Rags, Grease, Trash	Dry	Jones Falls	366	Gray water escaping the manhole.	366	Relieved mainline choke with 300 ft of pressure hose.	Performed CCTV inspection and confirmed the line is clear at this time.	969816
37	8/30/2021	1107 Slater Rd	21225	Rags, Grease, Trash	Wet	N/A	78	Gray water escaping the manhole.	780	Relieved 8" mainline choke with 100 ft of pressure hose.	Confirmed the mainline is clear at this time; CCTV inspection will be performed.	969996
38	8/30/2021	1601 S Haven St	21224	Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the manhole.	5	Relieved mainline choke with 70 ft of pressure hose.	CCTV inspection will be performed to determine structural integrity of the pipe.	970148
39	8/30/2021	1110 Ruthland Ave	21213	Grease	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection and confirmed the line is now clear.	970315
				# WWO	33			TOTAL	583,700	UNDER 100 GALLONS	20	