

SSO Notification List

December 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	12/1/2020	6701 Quad Ave	21237	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 130 ft of electric cable.	Confirmed lateral and mainline are clear.	893656
2	12/2/2020	2900 Belmont Ave	21216	Rags, Grease	Wet	N/A	50	Gray water escaping the cleanout at the rear of the property.	10	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	893779
3	12/2/2020	2732 W Lafayette St	21216	Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	8	Relieved choke with pressure truck. Discovered metal pole inside cleanout stack.	Performed CCTV inspection. Left notice to contact a plumber to remove pole.	893766
4	12/2/2020	442 S Augusta Ave	21229	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 35 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	893841
5	12/2/2020	2919 Overland Ave	21214	Structural	Wet	Herring Run	0	Heavy gray water observed around a manhole stack in the woods.	250	Investigated area to determine source and put appropriate measures in place.	Contractor is making repairs to restore manhole and mainline to regular functionality.	
6	12/3/2020	2114 Bank St	21231	Rags	Wet	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable and auger.	Performed CCTV inspection; confirmed lateral is clear.	893903
7	12/3/2020	18 Midvale Rd	21210	Roots	Wet	N/A	0	Gray water observed near the cleanout.	2	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	893993
8	12/3/2020	3303 Abell Ave	21218	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed line is clear.	894014
9	12/3/2020	1300 Parkman Ave	21230	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	894024
10	12/5/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	105	Structure monitored by metering equipment in the pipe. Not visually observed.	12,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital improvement projects.	
11	12/7/2020	3800 Benson Ave	21229	Rags, Trash	Wet	N/A	0	Gray water observed around the manhole.	3	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	894380
12	12/8/2020	401 Edgevale Rd	21210	Rags, Grease, Trash	Wet	Jones Falls	30	Gray water escaping from the manhole.	750	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	894426
13	12/9/2020	304 S Augusta Ave	21229	Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	894636
14	12/10/2020	722 N Fulton Ave	21217	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	894877
15	12/11/2020	1138 E Northern Pkwy	21239	Rags, Trash	Dry	Chinquapin Run	108	Gray water escaping the manhole in the street.	1,080	Relieved mainline choke with 250 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	894975
16	12/11/2020	2525 Arunah Ave	21216	Roots	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	895030
17	12/12/2020	1016 W Northern Pkwy	21210	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	25	Relieved mainline choke with 25 ft of pressure hose.	CCTV inspection will be performed to determine if structural damage is present.	895139
18	12/12/2020	1428 McCullough St	21217	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	7	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear.	895145

SSO Notification List

December 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
19	12/13/2020	15 S Augusta Ave	21229	Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	895207
20	12/13/2020	301 Edgevale Rd	21210	Rags, Roots	Dry	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 35 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	895225
21	12/14/2020	4507 Roland Ave	21210	Rags, Trash	Wet	N/A	0	Gray water observed around the manhole.	7	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear.	895335
22	12/14/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	285	Structure monitored by metering equipment in the pipe. Not visually observed.	456,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
23	12/14/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	25	Manhole adjacent to creek overflowed due to heavy rain.	17,000	Overflow subsided following heavy rain event.	Capital improvement projects are being implemented to prevent this overflow from reoccurring.	
24	12/14/2020	1003 Saint Georges Rd - Private	21210	Rags, Roots	Wet	N/A	0	Gray water observed around privately-owned cleanout.	10	DPW assisted by relieving choke with 175 ft of pressure hose.	Spoke to consumer. Confirmed lateral and mainline are clear.	895328
25	12/15/2020	616 Woodbourne Ave	21212	Roots	Wet	N/A	0	Gray water and debris observed around the cleanout.	5	Ran electric cable through lateral, blockage remained. Bypass pumping may be required in the interim.	Further investigation will continue via CCTV and lateral launch.	895487
26	12/15/2020	6608 Danville Ave	21224	Roots, Trash	Wet	N/A	0	Gray water and debris observed at the front of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	895411
27	12/15/2020	5501 O'Donnell St	21224	Rags, Grease	Wet	N/A	0	Gray water observed around the manhole.	6	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	895588
28	12/15/2020	2423 Reisterstown Rd	21217	Rags, Trash	Wet	Gwynns Falls	117	Gray water escaping the manhole at the rear of the property.	234	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	895622
29	12/16/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	485	Structure monitored by metering equipment in the pipe. Not visually observed.	4,584,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital projects.	
30	12/16/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	230	Manhole adjacent to creek overflowed due to heavy rain.	143,000	Overflow subsided following heavy rain event.	Capital improvement projects are being implemented to prevent the overflow from reoccurring.	
31	12/16/2020	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	255	Heavy gray water escaping manhole.	48,705	Overflow subsided following heavy rain event	Capital improvement projects are being implemented to prevent this overflow from reoccurring.	
32	12/17/2020	4118 Fernhill Ave	21215	Trash	Wet	N/A	204	Gray water escaping the cleanout at the rear of the property.	102	Relieved house connection choke with 8 ft of electric cable.	CCTV inspection will be performed.	897117
33	12/18/2020	Edgevale Rd & Elmwood Rd	21210	Rags, Trash	Wet	Jones Falls	37	Gray water escaping the manhole and entering nearby storm drain.	111	Relieved 6" mainline choke with 75 ft of electric cable.	Confirmed line is clear.	897203
34	12/18/2020	1304 Asbury Rd	21209	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	897362
35	12/18/2020	6701 Quad Ave	21237	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 75 ft of electric cable.	CCTV inspection will be performed.	897367
36	12/22/2020	525 Hurley Ave	21223	Rags, Grease, Trash	Dry	Gwynns Falls	0	Gray water and debris observed around the manhole.	150	Removed debris from the line. Appears to have surcharged recently due to capacity issue.	Confirmed line is clear.	897758

SSO Notification List

December 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
37	12/22/2020	Grantley Rd & Wabash Ave	21215	Rags, Grease, Sand, Gravel, Rocks	Dry	Gwynns Falls	152	Gray water escaping the manhole.	1,520	Relieved mainline choke with 325 ft of pressure hose.	Confirmed line is clear.	897794
38	12/23/2020	4507 Wakefield Rd	21216	Rags, Grease, Trash	Dry	Gwynns Falls	64	Choked mainline causing subsurface overflow to enter nearby storm drain.	192	Relieved mainline choke with 273 ft of pressure hose.	Further investigation, including CCTV inspection, will take place.	897927
39	12/23/2020	1017 W 37th St	21211	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	898111
40	12/24/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1065	Structure monitored by metering equipment in the pipe. Not visually observed.	4,094,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
41	12/25/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	80	Manhole adjacent to creek overflowed due to heavy rain.	295,000	Overflow subsided following heavy rain event.	The overflow will be prevented upon completion of capital improvement projects.	
42	12/26/2020	4120 Kathland Ave	21207	Roots	Wet	N/A	0	Gray water observed around the cleanout.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	898348
43	12/27/2020	2910 N Loudon Ave	21216	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	898429
44	12/28/2020	616 Woodbourne Ave	21212	Rags, Trash	Wet	N/A	0	Heavy gray water observed around the cleanout.	6	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	898490
45	12/28/2020	501 E 36th St	21218	Rags, Trash	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	898550
46	12/28/2020	2926 Erdman Ave	21213	Roots	Wet	N/A	0	Gray water observed at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	898617
47	12/29/2020	310 N Culver St	21229	Structural	Dry	Gwynns Falls	10059	Wastewater infiltrating storm drain from damaged pipe. Found during routine sampling.	50295	During bypass pump installation, dye testing confirmed mainline is no longer leaking.	Bypass pumping will ensure leak does not reoccur while pipe lining takes place.	898665
48	12/29/2020	2245 Eutaw Pl	21217	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	Performed CCTV inspection.	898758
49	12/30/2020	3917 W Mulberry St	21229	Rags, Grease, Trash	Dry	Gwynns Falls	215	Wastewater mainline causing subsurface infiltration into the storm drain.	645	Relieved mainline choke with 450 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	898866
				# WWO	33			TOTAL	9,705,156	UNDER 100 GALLONS	29	