| | | | | | S | SO Notificat | ion Lis | t | | | | |
|---------------|-----------------------|---------------------------------|----------|---|-------------------------------------|-----------------|-------------------|--|--|---|--|--------------|
| December 2022 | | | | | | | | | | | | |
| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet- Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
| 1 | 12/2/2022 | 6615 Harford Rd | 21214 | Rags, Grease, Infiltration | Wet | Herring Run | 1265 | Mainline choke causing sump pump discharges of wastewater onto the street surface. | 2,530 | Relieved mainline choke with 400 ft of pressure hose. | Mainline is now flowing freely. CCTV inspection will be performed. | 1159166 |
| 2 | 12/5/2022 | 1806 E Lafayette Ave | 21213 | Roots | Wet | N/A | - | Gray water observed at the rear of the property. | 2 | Blockage relived with 30 ft of electric machine cable. | Lateral is now clear. To address roots found, location will be placed on route cleaning. | 1159514 |
| 3 | 12/7/2022 | 984 N Franklintown Rd | 21216 | Rags, Grease | Wet | N/A | - | Gray water observed at the front of the property. | 1 | Relieved house connection choke with 60 ft of electric cable. | CCTV will be performed. Flushed and cleaned the mainline. | 1161846 |
| 4 | 12/8/2022 | 4100 Wilke Ave | 21206 | Rags, Roots | Wet | Herring Run | 58 | Gray water escaping the system subsurface; discovered during routine sampling. | 145 | Used high-pressure jet truck to relieve mainline choke. | CCTV inspection will be performed to determine what further steps need to be taken. | 1162022 |
| 5 | 12/9/2022 | 1735 N Ellamont St | 21216 | Rags, Roots, Grease | Dry | N/A | - | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 30 ft of electric cable. | Performed lateral CCTV inspection. | 1162364 |
| 6 | 12/10/2022 | 1639 Moreland Ave | 21216 | Rags, Grease | Dry | Gwynns Falls | 55 | Gray water discharging from sump pump. | 55 | Relieved mainline choke with 300 ft of pressure hose. | CCTV inspection will be performed to determine if further action is needed. | 1162541 |
| 7 | 12/11/2022 | 6301 Boston St | 21224 | Rags, Grease | Dry | Inner Harbor | 105 | Gray water escaping the manhole. | 1,575 | Relieved chokes in three sections of the mainline with 300 ft of pressure hose. | CCTV inspection will be performed to determine if further steps need to be taken. | 1162624 |
| 8 | 12/14/2022 | 4501 E Fayette St | 21224 | Rags, Trash | Dry | N/A | - | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 30 ft of electric cable. | Performed lateral CCTV inspection. | 1163324 |
| 9 | 12/15/2022 | 3900 Belair Rd | 21206 | Rain | Wet | Herring Run | 160 | Manhole adjacent to creek overflowed due to heavy rain. | 750,000 | Overflow subsided following heavy rain event. | Location is equipped with an Event Notification System meter. | _ |
| 10 | 12/15/2022 | 428 E Preston St - SSO Site #72 | 21202 | Rain | Wet | Jones Falls | 480 | Structure monitored by metering equipment in the pipe. Not visually observed. | 669,120 | SSO structure; not applicable. | SSO structure will be closed upon completion of capital improvement projects. | - |
| 11 | 12/15/2022 | 1901 Falls Rd - SSO Site #67 | 21217 | Rain | Wet | Jones Falls | 65 | Structure monitored by metering equipment in the pipe. Not visually observed. | 12,025 | SSO structure; not applicable. | SSO structure will be closed upon completion of capital improvement projects. | - |
| 12 | 12/16/2022 | 278 S Monastery Ave | 21229 | Rags, Rain | Wet | Maidens Choice | 128 | Mainline choke causing sewage to escape from sump pump. | 128 | Relieved mainline choke with 200 ft of pressure hose. | Confirmed the line is clear; CCTV will be performed. | 1164025 |
| 13 | 12/16/2022 | 4105 Liberty Heights Ave | 21207 | Rags, Grease, Sand, Gravel, Rocks | Wet | Gwynns Falls | 150 | Gray water escaping the manhole in the street. | 300 | Relieved mainline choke with 150 ft of pressure hose. | Confirmed the line is clear; CCTV will be performed. | 1164053 |
| 14 | 12/16/2022 | 2600 Insulator Dr | 21230 | Rags, Grease | Wet | N/A | 45 | Gray water escaping the manhole. | 450 | Relieved mainline choke with 250 ft of pressure hose. | Confirmed the mainline is clear; CCTV inspection will be performed. | 1164100 |
| 15 | 12/16/2022 | 5615 York Rd | 21212 | Rags, Grease | Wet | N/A | 140 | Gray water escaping the cleanout. | 14 | Relieved house connection choke with 45 ft of electric cable. | Performed lateral CCTV inspection and confirmed the line is clear. | 1164163 |
| 16 | 12/17/2022 | 1017 W 37th St | 21211 | Roots | Wet | N/A | - | Gray water observed at the rear of the property. | 1 | Relieved house connection choke with 15 ft of electric cable. | Confirmed the lateral and mainline are clear. | 1164242 |
| 17 | 12/19/2022 | 3601 Fords Ln | 21215 | Rags, Trash | Dry | N/A | 375 | Sewage water and debris discharging from cleanout. | 38 | Relieved house connection choke with 30 ft of electric cable. | Confirmed the lateral is now clear; CCTV will be performed. | 1164622 |
| 18 | 12/19/2022 | 612 Wyndhurst Ave | 21210 | Rags, Roots | Dry | N/A | Ι | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 30 ft of electric cable. | CCTV inspection confirmed the lateral is now clear. | 1164643 |
| 19 | 12/19/2022 | 4005 Carlisle Ave | 21216 | Rags, Trash | Dry | N/A | Ι | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | Confirmed the line is clear; CCTV will be performed. | 1164642 |
| 20 | 12/20/2022 | Hamilton Ave & Newholme Ave | 21206 | Rags, Trash | Dry | Moores Run | 205 | Heavy gray water escaping the manhole. | 820 | Used high-pressure jet truck to relieve choke; flushed and cleaned 8" mainline. | CCTV inspection will be performed. | 1164713 |

| SSO Notification List | | | | | | | | | | | | |
|-----------------------|------------|---------------------------------|-------|---|-----|-------------|-----|---|-----------|--|---|---------|
| December 2022 | | | | | | | | | | | | |
| 21 | 12/21/2022 | 530 E 43rd St | 21212 | Rags | Dry | N/A | 65 | Gray water escaping the cleanout at the rear of the property. | 13 | Relieved house connection choke with 30 ft of electric cable. | Advised resident to not flush sanitary wipes and other non- flushable items. | 1165203 |
| 22 | 12/21/2022 | 2728 Reisterstown Rd | 21215 | Rags, Roots | Dry | N/A | 220 | Gray water escaping the cleanout. | 22 | Relieved house connection choke with 30 ft of electric cable. | CCTV inspection will be performed. | 1165390 |
| 23 | 12/22/2022 | 3900 Belair Rd | 21206 | Rain | Wet | Herring Run | 705 | Manhole adjacent to creek overflowed due to heavy rain. | 573,165 | Overflow subsided following heavy rain event. | Location is equipped with an Event Notification System meter. | - |
| 24 | 12/22/2022 | 428 E Preston St - SSO Site #72 | 21202 | Rain | Wet | Jones Falls | 90 | Structure monitored by metering equipment in the pipe. Not visually observed. | 55,080 | SSO structure; not applicable. | SSO structure will be closed upon completion of capital improvement projects. | - |
| 25 | 12/23/2022 | 4400 White Oak Ave | 21215 | Rags | Wet | N/A | _ | Gray water and paper observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | Lateral CCTV inspection confirmed the line is now clear. | 1165686 |
| 26 | 12/24/2022 | 700 Cumberland St | 21217 | Rags | Wet | N/A | _ | Gray water observed at the rear of the property. | 1 | Relieved house connection choke with electric cable. | CCTV will determine if further action is needed. | 1165757 |
| 27 | 12/26/2022 | 2600 N Longwood St | 21216 | Rags, Roots, Grease | Dry | N/A | _ | Gray water observed around the manhole. | 3 | Relieved mainline choke with 100 ft of pressure hose. | CCTV confirmed line is now clear. | 1165856 |
| 28 | 12/26/2022 | 2825 E Chase St | 21205 | Roots | Dry | N/A | _ | Gray water observed at the rear of the property. | 1 | Relieved house connection choke with 30 ft of electric cable. | Performed CCTV inspection. | 1165858 |
| 29 | 12/26/2022 | 2775 W North Ave | 21216 | Roots | Dry | N/A | _ | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 30 ft of electric cable. | Confirmed connection and mainline are clear. | 1165889 |
| 30 | 12/26/2022 | 6211 Biltmore Ave | 21215 | Roots, Trash | Dry | N/A | _ | Gray water and debris observed around the cleanout. | 1 | Relieved house connection choke with 30 ft of electric cable. | Confirmed both the lateral and mainline are clear. | 1165927 |
| 31 | 12/27/2022 | 1806 E Lafayette Ave | 21213 | Rags | Dry | N/A | _ | Gray water observed around the rear cleanout. | 1 | Relieved house connection choke with 30 ft of electric cable. | Performed lateral CCTV inspection. | 1165949 |
| 32 | 12/27/2022 | 3817 Brooklyn Ave | 21225 | Rags, Grease, Trash | Dry | N/A | _ | Gray water observed around the sump pump. | 1 | Relieved mainline choke with 350 ft of pressure hose. | Confirmed the mainline is clear; CCTV will be performed. | 1166150 |
| 33 | 12/28/2022 | N Bond St & E Fayette St | 21231 | Rags, Grease | Dry | N/A | - | Gray water observed around the manhole. | 2 | Flushed the mainline with pressure hose. | CCTV inspection will be performed to determine if further action is needed. | 1166184 |
| 34 | 12/28/2022 | 1520 Clipper Rd | 21211 | Rags, Grease | Dry | N/A | _ | Gray water and debris around the cleanout. | 1 | Relieved house connection choke with 75 ft of pressure hose. | Confirmed the lateral and mainline are clear. | 1166298 |
| 35 | 12/28/2022 | 1534 Elrino St | 21224 | Trash, Sand, Gravel, Rocks | Dry | N/A | _ | Sump pump discharge reaching nearby storm drain. | 5 | Relieved choke with 300 ft of pressure hose. | CCTV will be performed to determine if further action is needed. | 1166428 |
| 36 | 12/30/2022 | 4720 York Rd | 21212 | Grease, Infiltration, Trash, Sand, Gravel, Rocks | Dry | Tiffany Run | 720 | Mainline choke causing a subsurface SSO; infiltrating nearby storm drain. | 180 | Flushed and cleaned 8" mainline with 150 ft of pressure hose. | Confirmed the subsurface SSO has been abated. | 1166816 |
| | | | | # WWO | 16 | | 1 | TOTAL | 2,065,686 | UNDER 100 GALLONS | 23 | |