

SSO Notification List												
December 2025												
Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	12/1/2025	York Rd & Cold Spring Ln	21212	Rags, Trash	Dry	Tiffany Run	299	Wastewater with rags and debris	299	Relieved mainline choke with 300 ft of pressure hose	CCTV Inspection was performed	1497002
2	12/2/2025	5015 Anntana Ave	21206	Rags	Wet	—	—	Observed wastewater coming from side house connection	2	Relieved house connection choke with 35 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1497368
3	12/2/2025	2700 Gwynns Falls Pkwy	21216	Rags, Trash	Wet	—	—	--	3	Relieved choke using 200' of pressure hose	CCTV Inspection will be performed	1497373
4	12/3/2025	1303 Ashland Ave	21205	Rags	Wet	—	—	Observed wastewater coming from rear house connection	1	Attempted to relieve house connection with 45 ft electric cable. Unable to relieve	Bypass Pumping was installed to stop the overflow. Also turned over for mainline cleaning	1497434
5	12/3/2025	4527 Pimlico Rd	21215	Rags, Roots	Wet	—	—	Wastewater with rags and roots	0.5	Relieved choke using electric cables and expander cutters	CCTV Inspection will be performed	1497959
6	12/6/2025	501 S Hanover St	21201	Roots	Dry	—	93	Wastewater with roots	93	Relieved choke using electric cables with sawtooth cutter	CCTV Inspection will be performed	1499332
7	12/6/2025	116 S Wolfe St - (Private)	21231	Rags	Dry	—	—	Observed wastewater coming from side house connection	(1)	Observed house connection located in alley on side between private properties	Plumber's notice left for Consumer to obtain plumber and to locate and install cleanout closer to the property line	1499335
8	12/8/2025	4212 Bonner Rd - (Private)	21216	Trash, Unknown	Dry	—	302	Wastewater with unknown debris	(151)	Relieved choke using pressure hose	Mainline cleaning was performed	1499502
9	12/8/2025	1921 Brunt St	21217	Rags, Grease, Trash	Dry	—	—	Observed wastewater coming from rear house connection	2	House connection choke relieved with Plumber's snake	Confirmed house connection is clear at this time. CCTV was performed	1499510
10	12/8/2025	2415 W Franklin St	21223	Rags, Trash	Dry	—	64	Wastewater with rags and debris	32	Relieved choke using electric cables with sawtooth cutter	CCTV Inspection will be performed	1499614
11	12/10/2025	3101 Pulaski Hwy	21224	Grease	Dry	—	—	Observed wastewater coming from front house connection	8	Relieved house connection choke with 75 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1500092
12	12/10/2025	2207 Druid Hill Ave	21217	Rags, Grease	Dry	—	—	Observed wastewater at the rear of 2207 Druid Hill Ave	25	Relieved mainline choke with 200 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1500234
13	12/11/2025	14 S Payson St	21223	Structural	Dry	—	—	Observed wastewater coming from rear house connection	3	Attempt to relieve house connection choke with 20 ft electric cable and found pipe break	Bypass pumping was installed to stop the overflow and turned over for repairs	1500438
14	12/11/2025	815 Winston Ave	21212	Rags, Infiltration, Trash	Dry	Tiffany Run	446	Choked sanitary sewer pipe overflowing into the adjacent storm drain pipe.	446	Relieved mainline choke with 300 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1500466
15	12/11/2025	1108 N Gilmor St	21217	Rags	Dry	—	—	Observed wastewater coming from rear house connection	1	Relieved house connection choke with 60 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1500563
16	12/12/2025	2603 Talbot Rd	21216	Structural	Dry	—	—	Observed wastewater at front house connection	1	Attempt to relieve house connection choke with 90 ft electric cable, found structural damage	Bypass Pumping installed to stop the SSO and turned over for further investigation and CCTV	1500705
17	12/12/2025	3300 Liberty Heights Ave	21215	Other	Dry	Gwynns Falls	117	Wastewater is infiltrating the storm drain below the surface	585	Crew 759 flushed 8 inch main	CCTV Inspection scheduled	1500785
18	12/13/2025	4641 Park Heights Ave	21215	Sand, Gravel, Rocks, Structural	Dry	Gwynns Falls	—	Observed wastewater coming from front house connection	5	Attempt to relieve house connection choke found broken pipe	Bypass pumping installed to stop the SSO. Referred for further investigation	1501015
19	12/13/2025	2900 Overland Ave	21214	Rags, Trash	Dry	—	—	Wastewater with rags and debris	1	Relieved choke using electric cables with expander cutter	CCTV Inspection will be performed	1501013
20	12/13/2025	3947 Greenmount Ave	21218	Rags, Roots	Dry	—	—	Observed wastewater at front house connection	1	Use electric machine cable to relieve house connection choke	CCTV will be performed. Consumer notified of existing older pipe construction that cause choke	1501022

SSO Notification List												
December 2025												
21	12/13/2025	2212 Russell St	21230	Rags, Trash	Dry	Gwynns Falls	—	Wastewater with rags and debris	5	Relieved main line choke with 350ft of pressure hose	CCTV Inspection scheduled	1501044
22	12/15/2025	1512 Poplar Grove St	21216	Rags, Roots	Wet	—	—	Wastewater with roots and rags	1	Relieved choke using electric machine cable with sawtooth cutter	CCTV Inspection will be scheduled	1501584
23	12/15/2025	4201 Ridgewood Ave	21215	Rags, Roots, Grease	Dry	—	1216	Observed wastewater coming from manhole	608	Relieved mainline choke with 250 ft pressure hose	Confirmed mainline is clear at this time. CCTV was performed	1501712
24	12/15/2025	3749 Elm Ave	21211	Other	Dry	—	193	Wastewater with wastewater cap in connection	386	Relieved choke using electric cable and spearhead cutter	CCTV Inspection will be performed	1501707
25	12/15/2025	3633 Yolando Rd	21218	Rags, Trash	Dry	—	93	Wastewater with rags and debris	139.5	Relieved choke using electric cable with 1/2" cutter	CCTV Inspection will be performed	1501726
26	12/16/2025	3300 Liberty Heights Ave	21215	Structural	Dry	Gwynns Falls	4240	Subsurface SSO infiltrating the storm drain underground.	21200	Bypass pumping installed to stop the SSO.	Mainline sewer will be repaired	1501890
27	12/17/2025	715 N Fulton Ave	21217	Rags, Grease, Trash	Wet	—	—	Observed wastewater coming from rear house connection	1	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1502055
28	12/18/2025	4025 W Belvedere Ave	21215	Grease	Wet	Gwynns Falls	170	Choked sanitary sewer pipe causing sewer overflow into storm pipe a block away. Grease deposits	850	Relieved choke using maintenance equipment	CCTV Inspection scheduled	1502393
29	12/20/2025	2728 Reisterstown Rd	21215	Rags, Roots, Trash	Wet	—	—	Observed wastewater coming from rear house connection	3	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1502798
30	12/21/2025	6 E Lafayette Ave	21202	Rags, Trash	Wet	—	—	Wastewater with rags and trash	1	Relieved choke using electric cable with spearhead cutter	CCTV Inspection will be performed	1502861
31	12/23/2025	W Mulberry St & Lyndhurst St	21229	Rags, Grease, Trash	Dry	Gwynns Falls	102	Mainline choke causing wastewater to infiltrate the storm drain below the surface	204	Relieved mainline choke with 300 ft pressure hose	Confirmed mainline is clear at this time. CCTV was performed	1503383
32	12/24/2025	2415 W Franklin St	21223	Rags	Dry	—	89	Observed wastewater coming from front house connection	89	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1503672
33	12/25/2025	2907 Wayne Ave	21207	Rags, Grease, Trash	Dry	—	—	Observed wastewater at front house connection	1	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1503719
34	12/27/2025	1231 N Gay St	21213	Rags	Dry	—	—	Wastewater with rags	2	Relieved choke with 45ft of electric machine cables	CCTV Inspection will be performed	1503911
35	12/27/2025	1904 N Pulaski St	21217	Structural	Dry	—	—	Observed wastewater at rear house connection	1	Attempts to relieve house connection choke, unable to pass after hitting hard spot 3 ft	Repairs were previously made.	1503927
36	12/28/2025	215 N Castle St	21231	Roots	Dry	—	—	Wastewater with roots	1	Relieved choke with 30ft of electric machine cables	CCTV Inspection will be performed	1503983
37	12/30/2025	1055 Ellicott Drwy	21216	Rags, Trash	Dry	—	—	Wastewater with rags and debris	1	Relieved choke by flushing mainline	CCTV Inspection has been scheduled	1504510
38	12/30/2025	422 S Lehigh St	21224	Rags, Trash	Dry	—	—	Observed evidence of mainline choke in rear alley	1	Relieved mainline choke with 250 ft pressure hose	Confirmed mainline is clear at this time	1504199
39	12/31/2025	2912 Erdman Ave	21213	Roots	Dry	—	—	Observed wastewater at front house connection	3	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1504565
				# WWO	9			TOTAL	25,005	UNDER 100 GALLONS	28	