

## SSO Notification List

February 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/1/2020	904 Nottingham Rd	21229	Rags, Roots, Grease	Dry	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	7	Relieved house connection choke with 30 ft of electric cable and sawtooth cutters.	Confirmed lateral and mainline are clear.	834620
2	2/1/2020	1613 Gwynns Falls Pkwy	21217	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the manhole.	4	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	834642
3	2/2/2020	1927 Kelly Ave	21209	Rags, Trash, Other	Wet	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	8	Restored lateral to regular functionality after it was lined.	Performed CCTV inspection; flushed and cleaned the mainline.	834683
4	2/2/2020	Edgevale Rd & Elmwood Rd	21210	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the manhole in the street.	5	Relieved 6" mainline choke with 100 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	834703
5	2/3/2020	242 N Monroe St	21223	Rags, Sand, Gravel, Rocks	Wet	Gwynns Falls	100	Gray water escaping the cleanout at the rear of the property.	50	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	835031
6	2/3/2020	1710 South Rd	21209	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral is clear.	835072
7	2/4/2020	1201 S Caton Ave	21223	Rags, Roots, Grease, Trash	Wet	Gwynns Falls	135	Heavy gray water escaping the manhole.	2,025	Relieved 8" mainline choke with 25 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	835103
8	2/4/2020	1248 N Gay St	21213	Rags, Grease, Trash	Wet	N/A	160	Gray water intermittently escaping the cleanout at the front of the property.	40	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	835286
9	2/4/2020	3500 Parkdale Ave	21211	Other	Wet	Jones Falls	14144	Sewage sump basin overflowing due to pump failure.	28,288	Pump was replaced to restore regular functionality.	Confirmed pumping cycle is working correctly.	
10	2/4/2020	2300 Garrison Blvd	21216	Rags, Roots, Trash, Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the manhole.	7	Relieved 6" mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	835350
11	2/4/2020	4505 Frederick Ave	21229	Rags, Roots, Trash	Wet	N/A	0	Water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed line is clear; flushed and cleaned the mainline.	835310
12	2/5/2020	3509 E Northern Pkwy	21206	Roots, Unknown	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property. Water is holding in the pipe.	60	Investigating potential obstruction in the lateral. Excavation will be performed.	Line has seen repeated issues. Root cause analysis will take place.	835645
13	2/6/2020	2207 Clifton Ave	21216	Rags, Roots	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	835909
14	2/7/2020	3104 Wilkins Ave	21229	Rain, Trash	Wet	Gwynns Falls	0	Heavy gray water observed around the manhole.	10	Line appears to have relieved itself following rain event.	CCTV inspection will be performed.	836559
15	2/8/2020	2700 Gwynns Falls Pkwy	21216	Rags, Roots	Wet	Gwynns Falls	254	Heavy gray water escaping the manhole.	2,540	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	836776
16	2/8/2020	1618 McCulloh St	21217	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	836778
17	2/9/2020	712 Deaconhill Ct	21225	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	836831
18	2/10/2020	3536 Overview Rd	21215	Rags, Roots, Trash	Wet	N/A	116	Gray water escaping from the cleanout at the rear of the property.	29	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the mainline.	836970
19	2/10/2020	1015 W 37th St	21211	Roots, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Relieved house connection choke and removed roots with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	837118

## SSO Notification List

February 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	2/11/2020	6209 Everall Ave	21206	Roots	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 90 ft of electric cable.	Confirmed lateral is clear.	838069
21	2/13/2020	4657 Harcourt Rd	21214	Rags, Grease, Trash	Wet	Herring Run	120	Choked mainline causing overflow and infiltration into storm drain.	30	Relieved mainline choke with 250 ft of pressure hose.	Confirmed mainline is clear.	838663
22	2/14/2020	4277 Rokeby Rd	21229	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	838896
23	2/14/2020	712 Springfield Ave	21212	Rags, Trash	Wet	Herring Run	257	Sewage discharging and entering storm drain.	1,285	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	839234
24	2/14/2020	3329 Avondale Ave	21215	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	839136
25	2/17/2020	3811 Canterbury Rd	21218	Rags, Trash, Sand, Gravel, Rocks	Dry	Jones Falls	120	Sump pump discharging sewage due to mainline choke.	1,440	Flushed and cleaned 8" mainline with 280 ft of pressure hose to relieve choke.	Confirmed mainline is clear; CCTV inspection will be performed.	844596
26	2/17/2020	6714 Holabird Ave	21222	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	844762
27	2/17/2020	1701 N Caroline St	21213	Rags, Roots, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	844747
28	2/17/2020	800 N Hilton St	21229	Rags, Roots, Trash	Dry	Gwynns Falls	159	Gray water escaping the manhole.	318	Relieved mainline choke with 150 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	844745
29	2/18/2020	532 Winston Ave	21212	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	845407
30	2/18/2020	3500 Parkdale Ave	21211	Other	Dry	Jones Falls	2608	Sewage sump basin overflowing due to pump failure.	5,216	Contractor reset electric components to return pump to regular operation.	Pump will remain online until long-term solution is put into effect.	
31	2/19/2020	265 W 31st St	21211	Rags, Roots	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	845454
32	2/19/2020	3308 Elgin Ave - (Private)	21216	Rags, Roots, Structural	Dry	N/A	0	Gray water observed at the rear of the property. No City utilities are present. Believed to be a broken internal plumbing issue.	20	Lateral and mainline were confirmed clear. Referred to Housing Authority to take proper measures.	Alerted consumer regarding private problem.	845578
33	2/20/2020	3305 Grenton Ave	21214	Rags, Roots, Trash	Dry	Herring Run	162	Choked mainline causing sewage to infiltrate storm drain.	3,240	Relieved mainline choke with 300 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	845985
34	2/20/2020	N Franklintown Rd & W Baltimore St	21223	Rags, Grease, Trash	Dry	Jones Falls	34	Sanitary mainline choke causing wastewater to infiltrate the storm drain. Found during routine sampling.	850	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed line is clear.	846007
35	2/20/2020	530 N Milton Ave	21205	Trash	Dry	N/A	0	Gray water observed at the front of the property.	3	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	846203
36	2/20/2020	1248 N Gay St	21213	Rags, Grease	Dry	N/A	0	Gray water observed at the front of the property.	8	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection and mainline cleaning will be performed.	846297
37	2/24/2020	309 N Payson St	21223	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved 6" house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; mainline will be cleaned.	847120
38	2/24/2020	3501 Trainor Ave	21215	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	847137

## SSO Notification List

February 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
39	2/25/2020	2700 Gibbons Ave	21214	Rags, Roots	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	847758
40	2/26/2020	3309 Saint Ambrose Ave	21215	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	5	Relieved 6" house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear. Flushed and cleaned 8" mainline.	848040
41	2/26/2020	513 W Mulberry St	21201	Grease, Structural, Unknown	Wet	Inner Harbor	0	Gray water observed around the cleanout.	2	Ran 7 ft of electric cable through the lateral; blockage remained.	Further investigation will continue to determine long-term solution. Bypass pumping may be required.	848352
42	2/27/2020	6600 Boston St - (Private)	21224	Rags, Grease, Trash	Wet	N/A	214	Gray water escaping the manhole in the street.	1,070	Relieved mainline choke with 250 ft of pressure hose.	Confirmed line is clear.	848425
43	2/27/2020	3215 Berkshire Rd	21214	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	848701
44	2/28/2020	1280 Riverside Ave	21230	Rags, Trash	Wet	Inner Harbor	263	Gray water escaping the cleanout at the rear of the property.	132	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	849305
45	2/28/2020	210 S Loudon Ave	21229	Rags, Trash	Wet	Gwynns Falls	0	Heavy gray water and debris observed around the cleanout.	10	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	849020
46	2/28/2020	4206 Maine Ave	21207	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	849293
47	2/29/2020	2409 Smith Ave	21230	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the side of the property.	3	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear.	849334
48	2/29/2020	1516 Cox St	21211	Rags, Grease, Trash	Wet	N/A	48	Gray water escaping the manhole.	144	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	849334
49	2/29/2020	1114 Wood Heights Ave	21211	Rags, Roots	Wet	Jones Falls	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	849365
				# WWO	31			TOTAL	45,791	UNDER 100 GALLONS	36	