SSO Notification List

February 2023

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet- Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|-----------------------|---------------------------------|----------|--------------------------------------|-------------------------------------|------------------|-------------------|--|--|---|--|--------------|
| 1 | 2/1/2023 | N Bond St & E Fayette St | 21231 | Structural, Unknown | Dry | N/A | | Gray water observed around the manhole in the street. | 3 | Flushed and cleaned 24" mainline with 25 ft of pressure hose. | Further investigation, including CCTV inspection, will take place to determine next steps. | 1194299 |
| 2 | 2/2/2023 | 1911 Jefferson St | 21205 | Rags, Grease, Sand, Gravel, Rocks | Dry | Northwest Harbor | | Gray water observed around the sump pump and storm drain. | 3 | Relieved mainline choke with 200 ft of pressure hose. | Confirmed the mainline is now clear. | 1194759 |
| 3 | 2/2/2023 | 2932 Mosher St | 21216 | Roots | Dry | N/A | | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | CCTV inspection confirmed the lateral is now clear. | 1194820 |
| 4 | 2/4/2023 | 5208 Kelway Rd | 21239 | Rags, Roots, Grease | Dry | N/A | | Gray water observed around the manhole in the street. | 3 | Relieved mainline choke with 200 ft of pressure hose. | Confirmed the mainline is now clear; CCTV will be performed. | 1195219 |
| 5 | 2/6/2023 | 2809 Georgetown Rd | 21230 | Rags, Roots, Grease, Unknown | Dry | N/A | 10 | Gray water and debris observed around the cleanout. | 2 | Relieved m/l choke with pressure truck 300 ft of 8" in h | ссти | 1195325 |
| 6 | 2/6/2023 | 100 W Barre St | 21201 | Rags, Unknown | Dry | N/A | | Gray water and debris observed around the manhole. | 1 | Ran 30 ft of electric cable through the house connection. | Lateral launch will take place to clear the line. | 1195354 |
| 7 | 2/6/2023 | 4300 Keswick Rd | 21210 | Rags, Trash | Dry | N/A | | Gray water observed around the manhole in the street. | 2 | Flushed and cleaned 8" mainline with 200 ft of pressure hose. | Confirmed the line is clear; CCTV inspection will be performed. | 1195616 |
| 8 | 2/6/2023 | 820 N Broadway | 21205 | Roots | Dry | N/A | | Gray water observed at the rear of the property. | 1 | Relieved house connection choke with 30 ft of electric cable. | Confirmed the lateral is now clear. | 1195627 |
| 9 | 2/7/2023 | 5615 York Rd | 21212 | Grease, Trash | Dry | N/A | | Gray water observed around the cleanout. | 3 | Relieved house connection choke with 30 ft of electric cable. | Confirmed the lateral is now clear. | 1195844 |
| 10 | 2/8/2023 | 2932 Mosher St | 21216 | Roots | Dry | N/A | | Gray water observed at the front of the property. | 1 | Relieved house connection choke with 45 ft of electric cable. | CCTV confirmed the line is now clear. | 1195962 |
| 11 | 2/8/2023 | 1910 N Pulaski St | 21217 | Rags, Grease | Dry | N/A | | Twin lateral choke causing overflow from cleanout. | 2 | Relieved choke with 200 ft of pressure hose. | Confirmed lines are clear at this time. | 1195217 |
| 12 | 2/8/2023 | Druid Park Dr & Reisterstown Rd | 21215 | Rags, Trash | Dry | Jones Falls | 1403 | Heavy gray water escaping the manhole and reaching waterway. | 14030 | Relieved 10" mainline choke with 150 ft of pressure hose. | Confirmed the line is now clear; CCTV inspection will be performed. | 1196163 |
| 13 | 2/8/2023 | 3647 Park Heights Ave | 21215 | Rags | Dry | N/A | | Gray water and debris observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | CCTV inspection confirmed the line is now clear. | 1196200 |
| 14 | 2/9/2023 | 4547 Keswick Rd | 21210 | Structural | Dry | Stony Run | 46500 | Sewer lateral pipe leaking into adjacent storm pipe. | 930 | Pipe was repaired to stop the leak and abate the SSO. | Line has been restored to regular functonality. | |
| 15 | 2/9/2023 | 2627 N Calvert St | 21218 | Structural | Dry | Jones Falls | 39180 | Damaged pipe causing SSO that is reaching a waterway. | 3918 | Installed new pipe and manhole to change flow and stop the SSO. | New system will allow flow to redirect and remain stable. | |
| 16 | 2/9/2023 | 115 N Ellwood Ave | 21224 | Rags, Trash | Dry | N/A | | Gray water and debris observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | Performed CCTV inspection; confirmed lateral is clear. | 1196300 |
| 17 | 2/10/2023 | 530 E 43rd St | 21212 | Rags | Dry | N/A | | Mainline choke causing cleanout to overflow. | 1 | Relieved mainline choke with 250 ft of pressure hose. | Confirmed the lines are now clear; CCTV inspection will be performed. | 1196782 |
| 18 | 2/10/2023 | 2020 Hollins Ferry Rd | 21230 | Rags, Roots, Grease | Dry | N/A | 1551 | Gray wastewater overflowing from sanitary manhole. | 7755 | Relieved mainline choke with 275 ft of pressure hose. | CCTV inspection will be performed. | 1196626 |
| 19 | 2/11/2023 | 1213 Anglesea St | 21224 | Structural, Unknown | Dry | N/A | | Gray water observed at the front of the property. | 1 | Ran 17 ft of electric cable through the lateral; blockage remained. | Bypass pumping may be needed while structural damage is repaired. | 1197046 |
| 20 | 2/12/2023 | 3710 Gibbons Ave | 21206 | Rags, Roots | Dry | N/A | | Gray water observed at the rear of the property. | 1 | Relieved house connection choke with 45 ft of electric cable. | CCTV confirmed the lateral is now clear. | 1197069 |

| SSO | Notification | lict |
|-----|--------------|------|
| | | |

| | SSO Notification List | | | | | | | | | | | |
|---|-----------------------|------------------------------|-------|------------------------------------|-----|--------------|------|---|--------|--|--|---------|
| February 2023 | | | | | | | | | | | | |
| 21 | 2/12/2023 | 108 N Fremont Ave | 21201 | Rags, Grease | Dry | N/A | | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 60 ft of electric cable. | Confirmed both the lateral and mainline are now clear. | 1197081 |
| 22 | 2/13/2023 | 1200 Broening Hwy | 21224 | Rags, Grease | Wet | Inner Harbor | 590 | Gray water escaping the manhole at the front of the property. | 118 | Relieved mainline choke with 300 ft of pressure hose. | Confirmed the line is now clear, CCTV inspection will be performed. | 1197338 |
| 23 | 2/13/2023 | 520 N Clinton St | 21205 | Structural | Wet | N/A | | Gray water observed around the cleanout. | 1 | House connection will need repair. Contractor has been engaged on project. | Line will be restored to regular functionality. | 1197232 |
| 24 | 2/13/2023 | 2024 Mount Royal Ter | 21217 | Roots | Wet | N/A | | Sewage and rags observed near the cleanout. | 1 | Relieved house connection choke with 75 ft of electric cable. | Confirmed the lateral is now clear. | 1197263 |
| 25 | 2/14/2023 | 1541 Cox St | 21211 | Rags, Roots | Wet | N/A | | Gray water observed at the front of the property. | 1 | Relieved house connection choke. Discovered broken mainline. | Mainline will be repaired to restore system to regular functionality. | 1197463 |
| 26 | 2/15/2023 | 2861 Mayfield Ave | 21213 | Roots | Wet | N/A | | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | CCTV inspection confirmed the lateral is now clear. | 1198029 |
| 27 | 2/15/2023 | 6611 Chandlery St | 21224 | Sand, Gravel, Rocks, Structural | Wet | N/A | | Heavy discharge from a medical waste facility. | 1000 | Ran electric cable through the lateral, determined structural damage exists. | Line will need repair to restore the system's functionality. | 1198028 |
| 28 | 2/17/2023 | 3900 Belair Rd | 21206 | Rain | Wet | Herring Run | 135 | Manhole adjacent to creek overflowed due to heavy rain. | 583065 | Overflow subsided following heavy rain event. | Location is equipped with an Event Notification System meter. | |
| 29 | 2/17/2023 | N Bentalou St & Walbrook Ave | 21216 | Rags, Grease | Wet | Gwynns Falls | 360 | Sewage escaping the manhole. | 1800 | Relieved mainline choke with 200 ft of pressure hose. | Confirmed the line is clear; CCTV inspection will be performed. | 1198561 |
| 30 | 2/17/2023 | 5007 W Forest Park Ave | 21207 | Rags, Roots, Rain, Grease | Wet | Gwynns Falls | 275 | Gray water escaping the manhole in the street. | 13750 | Overflow subsided following heavy rain event. | Flushed and cleaned the 8" mainline with 200 ft of pressure hose. | 1198574 |
| 31 | 2/20/2023 | 2447 Harriet Ave | 21230 | Rags, Trash | Dry | Gwynns Falls | 280 | Heavy gray water escaping the manhole. | 560 | Relieved mainline choke with 200 ft of pressure hose. | Confirmed the line is clear; CCTV inspection will be performed. | 1198969 |
| 32 | 2/21/2023 | 5430 Force Rd | 21206 | Rags, Grease, Trash | Dry | Moores Run | 610 | Gray water escaping the manhole in the alleyway. | 305 | Relieved mainline choke with 200 ft of pressure hose. | CCTV inspection will be performed to ensure all blockage was remvoed. | 1199011 |
| 33 | 2/22/2023 | 410 Hollen Rd | 21212 | Rags, Roots | Dry | N/A | | Gray water and debris observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | Lateral CCTV inspection will be performed. | 1199358 |
| 34 | 2/22/2023 | 1305 Winchester St | 21217 | Rags, Grease | Wet | N/A | | Gray water observed at the front of the property. | 1 | Relived house connection choke with 30 ft of electric cable. | CCTV confirmed the lateral and mainline are now clear. | 1199477 |
| 35 | 2/23/2023 | 1120 E Cold Spring Ln | 21239 | Rags, Trash | Wet | Herring Run | 1044 | Sewage and water escaping the manhole. | 522 | Relieved choke with pressure hose and electric cable. | CCTV will be performed; confirmed line is clear. | 1199660 |
| 36 | 2/24/2023 | 518 N Clinton St | 21205 | Grease | Wet | N/A | | Gray water observed at the front of the property. | 1 | Relieved house connection choke with 60 ft of electric cable. | Confirmed the lateral is now clear. | 1199850 |
| 37 | 2/26/2023 | 2932 Mosher St | 21216 | Rags, Roots | Dry | N/A | | Gray water and debris observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | Confirmed the lateral and mainline are now both clear. | 1200321 |
| 38 | 2/26/2023 | 732 E 35th St | 21211 | Rags, Roots | Dry | N/A | | Gray water observed around the cleanout. | 1 | Relieved house connection choke with 45 ft of electric cable. | Confirmed the lateral and mainline are clear; CCTV inspection will be performed. | 1200326 |
| 39 | 2/27/2023 | 3212 Guilford Ave | 21218 | Rags, Trash | Dry | N/A | | Gray water observed at the front of the property. | 1 | Relieved house connection choke with 30 ft of electric cable. | Performed CCTV inspection and the results showed the line is clear. | 1200429 |
| 40 | 2/28/2023 | 100 Kane St | 21224 | Structural | Wet | N/A | | Sewage escaped mainline during repair work. | 50 | Contractor for City schools in the process of repairing mainline. | Once repair is complete, line will be restored to regular functionality. | 1200851 |
| 41 | 2/28/2023 | 2058 Harford Rd | 21218 | Roots, Sand, Gravel, Rocks | Wet | N/A | | Gray water observed around the cleanout. | 2 | Ran 60 ft of electric cable; blockage temporarily relieved at this time. | Further investigation, including a CCTV inspection, will take place. | 1201031 |
| # WWO 14 TOTAL 627,843 UNDER 100 GALLONS 29 | | | | | | | | | | | | |