

## SSO Notification List

February 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/2/2024	3902 Hillsdale Rd	21215	Rags, Roots	Dry	—	—	Gray water and paper observed near the cleanout.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed the lateral is clear at this time.	1307306
2	2/3/2024	1128 N Gilmor St	21217	Rags	Dry	—	—	Gray water and debris observed at the rear of the property.	1	Partially relieved choke with electric cable.	Advised resident to have plumber investigate their side of the lateral.	1307577
3	2/4/2024	9 N Decker Ave	21224	Rags	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1307684
4	2/6/2024	2113 E Chase St	21205	Rags	Dry	—	—	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with electric cable.	Confirmed the issue has been resolved at this location.	1308363
5	2/8/2024	929 N Wolfe St	21205	Rags, Grease	Dry	Northwest Harbor	78	Sewage and water escaping manhole and entering nearby storm drain.	234	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear at this time; CCTV will be performed.	1308878
6	2/8/2024	125 N Hilton St	21229	Rags, Roots	Dry	Gwynns Falls	111	Choked mainline causing subsurface SSO to enter the storm drain system.	555	Relieved mainline choke with 200 ft of pressure hose.	Abatement confirmed via the Office of Research & Environmental Protection.	1308949
7	2/8/2024	6640 Quad Ave	21237	Rags, Roots	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is clear.	1309024
8	2/11/2024	2410 Druid Hill Ave	21217	Rags, Trash	Dry	Jones Falls	218	Sewage water discharging from the manhole cover.	654	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is now clear; CCTV will be performed.	1309522
9	2/12/2024	18 Midvale Rd	21210	Unknown	Dry	—	—	Gray water and debris observed near the cleanout.	2	Ran 35 ft of electric cable through lateral; determined structural damage exists.	House connection will be repaired to restore functionality.	1309570
10	2/12/2024	1315 N Stockton St	21217	Roots	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV will be performed to confirm line is clear.	1309781
11	2/12/2024	3513 Oakmont Ave	21215	Roots	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV will be performed to ensure all obstructions were removed.	—
12	2/14/2024	4401 Frankford Ave	21206	Rags, Trash	Wet	Biddison Run	218	Choked mainline causing subsurface overflow into the adjacent storm drain.	218	Relieved mainline choke with 400 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1310461
13	2/16/2024	2546 Tolley St	21230	Rags, Trash	Dry	Gwynns Falls	—	Gray water observed in the street and near storm drain.	10	Relieved mainline choke with 150 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1311033
14	2/16/2024	6600 Moravia Park Dr	21237	Rags, Trash	Dry	Moores Run	190	Heavy gray water with tinted industrial discharge flowing from house connection.	950	Relieved house connection choke with 60 ft of electric cable.	CCTV inspection confirmed the lateral is now clear.	1311169
15	2/17/2024	2455 Etting St	21217	Rags	Dry	—	—	Gray water and paper observed near cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and advised resident to replace missing cleanout cap.	1311540
16	2/19/2024	226 Mallow Hill Rd	21229	Rags, Roots	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1311619
17	2/20/2024	5217 Linden Heights Ave	21215	Rags, Roots	Dry	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 40 ft of electric cable.	Confirmed the lateral is now clear.	1311870
18	2/21/2024	2523 Arunah Ave	21223	Rags	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed.	1312091
19	2/21/2024	423 E Hamburg St	21230	Rags, Trash	Dry	—	—	Mainline choke causing cleanout to overflow.	2	Relieved mainline choke with 250 ft of pressure hose.	CCTV will be performed to ensure all obstructions were removed.	1312139
20	2/21/2024	3455 Erdman Ave	21213	Rags, Grease, Trash	Dry	Herring Run	147	Choked sewer causing subsurface overflow into adjacent storm drain.	441	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear; CCTV will be performed.	1312205

SSO Notification List

February 2024

21	2/23/2024	816 N Fulton Ave	21217	Rags	Wet	—	—	Gray water and paper observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV will confirm whether further action is needed.	1312771
22	2/23/2024	1231 N Gay St	21213	Rags, Roots	Wet	—	—	Gray water observed at the front cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1312893
23	2/23/2024	800 W 33rd St	21211	Rags, Trash	Wet	—	—	Evidence of an SSO at the front of the property.	1	Relieved house connection choke with 75 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1312971
24	2/26/2024	1614 Moreland Ave	21216	Structural Damage	Wet	—	—	Sewage water and rags around cleanout.	2	Ran electric cable through the lateral; determined structural damage exists.	House connection will be repaired to restore system to regular functionality.	1313136
25	2/26/2024	607 E 35th St	21218	Sand, Gravel, Rocks	Wet	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed City lateral is clear.	1313409
26	2/27/2024	844 W Pratt St	21201	Rags	Dry	—	—	Gray water and paper observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	1313506
27	2/28/2024	3623 Milford Ave	21207	Rags	Wet	—	—	Gray water and debris observed at the side of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is now clear.	—
28	2/29/2024	6212 Wallis Ave	21215	Rags, Roots	Wet	—	—	Gray water and paper observed near the front cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1314359
29	2/29/2024	402 Kingston Rd	21229	Roots	Wet	Maidens Choice	—	Gray water observed near the cleanout and nearby storm drain.	4	Relieved house connection choke with 45 ft of electric cable.	CCTV will be performed to determine if further actions is needed.	1314595
				# WWO	9			TOTAL	3,090	UNDER 100 GALLONS	23	