

SSO Notification List												
February 2025												
Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/3/2025	3840 Greenspring Ave	21211	Roots, Trash	Wet	Jones Falls	—	Observed wastewater from manhole enter nearby adjacent storm drain	10	Relieved mainline choke with 300 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1412938
2	2/3/2025	2310 N Rosedale St	21216	Rags, Trash	Wet	—	—	Wastewater with rags and debris	7	Flushed and cleaned 300' of 8" sewer main	CCTV Inspection will be performed	1412975
3	2/3/2025	2821 Eastshire Dr	21230	Rags, Trash	Wet	—	—	Sewer water and rags and trash	25	Used 30' of electric cable with saw tooth to relieve house connection choke	CCTV will be performed	1413006
4	2/4/2025	6201 Greenspring Ave	21209	Rags, Trash	Dry	—	—	Wastewater with heavy presence of rags and debris	5	Used 105' of electric machine with cutter to relieve choke	CCTV Inspection will be performed	1413086
5	2/4/2025	807 Spedden St	21216	Rags, Grease, Trash	Dry	Gwynns Falls	166	Wastewater observed from manhole overflowing into adjacent storm drain	166	Relieved mainline choke with 400 ft pressure hose	Confirmed mainline is clear at this time. Referred for mainline cctv	1413106
6	2/4/2025	5405 N Charles St	21210	Rags, Grease, Trash	Dry	Stony Run	1710	Manhole discharging wastewater into nearby athletic field and storm inlet.	42750	Relieved mainline choke with 150 ft of pressure hose.	Abatement confirmed via Office of Research & Environmental Protection.	1413227
7	2/5/2025	Moyer Ave & Woodhome Ave	21234	Rags, Grease, Trash	Dry	Moores Run	1484	Subsurface mainline choke infiltrating into nearby storm drain	7420	Relieved mainline choke with 345 ft pressure hose	Confirmed mainline is flowing freely. Referred for mainline CCTV	1413700
8	2/6/2025	6409 Falkirk Rd	21239	Trash	Wet	—	—	Sewer water with toilet tissue and debris	5	Ran 45ft of cable to relieve house connection choke	CCTV will be performed	1414459
9	2/8/2025	Greenspring Ave & W Cold Spring Ln	21209	Rags, Grease, Trash	Wet	Jones Falls	608	Wastewater with rags, trash and grease deposits	60800	Flushed and cleaned 8" sewer with 400' of pressure hose	CCTV Inspection will be performed	1415054
10	2/9/2025	104 Elmhurst Rd	21210	Roots	Wet	—	180	Observed wastewater coming from rear house connection	90	Relieved house connection choke with 50ft electric cable	Confirmed house connection is clear at this time	1415147
11	2/10/2025	Deepdene Rd & Edgevale Rd	21210	Rags, Grease	Dry	Jones Falls	98	Sewer water with rags and grease deposits	980	Relieved main line choke with 325ft of pressure hose	CCTV Inspection will be performed	1415326
12	2/10/2025	501 Collins Ave	21229	Roots, Trash	Dry	—	—	Observed wastewater coming from rear house connection	4	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear. CCTV will be performed	1416465
13	2/11/2025	5919 Simmonds Ave	21215	Grease, Sand, Gravel, Rocks	Dry	—	—	Observed wastewater coming from manhole	3	Relieved mainline choke with 145 ft pressure hose	Referred for CCTV	1416794
14	2/11/2025	W Redwood St & Penn St	21201	Rags, Grease, Trash	Dry	—	396	Mainline choke causing wastewater to infiltrate the storm drain below the surface	1980	Relieved mainline choke with 350' of pressure hose	CCTV Inspection will be performed	1416830
15	2/13/2025	1740 E Lanvale St	21213	Roots	Wet	—	—	Observed wastewater at rear house connection	2	Relieved house connection choke with 30ft electric machine cable	Confirmed house connection and mainline is clear at this time. CCTV was performed	1417692
16	2/13/2025	732 Deepdene Rd	21210	Structural	Wet	Stony Run	27558	Wastewater leaking from sanitary sewer into storm drain structures	13779	Contractor performed a point repair to stop the leak	Abatement confirmed via OREP	1417828
17	2/14/2025	2838 Woodbrook Ave	21217	Rags, Roots, Trash	Wet	Gwynns Falls	198	Observed wastewater coming from rear house connection into alley	99	Relieved house connection choke with 35 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1418973
18	2/16/2025	2300 Cedley St	21230	Rags, Grease, Trash	Wet	—	143	Observed wastewater coming from manhole	715	Relieved mainline choke with 275 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV to be performed	1419224
19	2/16/2025	3410 Lynchester Rd	21215	Trash	Wet	—	—	Wastewater with debris	3	Relieved house connection choke with 45ft of electric machine cable	CCTV Inspection will be performed	1419246
20	2/17/2025	6201 Greenspring Ave	21209	Rags	Wet	Western Run	230	Observed wastewater coming from front house connection	115	Relieved house connection choke with 120 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1419281

SSO Notification List												
February 2025												
21	2/17/2025	3913 Glen Ave	21215	Trash	Wet	—	86	Wastewater and tissue	43	House connection was relieved with 30' of electric cable	CCTV Inspection was performed	1419291
22	2/18/2025	2300 Hollins St	21223	Rags, Grease, Trash	Wet	Gwynns Falls	142	Wastewater with rags, grease, and trash	710	Relieved mainline choke and cleaned 650' of 8" sewer main	CCTV Inspection has been scheduled	1419390
23	2/18/2025	831 Harlem Ave	21201	Structural	Wet	—	—	Wastewater with mud	3	Unable to relieve the blockage with electric machine cable. Bypass pumping set up	This location will be investigated using CCTV.	1419737
24	2/19/2025	907 N Rose St	21205	Rags, Roots	Dry	—	—	Wastewater with rags and roots	5	Relieved choke using 30' of electric cable with cutter attachment	CCTV will be performed	1420248
25	2/19/2025	2500 Queen Anne Rd	21216	Rags, Trash	Dry	Gwynns Falls	—	Observed wastewater coming from manhole	10	Relieved mainline choke flushed and cleaned with 305 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1420315
26	2/20/2025	2415 W Franklin St	21223	Rags, Roots	Dry	Gwynns Falls	460	Observed wastewater coming from front house connection	115	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear, and CCTV was performed	1420920
27	2/20/2025	2200 W Lexington St	21223	Rags, Roots	Dry	—	—	Wastewater with rags and roots	4	Relieved house connection choke using 30' of electric cable with cutter	CCTV Inspection has been scheduled	1420949
28	2/21/2025	2536 Washington Blvd	21230	Rags, Trash	Dry	—	—	Wastewater with rags and debris	6	Relieved house connection choke with 45' of electric cables & cutter	CCTV Inspection will be performed	1420998
29	2/21/2025	404 N Athol Ave	21229	Rags, Trash	Dry	Gwynns Falls	318	Wastewater with rags and debris	15900	Relieved main line choke with 400ft of pressure hose	CCTV Inspection will be performed	1421294
30	2/21/2025	1533 Barclay St	21202	Roots	Dry	—	—	Observed wastewater at rear house connection	2	Relieved house connection choke with 30 ft electric machine cable	Confirmed house connection is clear at this time. CCTV was performed	1421303
31	2/22/2025	2611 Gwynndale Ave (Private)	21207	Grease	Dry	—	198	Wastewater with grease at the rear of the property.	(5940)	Relieved mainline choke with 345 ft of pressure hose	No action taken at this time	1421373
32	2/23/2025	3434 Wilkens Ave	21229	Rags, Grease, Trash	Dry	—	2799	Observed wastewater coming from manhole	13995	Relieved mainline choke flushed and cleaned with 450 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1421582
33	2/25/2025	1512 Poplar Grove St	21216	Roots	Dry	—	—	Observed wastewater coming from rear house connection	2	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time, CCTV was performed	1422306
34	2/26/2025	3917 Pascal Ave (Private)	21226	Trash	Dry	—	—	Wastewater with trash	(5)	Relieved choke with 34' of electric cable with head and cutter	Referred resident to plumber	1422450
35	2/26/2025	5814 Hillen Rd	21239	Rags, Grease, Trash	Dry	—	2107	Observed wastewater coming from manhole	6,321	Relieved mainline choke with 350 ft pressure hose	Confirmed mainline is clear and flowing at this time. Referred for CCTV inspection	1422519
36	2/26/2025	Edmondson Ave & Braddish Ave	21223	Rags, Grease, Trash	Dry	Gwynns Falls	1356	Wastewater with rags, grease and trash	6,780	Relieved choke with 250 ft of pressure hose.	CCTV Inspection will be performed	1422568
37	2/27/2025	268 Deepdene Rd	21210	Rags, Trash	Dry	Jones Falls	331	Observed wastewater coming from manhole	1,655	Relieved mainline choke with 230 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1422779
38	2/27/2025	4201 Glenmore Ave	21206	Rags, Roots	Dry	—	—	Wastewater with roots and rags	2	Relieved choke using 30 ft. of electric cable with saw teeth	CCTV Inspection was performed	1422990
39	2/28/2025	1512 Eutaw Pl	21217	Rags, Grease, Trash	Dry	Jones Falls	133	Subsurface SSO wastewater infiltrating adjacent storm drain.	665	Relieved choke with 250 ft of pressure hose	CCTV Inspection scheduled	1423186
				# WWO	15			TOTAL	175,176	UNDER 100 GALLONS	20	