

## SSO Notification List

January 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2021	4808 Sipple Ave	21206	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	899104
2	1/1/2021	1312 John St	21217	Rags, Roots, Trash	Wet	N/A	0	Gray water and debris observed at the rear of the property.	2	Relieved mainline choke with 250 ft of pressure hose. Ran 45 ft of electric cable through the lateral.	Confirmed lines are clear; CCTV inspection will be performed.	899112
3	1/1/2021	624 Oldham St	21224	Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed at the rear of the property.	1	Ran 8 ft of electric cable through the lateral; blockage remained.	Stones need to be removed from the line. Bypass pump may be installed to account for flow during this process.	899136
4	1/1/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	295	Structure monitored by metering equipment in the pipe. Not visually observed.	1,898,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
5	1/1/2021	3900 Belair Rd	21206	Rain	Wet	Herring Run	110	Manhole adjacent to creek overflowed due to heavy rain.	242,000	Overflow subsided following heavy rain event.	Overflow will be prevented after completion of capital improvement projects.	
6	1/2/2021	1904 N Pulaski St	21217	Rags, Roots, Trash	Wet	N/A	0	Gray water and debris observed at the rear of the property.	3	Relieved 6" line choke with 250 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	899178
7	1/3/2021	1044 Bethune Rd - Private	21225	Rags, Grease, Trash	Wet	N/A	130	Gray water escaping the private manhole behind the property.	5,850	DPW assisted by relieving mainline choke with 275 ft of pressure hose.	Confirmed line is clear.	899235
8	1/3/2021	3652 Elm Ave	21211	Roots	Wet	N/A	0	Gray water observed at the side of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	899256
9	1/3/2021	3308 Rosekemp Ave	21214	Rags, Trash	Wet	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	899231
10	1/3/2021	315 Winston Ave	21212	Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	899233
11	1/4/2021	N Washington St & E Fayette St	21231	Rags, Grease, Trash	Wet	Inner Harbor	145	Gray water escaping the manhole and entering nearby storm drain.	290	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	899371
12	1/5/2021	3721 Roland Ave	21211	Rags, Roots, Grease	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 90 ft of electric cable.	Confirmed line is clear.	899444
13	1/5/2021	914 E 20th St	21218	Rags, Grease, Trash	Wet	Jones Falls	263	Gray water escaping the manhole and entering nearby storm drain.	526	Relieved mainline choke with 400 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	899573
14	1/5/2021	251 S Morley St	21229	Rags, Roots, Grease, Trash	Wet	N/A	148	Gray water escaping from the cleanout at the front of the property.	74	Relieved choke with 45 ft of electric cable and 200 ft of pressure hose.	CCTV inspection will be performed.	899517
15	1/5/2021	426 Swale Ave	21225	Rags, Grease, Trash, Sand, Gravel, Rocks	Wet	N/A	1079	Gray water escaping the manhole and entering nearby storm drain.	10,790	Relieved mainline choke with 100 ft of pressure hose and vacuum.	Confirmed mainline is clear.	899667
16	1/6/2021	2200 Cecil Ave - Private	21218	Structural	Wet	N/A	0	Gray water observed at the rear of the property.	5	Ran 7 ft of electric cable through the lateral.	Determined structural damage exists on the consumer's pipe. Left notice to contact private plumber.	899676
17	1/6/2021	5914 Glenoak Ave	21214	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	899744
18	1/6/2021	1239 N Broadway	21213	Rags	Wet	N/A	0	Gray water and debris observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	899763
19	1/7/2021	1631 Gwynns Falls Pkwy	21217	Roots	Dry	N/A	0	Heavy gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	899911

## SSO Notification List

January 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	1/8/2021	1817 Penrose Ave	21223	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved mainline and house connection chokes with 300 ft of pressure hose.	Confirmed lines are clear.	900143
21	1/8/2021	6501 Erdman Ave - Private	21205	Rags, Trash	Dry	Herring Run	1285	Heavy gray water escaping private manhole.	6,425	DPW assisted by relieving privately-owned manhole with 25 ft of pressure hose.	Confirmed line is clear.	900192
22	1/8/2021	1203 Morling Ave	21211	Rags, Grease, Trash	Dry	N/A	0	Gray water and debris observed around the manhole.	5	Relieved mainline choke with 10 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	900214
23	1/9/2021	1647 Northwick Rd	21218	Rags	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	900217
24	1/10/2021	642 E Clement St	21230	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Flushed and cleaned the mainline; CCTV inspection will be performed.	900270
25	1/10/2021	2901 W North Ave	21216	Rags, Grease, Trash	Dry	Gwynns Falls	147	Gray water escaping the manhole.	735	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	900302
26	1/11/2021	1816 Poplar Grove St	21216	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole in the street.	5	Flushed and cleaned 8" mainline with 250 ft of pressure hose.	Confirmed line is clear.	900324
27	1/11/2021	Hartsdale Rd & Perring Pkwy	21214	Unknown	Dry	Herring Run	3011	Heavy wastewater discharging from manhole. Found during routine sampling.	451,650	Contractor set up bypass pumping to stop the overflow.	Further investigation will take place, including CCTV inspection, to determine cause and address any issues found.	900393
28	1/11/2021	5501 Alhambra Ave	21212	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	900491
29	1/11/2021	2413 Ashland Ave	21205	Rags, Trash	Dry	N/A	204	Gray water escaping the manhole.	204	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	900481
30	1/12/2021	726 N Patterson Park Ave	21205	Trash	Dry	N/A	0	Gray water observed at the rear of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Confirmed line is clear; flushed and cleaned the mainline.	900529
31	1/13/2021	2661 Wilkens Ave	21223	Trash	Dry	N/A	0	Gray water observed at the rear of the property.	5	Relieved mainline choke with 500 ft of pressure hose.	Confirmed mainline is clear.	900841
32	1/13/2021	4403 Frederick Ave - Private	21229	Rags, Grease, Trash	Dry	Gwynns Falls	314	Gray water escaping privately-owned manhole.	3,140	DPW assisted by relieving mainline choke with 275 ft of pressure hose.	Confirmed line is clear.	900755
33	1/14/2021	1001 E 43rd St	21212	Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	901000
34	1/14/2021	3700 Eastwood Dr	21206	Structural	Dry	Herring Run	TBD	Wastewater infiltrating nearby storm drain subsurface. Confirmed via dye testing.	Ongoing, 0.5 gpm	Further investigation will take place to determine best way to abate overflow.	Pipe lining or point repair should prevent further leaks from this line.	901015
35	1/14/2021	5600 Benton Heights Ave	21206	Rags, Roots	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	901756
36	1/14/2021	400 N Highland Ave	21224	Rags, Trash	Dry	Inner Harbor	0	Gray water observed near manhole and storm drain.	10	Relieved 8" mainline choke with 65 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	901659
37	1/16/2021	5007 Greenhill Ave	21206	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the mainline.	901947
38	1/16/2021	205 Club Rd	21210	Rags, Roots, Trash	Wet	N/A	0	Heavy gray water observed at the rear of the property.	10	Relieved mainline choke with 240 ft of pressure hose.	CCTV inspection will be performed.	901954

## SSO Notification List

January 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
39	1/17/2021	726 N Patterson Park Ave	21205	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	902007
40	1/17/2021	3103 Elm Ave	21211	Trash, Unknown	Wet	N/A	0	Gray water observed at the rear of the property.	4	Ran 60 ft of electric cable through the lateral. Flushed and cleaned the mainline.	CCTV inspection will be performed.	902012
41	1/18/2021	3302 The Alameda	21218	Rags, Roots, Grease	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	902074
42	1/18/2021	3511 Greenspring Ave	21209	Rags, Roots, Grease, Unknown	Wet	N/A	0	Gray water observed at the front of the property.	2	Ran 40 ft of electric cable through the lateral, blockage remained.	Flushed and cleaned the mainline. CCTV inspection will be performed.	902077
43	1/20/2021	2424 W Rogers Ave	21209	Rags, Grease, Trash	Dry	N/A	0	Gray water and paper observed at the rear of the property.	2	Relieved house connection choke with 105 ft of electric cable.	Confirmed lateral is clear; cleaned the mainline.	902329
44	1/20/2021	1405 John St	21217	Rags, Grease, Trash	Dry	N/A	0	Gray water observed in the rear alleyway.	3	Relieved house connection choke with electric cable.	CCTV inspection will be performed.	902424
45	1/20/2021	1001 Dartmouth Glen Way	21212	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	902444
46	1/20/2021	5708 Falls Rd	21209	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with electric cable.	CCTV inspection will be performed.	902499
47	1/20/2021	2114 Bank St	21231	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	902504
48	1/21/2021	3721 Roland Ave	21211	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran electric cable through the lateral. Gave notice to install cleanout closer to mainline.	CCTV inspection will be performed.	902550
49	1/21/2021	1019 N Arlington Ave	21217	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	902678
50	1/22/2021	101 Cotswold Rd	21210	Roots	Dry	N/A	0	Gray water and paper observed at the front of the property.	2	Relieved house connection choke with electric cable.	Performed CCTV inspection; mainline will be cleaned.	902847
51	1/23/2021	3902 Maine Ave	21207	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	903001
52	1/25/2021	1143 Homestead St	21218	Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	903894
53	1/25/2021	2215 Cross Country Blvd	21209	Roots	Dry	N/A	0	Heavy gray water observed at the front of the property.	5	Relieved house connection choke with 90 ft of electric cable.	Performed CCTV inspection.	904013
54	1/26/2021	251 S Morley St	21229	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	3	Relieved mainline choke with 250 ft of pressure hose. Ran 30 ft of electric cable through the lateral.	Confirmed mainline and lateral are clear.	903947
55	1/27/2021	1226 N Bentalou St	21216	Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	904085
56	1/27/2021	3721 Roland Ave	21211	Rags, Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	1	Pumped down connection to temporarily give relief to the line.	Cleanout must be moved closer to the mainline in order for more work to be performed.	904092
57	1/27/2021	2800 Rosalind Ave	21215	Rags	Dry	N/A	0	Gray water observed around the cleanout.	5	Relieved choke with 75 ft of electric cable and 250 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	904233

## SSO Notification List

January 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
58	1/27/2021	5622 Frankford Ave	21206	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved mainline choke with 110 ft of pressure hose.	Confirmed mainline is clear.	904240
59	1/28/2021	301 Edgevale Rd	21210	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	5	Relieved mainline choke with 65 ft of pressure hose.	Confirmed mainline is clear.	904461
60	1/29/2021	3919 W Mulberry St	21229	Rags, Grease, Trash	Dry	Gwynns Falls	117	Subsurface SSO infiltrating into the storm drain inlet catch basin.	117	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	904519
61	1/29/2021	1111 Harlem Ave	21217	Rags, Roots, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed.	904555
62	1/30/2021	2610 Oswego Ave	21215	Rags, Trash	Dry	N/A	0	Gray water and paper observed at the rear of the property.	2	Ran electric cable through the lateral. Advised consumer to install cleanout.	Confirmed line is clear.	904701
				<b># WWO</b>	<b>23</b>			<b>TOTAL</b>	<b>2,604,508</b>	<b>UNDER 100 GALLONS</b>	<b>48</b>	