

## SSO Notification List

January 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/3/2022	1831 S Charles St	21230	Rags, Grease	Wet	N/A	224	Mainline choke causing gray water to escape the cleanout.	112	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed.	1006450
2	1/3/2022	1905 Aisquith St	21218	Rags, Roots, Grease	Wet	Jones Falls	900	Gray water escaping the manhole in the street.	900	Relieved mainline choke with 285 ft of pressure hose.	Confirmed the line is clear at this time; CCTV inspection will be performed.	1006492
3	1/5/2022	509 S Exeter St	21202	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved mainline choke with 65 ft of pressure hose.	Confirmed both the mainline and lateral are now clear.	1007066
4	1/5/2022	Belvedere Ave & York Rd	21212	Rags, Infiltration	Dry	Chinquapin Run	1470	Choked sanitary mainline causing a subsurface SSO.	36,750	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	1007182
5	1/5/2022	600 S Hanover St	21230	Roots, Grease	Dry	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear; flushed and cleaned the mainline.	1007250
6	1/6/2022	605 Orkney Rd	21212	Structural	Dry	Chinquapin Run	17435	Broken mainline leaking into adjacent storm drain.	8,718	Contractor lined pipe the stop the overflow.	Abatement confirmed via the Office of Compliance and Research.	1008175
7	1/6/2022	2732 W Lafayette Ave	21216	Rags	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection to ensure the lateral is clear.	1008311
8	1/6/2022	3300 Windsor Ave	21216	Rags, Roots, Trash	Dry	N/A		Gray water observed around the manhole.	2	Relieved mainline choke with 500 ft of pressure hose.	Confirmed the mainline is clear at this time.	1008328
9	1/7/2022	1906 N Pulaski St	21217	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 40 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1008692
10	1/7/2022	3002 Elizabeth Ave	21230	Rags, Roots	Dry	N/A	449	Mainline choke causing multiple cleanouts to overflow.	112	Relieved mainline choke with 300 ft of pressure hose.	Conducted CCTV inspection and plan to have follow-up work performed.	1008732
11	1/10/2022	1719 Covington St	21230	Rags	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are flowing freely.	1009083
12	1/10/2022	28 N Morley St	21229	Rags, Grease, Trash	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 75 ft of electric cable.	CCTV inspection will be performed. Flushed and cleaned the mainline.	1008814
13	1/10/2022	5512 Elderon Ave	21215	Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is now clear.	1009156
14	1/10/2022	424 Calvin Ave	21218	Roots, Grease, Trash, Unknown	Wet	N/A		Gray water observed around the cleanout.	1	Ran 45 ft of electric cable through the lateral.	Further investigation will take place to ensure the blockage is removed.	1009207
15	1/11/2022	1312 John St	21217	Rags, Grease, Sand, Gravel, Rocks	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	1009491
16	1/12/2022	2121 E Chase St	21213	Unknown	Wet	N/A		Gray water observed at the rear of the property.	1	Ran 10 ft of electric machine cable through the lateral; blockage remained.	Further investigation will take place. Bypass pumping may be needed in the interim.	1009559
17	1/12/2022	4000 Buena Vista Ave	21211	Rags	Dry	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with 35 ft of pressure hose.	Confirmed the lateral and mainline are both clear.	1009771
18	1/13/2022	3713 Clipper Rd	21211	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; lateral and mainline are both clear.	1010085
19	1/17/2022	3900 Belair Rd	21206	Rain	Wet	Herring Run	95	Manhole adjacent to creek overflowed due to heavy rain.	532,000	Overflow subsided following heavy rain event.	SSOs will be prevented at this location after completion of capital improvement projects.	—
20	1/17/2022	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	60	Structure monitored by metering equipment in the pipe. Not visually observed.	26,040	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	—
21	1/17/2022	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	135	Structure monitored by metering equipment in the pipe. Not visually observed.	286,065	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	—
22	1/18/2022	2803 Elgin Ave	21216	Rags, Grease	Wet	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with 200 ft of pressure hose.	Confirmed the lateral is clear; flushed and cleaned the 8" mainline.	1011362
23	1/18/2022	1333 Glenwood Ave	21239	Rags, Grease, Trash	Wet	Chinquapin Run	900	Gray water actively escaping the manhole.	900	Relieved mainline choke with 310 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed.	1011552
24	1/19/2022	2204 Booth St	21223	Rags, Grease	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	CCTV inspection and mainline cleaning will take place.	1011634
25	1/19/2022	1638 Forest Hill Ave	21230	Rags, Roots	Wet	Gwynns Falls	245	Gray water escaping the manhole.	2,450	Relieved mainline choke with 275 ft of pressure hose.	CCTV will be performed; confirmed mainline is clear at this time.	1011639

## SSO Notification List

### January 2022

26	1/20/2022	1600 N Calvert St	21202	Rags, Grease, Trash	Wet	Jones Falls	104	Gray water escaping the manhole.	104	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is clear; CCTV will be performed.	1012098
27	1/20/2022	Moravia Park Dr & Amberwood Rd	21206	Rags, Grease, Trash	Wet	N/A	4156	Gray water escaping the manhole.	8,312	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is now flowing freely; CCTV inspection will be performed.	1012204
28	1/20/2022	1541 N Broadway	21213	Rags, Roots	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	1012171
29	1/21/2022	510 N Chester St	21205	Rags	Wet	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	1012465
30	1/24/2022	5216 The Alameda	21239	Rags, Roots, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed and mainline cleaned.	1012893
31	1/25/2022	2130 Mount Holly St	21216	Roots	Dry	N/A		Gray water observed around the rear cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; flushed and cleaned the mainline.	1013390
32	1/26/2022	3300 Windsor Ave	21216	Rags	Dry	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1013775
33	1/28/2022	3910 Wabash Ave	21215	Rags, Grease, Trash	Dry	Gwynns Falls	305	Gray water escaping the manhole.	1,525	Relieved mainline choke with 70 ft of pressure hose.	Confirmed the line is clear at this time; CCTV inspection will be performed.	1014304
34	1/28/2022	2115 Letitia Ave	21230	Structural	Dry	Gwynns Falls	20495	Sewage escaping the manhole and entering nearby stream.	2,049,500	DPW contractor is pumping the line into nearby tanks to stop the overflow.	Mainline will be repaired to restore the system to regular functionality.	1014306
35	1/28/2022	930 N Payson St	21217	Rags	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	1014370
36	1/29/2022	22 S Tremont Rd	21229	Rags, Grease, Trash	Dry	N/A		Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and the mainline are both clear.	1015048
				# WWO	19			TOTAL	2,953,515	UNDER 100 GALLONS	22	