

## SSO Notification List

July 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/3/2019	4009 Barrington Rd	21207	Rags, Roots	Wet		0	Gray water and rags observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	736767
2	7/3/2019	1147 Monroe Cir	21225	Structural	Wet		0	Gray water observed around the cleanout.	4	Ran 9 ft of electric cable. Found damage on consumer's side.	Left door notice to have private plumber investigate.	736820
3	7/4/2019	3501 Trainor Ave	21215	Grease, Trash	Wet		0	Gray water and grease observed around the cleanout.	3	Relieved house connection choke with electric cable and pressure hose.	Confirmed lateral is clear; flushed the mainline.	736900
4	7/5/2019	1520 Clipper Rd	21211	Rags, Grease	Wet	Jones Falls	742	Gray water, grease, and rags escaping the cleanout.	1,113	Flushed the cleanout and mainline to remove obstructions.	Further investigation will take place to determine possible issues.	736996
5	7/6/2019	436 Kane St	21224	Structural	Wet	Harbor	0	Gray water observed around the manhole.	70	Temporarily abated the overflow by flushing the mainline.	Engaging a contractor to make necessary repairs.	737062
6	7/8/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	360	Structure monitored by metering equipment in the pipe. Not visually observed.	1,304,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
7	7/8/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	80	Structure monitored by metering equipment in the pipe.	26,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
8	7/8/2019	4800 Briarclift Rd	21229	Rags, Roots, Rain, Grease, Trash	Wet		249	Heavy water escaping the manhole.	6,225	Relieved 10" mainline choke with 175 ft of pressure hose.	Mainline CCTV inspection will be performed.	737249
9	7/9/2019	1300 Excelsior Ave	21227	Rags, Roots, Trash	Wet		0	Heavy gray water observed around the manhole.	15	Relieved mainline choke with 400 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	737504
10	7/9/2019	2909 Orleans St	21224	Trash, Structural	Wet		0	Gray water observed in the rear alleyway.	90	Informed consumer of damage on private side of lateral.	Flushed the mainline and performed CCTV inspection.	737518
11	7/9/2019	4603 Briarclift Rd	21229	Trash, Sand, Gravel, Rocks	Wet		289	Sewage discharging from sanitary stack near woods.	14,450	Relieved mainline choke using pressure hose and bypass pumping.	Mainline CCTV inspection will be performed.	737587
12	7/9/2019	436 Kane St	21224	Structural	Wet	Harbor	964	Colored water escaping the manhole in the street.	4,820	Contractor set up a bypass pump to abate the overflow while repairs are completed.	CCTV inspection will be performed when work is finished.	737700
13	7/9/2019	1147 Monroe Cir	21225	Grease, Sand, Gravel, Rocks	Wet		0	Grease and water observed around the cleanout.	4	Ran 13 ft of electric cable through lateral.	Left notice for possible damage on consumer's side of pipe.	737577
14	7/11/2019	4401 Kennison Ave	21215	Rain	Wet	Gwynns Falls	327	Heavy gray water surcharging from a manhole.	9,810	Flushed and cleaned mainline with 300 ft of pressure hose.	Overflow subsided following heavy rain event. Confirmed mainline is clear.	738276
15	7/11/2019	Lancaster St & S Eden St	21231	Rags, Trash	Wet		0	Gray water observed around manholes.	10	Flushed and cleaned 8" mainline with 200 ft of pressure hose.	Confirmed mainline is clear.	738268
16	7/11/2019	Garrison Ave & Queensberry Rd - SSO Site #1	21215	Rain	Wet	Jones Falls	35	Structure monitored by metering equipment in the pipe. Not visually observed.	11,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
17	7/11/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	400	Structure monitored by metering equipment in the pipe. Not visually observed.	1,515,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
18	7/11/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	340	Structure monitored by metering equipment in the pipe.	2,059,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
19	7/11/2019	W Cold Spring Ln & Ayrdale Ave - SSO Site #13	21215	Rain	Wet	Jones Falls	45	Structure monitored by metering equipment in the pipe. Not visually observed.	1,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	

## SSO Notification List

July 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	7/11/2019	3900 Belair Rd	21206	Rain	Wet	Herring Run	160	Manhole adjacent to creek overflowed due to heavy rain.	2,389,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
21	7/12/2019	701 Denison St	21229	Rags, Roots	Wet		0	Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	738434
22	7/12/2019	Drew St & E Pratt St	21224	Rags, Trash	Wet		0	Gray water and grease observed around the manhole.	4	Relieved mainline choke with 100 ft of pressure hose.	Confirmed that the line is clear.	738541
23	7/13/2019	5900 Poplin Ave	21209	Rags, Roots, Grease, Sand, Gravel, Rocks	Wet		0	Gray water and debris observed around the manhole.	15	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	738670
24	7/14/2019	1520 Clipper Rd	21211	Rags, Grease, Trash	Wet		883	Heavy gray water and debris escaping the cleanout at the rear of the property.	1,766	Ran 70 ft of electric cable and flushed the lateral with pressure hose.	CCTV inspection will be performed. Bypass pumping may need to be set up if overflow reoccurs.	738777
25	7/18/2019	5802 Eastern Ave	21224	Rags, Grease, Trash	Wet		0	Gray water observed around the manhole.	10	Relieved mainline choke with 300 ft of pressure hose.	Performed dye test and CCTV inspection.	749700
26	7/20/2019	4009 Barrington Rd	21207	Rags, Roots, Trash	Wet		0	Water and debris observed around the cleanout at the front of the property.	7	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	750135
27	7/20/2019	1618 McCulloh St	21217	Rags, Grease, Trash	Wet		0	Sewage observed around the cleanout.	4	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	750142
28	7/20/2019	3404 Glen Ave - SSO Site #155	21215	Unknown	Dry	Jones Falls	1450	Structure monitored by metered equipment in the pipe. Not visually observed.	500	SSO structure is monitored by metering equipment in the pipe; not applicable.	SSO structure will be closed upon completion of necessary capital project. Physically checked site location.	
29	7/22/2019	4906 Westhills Rd	21229	Rags, Trash	Dry		0	Gray water and paper observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	750279
30	7/24/2019	4029 N Rogers Ave	21207	Rags, Roots	Wet		0	Gray water observed around the cleanout at the side of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	751253
31	7/25/2019	1510 N Patterson Park Ave	21213	Rags, Trash	Wet		0	Gray water and paper observed around the cleanout.	20	Relieved house connection choke with electric cable and expander.	Performed lateral CCTV inspection.	751309
32	7/25/2019	325 Yale Ave	21229	Rags, Grease, Trash	Wet		0	Water and paper observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	751450
33	7/30/2019	2532 Marbourne Ave	21230	Rags, Roots	Dry		69	Gray water escaping the cleanout at the front of the property.	35	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	752702
34	7/30/2019	2708 Hillsdale Rd	21216	Grease, Sand, Gravel, Rocks	Dry		0	Sewage and grease observed around the cleanout at the front of the property.	8	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	753052
35	7/30/2019	3350 Chestnut Ave	21211	Rags, Trash	Dry		0	Gray water and grease observed at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed; flushed and cleaned the mainline.	753071
36	7/31/2019	1600 Ashburton St	21216	Rags, Grease, Trash	Dry		65	Sewage escaping the cleanout at the rear of the property.	195	Relieved choke with electric cable and pressure hose.	CCTV inspection will be performed.	753301
				# WWO	30			TOTAL	7,344,190	UNDER 100 GALLONS	21	