

SSO Notification List

July 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/1/2021	2205 Crest Rd	21209	Rags, Roots, Trash	Wet	N/A	0	Heavy gray water observed around the manhole.	2	Relieved mainline choke with 40 ft of pressure hose.	Mainline is now flowing freely; CCTV inspection will ensure all obstructions were removed.	957772
2	7/2/2021	4800 Falls Rd	21210	Rags, Roots	Wet	Jones Falls	307	Heavy gray water escaping the manhole.	1,535	Relieved 8" mainline choke with 250 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	958020
3	7/8/2021	2510 Queen Anne Rd	21216	Structural	Dry	N/A	18740	Wastewater leaking from house connection into storm drain.	187	City construction crew repaired the broken lateral to stop the SSO.	Line has been restored to regular functionality.	959070
4	7/9/2021	4120 W Belvedere Ave	21215	Rags, Trash	Dry	N/A	60	Gray water escaping the cleanout at the front of the property.	12	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	959259
5	7/11/2021	4903 W Forest Park Ave	21216	Rags, Roots	Wet	N/A	0	Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 15 ft of electric cable.	Performed lateral CCTV inspection and results showed the line to be clear.	959622
6	7/12/2021	115 N Ellwood Ave	21224	Rags, Grease, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results showed line is clear.	959900
7	7/13/2021	4507 Schenley Rd	21210	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral and mainline are clear at this time.	959940
8	7/13/2021	4209 Maine Ave	21207	Sand, Gravel, Rocks	Dry	Gwynns Falls	0	Gray water observed around the cleanout at the rear of the property.	3	Ran 20 ft of electric cable through the lateral.	CCTV inspection will be performed to determine if blockage remains.	960173
9	7/16/2021	2601 Oswego Ave - Private	21215	Rags, Grease, Trash	Dry	Jones Falls	100	Gray water escaping a privately-owned collection system.	(100)	DPW assisted by relieving choke with 250 ft of pressure hose.	City confirmed that private line is no longer choked.	960992
10	7/18/2021	1110 Key Hwy	21230	Rags, Trash, Sand, Gravel, Rocks	Dry	Inner Harbor	237	Heavy gray water escaping the manhole.	1,185	Relieved mainline choke with 50 ft of pressure hose.	Confirmed the mainline is now flowing freely. CCTV inspection will be performed.	961214
11	7/18/2021	4103 8th St	21225	Rags, Trash, Sand, Gravel, Rocks	Dry	N/A	0	Gray water observed around the manhole in the street.	3	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	961231
12	7/20/2021	6701 Quad Ave	21237	Rags, Roots, Grease	Dry	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection to confirm there are no longer obstructions in the pipe.	961664
13	7/20/2021	1719 W Lexington St	21223	Rags, Roots, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is now flowing freely.	961843
14	7/21/2021	2319 McCulloh St	21217	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 35 ft of electric cable.	Performed CCTV inspection and results showed the line to be clear.	962055
15	7/21/2021	2738 Baker St	21216	Rags, Trash	Dry	Gwynns Falls	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the 8" mainline.	962075
16	7/21/2021	4003 Springdale Ave	21207	Trash	Dry	N/A	0	Gray water observed around the manhole.	2	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is clear at this time; CCTV inspection will be performed.	962083
17	7/24/2021	3903 Mayberry Ave	21206	Roots, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	962581
18	7/25/2021	722 N Fulton Ave	21217	Sand, Gravel, Rocks	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are clear at this time.	962627
19	7/27/2021	3700 Springdale Ave	21216	Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Informed consumer to replace cleanout cap in order to have CCTV inspection performed.	963064
20	7/27/2021	2216 Lyndhurst Ave	21216	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection and results showed the line is clear.	963237
21	7/27/2021	5013 Greenhill Ave	21206	Rags, Trash	Dry	N/A	0	Gray water observed on the front sidewalk.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection to confirm the line is clear.	963243
22	7/27/2021	2121 Kentucky Ave	21218	Roots, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is clear.	963254

SSO Notification List

July 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
23	7/28/2021	2557 W Baltimore St	21223	Structural	Dry	N/A	55	Gray water slowing escaping the cleanout.	6	Ran 5 ft electric machine cable; blockage remained. CCTV will determine next steps.	Advised consumer to install cleanout cap to prevent debris from falling into lateral.	963357
				# WWO	4			TOTAL	2,952	UNDER 100 GALLONS	19	