

SSO Notification List

July 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/2/2022	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	25	Structure monitored by metered equipment in the pipe. Not visually observed.	3,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
2	7/2/2022	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	30	Structure monitored by metering equipment in pipe.	11,010	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
3	7/2/2022	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	35	Structure discharges to an outfall pipe and is monitored by metering equipment in the pipe.	63,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
4	7/2/2022	N Charles St & Lafayette Ave - SSO Site #154	21201	Rain	Wet	Jones Falls	30	Structure monitored by metering equipment in the pipe. Not visually observed.	84,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
5	7/2/2022	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	60	Structure monitored by metering equipment in the pipe. Not visually observed.	657,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
6	7/2/2022	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	115	Structure monitored by metering equipment in the pipe. Not visually observed.	235,980	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
7	7/3/2022	401 Overhill Rd	21210	Rags, Grease, Trash	Dry	—	—	Gray water observed around the manhole.	2	Relieved mainline choke with pressure hose.	CCTV inspection will be performed to ensure the line is clear.	1116642
8	7/4/2022	1378 N Carey St	21217	Structural, Unknown	Dry	—	—	Gray water observed around the cleanout.	1	Ran 60 ft of electric cable through the lateral.	Flushed and cleaned the mainline. Advised consumer to have line inspected.	1116712
9	7/4/2022	1645 Walterswood Rd	21239	Rags, Roots	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1116724
10	7/5/2022	4518 Pimlico Rd	21215	Roots	Wet	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection confirmed line is clear.	1117152
11	7/6/2022	2207 Barclay St	21218	Rags, Grease	Wet	Jones Falls	182	Gray water escaping the manhole and entering storm drain.	728	Relieved mainline choke with 320 ft of pressure hose.	CCTV inspection will be performed to determine main cause of SSO.	1117203
12	7/11/2022	3013 Royston Ave	21214	Roots	Wet	—	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are clear.	1118628
13	7/16/2022	24 Gorman Ave	21223	Rags, Roots	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed lateral and mainline are clear at this time.	1120789
14	7/17/2022	3030 Poplar Terr	21216	Roots	Wet	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1120891
15	7/17/2022	1600 W 41st St	21211	Rags, Roots, Grease, Trash	Wet	—	—	Gray water observed around the manhole.	10	Relieved mainline choke with 350 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1120894
16	7/19/2022	116 E Randall St	21230	Rags, Grease	Wet	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with electric cable.	Lateral CCTV inspection will be performed.	1121427
17	7/19/2022	3500 Parkdale Ave	21211	Structural	Wet	Jones Falls	2760	Pump discharge pipe has separated.	2,760	Pump discharge pipe was repaired to restore regular functionality.	Long-term solution is still being implemented for myriad issues at this location.	0
18	7/19/2022	436 Kane St	21224	Rags, Grease, Trash	Wet	—	—	Gray water observed on the street.	5	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is now clear and flowing freely.	1121761
19	7/20/2022	919 E Fort Ave	21230	Rags, Roots, Grease, Trash	Wet	—	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1121850
20	7/20/2022	1516 Patapsco St	21230	Roots	Wet	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	1121958

SSO Notification List

July 2022

21	7/22/2022	2 N Wheeler Ave	21223	Rags	Wet	—	—	Gray water observed at the side of the property.	1	Relieved mainline choke with 100 ft of pressure hose.	Investigation will take place to determine if further action is needed.	1122347
22	7/25/2022	1378 N Carey St	21217	Rags, Roots	Dry	—	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the mainline and lateral are clear.	1123082
23	7/25/2022	1740 E Lanvale St	21213	Rags	Dry	—	—	Gray water observed at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection. Advised consumer to install cleanout cap.	1123122
24	7/25/2022	4301 Keswick Rd	21210	Rags, Roots, Grease	Dry	—	—	Gray water observed near the manhole.	2	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is clear at this time.	1123172
25	7/28/2022	4311 Penhurst Ave	21215	Sand, Gravel, Rocks, Unknown	Dry	—	—	Gray water observed around the cleanout.	1	Ran 75 ft of electric cable through the lateral; partially relieved.	CCTV inspection will be performed.	1124152
				# WWO	17			TOTAL	1,057,512	UNDER 100 GALLONS	17	