

SSO Notification List

July 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/3/2023	147 N Streeper St	21224	Rags, Other	Wet	N/A	—	Gray water observed at the rear of the property.	1	Flushed and cleaned mainline; will revisit location to fix cleanout cap.	Regular functionality will be restored to system.	1239899
2	7/3/2023	3900 Belair Rd	21206	Rain	Wet	Herring Run	60	Manhole adjacent to creek overflowed due to heavy rain.	162000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
3	7/7/2023	3700 Gwynns Falls Pkwy	21216	Rags	Dry	N/A	—	Gray water observed at the property.	1	Relieved choke with 30 ft of electric cable.	CCTV confirmed the line is clear.	1240735
4	7/7/2023	816 N Fulton Ave	21217	Roots	Wet	N/A	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is now clear.	—
5	7/9/2023	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	85	Structure monitored by metered equipment in the pipe. Not visually observed.	9010	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
6	7/9/2023	3900 Belair Rd	21206	Rain	Wet	Herring Run	50	Manhole adjacent to creek overflowed due to heavy rain.	111000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
7	7/10/2023	341 E 27th St	21218	Roots	Wet	N/A	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1241459
8	7/10/2023	2640 Miles Ave	21211	Sand, Gravel, Rocks, Unknown	Wet	N/A	—	Gray water observed around the cleanout.	1	Ran electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will take place.	1241482
9	7/10/2023	3724 Elmley Ave	21213	Rags, Roots	Wet	N/A	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and flushed the mainline.	1241486
10	7/11/2023	631 McCabe Ave	21212	Rags, Grease, Sand, Gravel, Rocks	Wet	Tiffany Run	1280	Heavy wastewater leaving sanitary manhole and entering nearby storm drain inlet.	128000	Used high-pressure jet truck to relieve mainline choke in 60 ft section.	CCTV inspection will be performed to determine if further steps are necessary.	1241639
11	7/12/2023	3408 Round Rd	21225	Rags, Grease	Wet	N/A	—	Gray water and paper around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	CCTV confirmed the lateral is clear.	1241949
12	7/12/2023	3120 Berkshire Rd	21214	Rags, Roots	Wet	N/A	—	Debris observed at the front of the property.	1	Blockage relieved with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1241957
13	7/12/2023	6013 Wallis Ave	21215	Rags, Grease, Trash	Dry	N/A	—	Gray water and debris around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection to confirm the lateral is clear.	1242195
14	7/14/2023	2640 Miles Ave	21211	Sand, Gravel, Rocks	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 8 ft of electric cable.	CCTV will be performed; left door notice for consumer.	1242581
15	7/21/2023	3900 Belair Rd	21206	Rain	Wet	Herring Run	25	Manhole adjacent to creek overflowed due to heavy rain.	82000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
16	7/21/2023	1809 Penrose Ave	21223	Rags, Grease	Wet	N/A	—	Gray water and paper around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral and mainline are clear.	1244326
17	7/24/2023	3900 Belair Rd	21206	Rain	Wet	Herring Run	20	Manhole adjacent to creek overflowed due to heavy rain.	25000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
18	7/26/2023	2800 Walbrook Ave	21216	Rags	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed the lateral is clear at this time.	1245665
19	7/27/2023	4410 Frankford Ave	21206	Sand, Gravel, Rocks	Dry	Biddison Run	62	Choked sewer pipe overflowing into adjacent storm pipe.	62	Used high-pressure jet truck to flush & relieve mainline choke.	CCTV inspection will be completed to determine if further action is needed.	1245901
20	7/28/2023	3300 Sequoia Ave	21215	Rags, Trash	Dry	Gwynns Falls	110	Wastewater escaping manhole and infiltrating the nearby storm drain below the surface.	110	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear at this time.	1246497
				# WWO	15			TOTAL	517,194	UNDER 100 GALLONS	13	