

## SSO Notification List

July 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/2/2024	1540 S Hanover St	21230	Structural	Wet	—	—	Rear house connection choke	1	Ran electric cable; discovered damage to the pipe.	Lateral will need to be repaired.	1354978
2	7/5/2024	1417 Hollins St	21223	Rags	Dry	—	—	Wastewater observed near the cleanout.	1	Relieved house connection choke with 40 ft of electric cable.	CCTV confirmed the line is now clear.	1355548
3	7/8/2024	1408 W Pratt St	21223	Roots	Dry	—	—	Wastewater observed at the rear of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed line is clear; CCTV will be performed.	1356009
4	7/9/2024	1520 Clipper Rd	21211	Rags	Dry	—	—	Gray water and debris observed near cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral is clear.	1356276
5	7/11/2024	Ravenwood Ave & Longview Ave	21213	Rags, Trash, Sand, Gravel, Rocks	Dry	Herring Run	186	Wastewater from choked mainline escaping sump pump and entering storm drain.	930	Relieved mainline choke with 350 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1356836
6	7/11/2024	Guilford Ave & E 26th St	21218	Rags, Trash	Dry	—	—	Wastewater observed near the manhole.	5	Relieved mainline choke with 400 ft of pressure hose.	Confirmed line is clear. OREP will do follow-up testing.	1356932
7	7/13/2024	429 Westgate Rd	21229	Roots, Trash	Wet	—	—	Water and paper observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1357152
8	7/14/2024	2113 E Chase St	21205	Sand, Gravel, Rocks, Structural	Wet	—	—	Wastewater observed near the cleanout.	1	Partially relieved choke with electric cable; pipe damage is present.	Lateral will be fully repaired to stop any future issues.	1357260
9	7/15/2024	6200 Pulaski Hwy	21205	Rags, Grease	Wet	—	—	Wastewater observed near the manhole.	5	Relieved mainline choke with 250 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1357399
10	7/17/2024	118 N Fremont Ave	21201	Rags, Trash	Wet	—	—	Wastewater and debris observed near cleanout and storm drain.	6	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection to confirm the pipe is clear.	1358025
11	7/18/2024	2819 Boarman Ave	21215	Rags, Grease, Trash	Wet	—	300	Wastewater and debris discharging from the cleanout.	30	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and confirmed lateral is now clear.	1360433
12	7/21/2024	1130 Homestead St	21218	Roots	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is now clear; CCTV will be performed.	1360783
13	7/22/2024	3808 Chatham Rd	21215	Grease	Wet	—	—	Wastewater observed near the cleanout.	1	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is now clear.	1361082
14	7/24/2024	4910 Chalgrove Ave	21215	Rags	Wet	—	—	Water and debris observed at the rear of the property.	1	Ran 9 ft of electric cable through the lateral; further work is necessary.	Property is vacant; need housing authority to investigate.	1361451
15	7/25/2024	3800 N Charles St	21218	Structural	Wet	Stony Run	TBD	Subsurface sewage leak entering storm drain underground through pipe joint.	TBD*	Investigation concluded the pipe will need to be repaired or lined to stop SSO.	CCTV will determine the specificity of the work.	—
16	7/25/2024	1300 E Fayette St	21231	Rags, Trash	Wet	—	—	Gray water observed at the front of the property.	2	Relieved house connection choke with electric cable.	Flushed and cleaned the nearby mainline.	1361875
				# WWO	10			TOTAL	987*	UNDER 100 GALLONS	14	