

SSO Notification List												
July 2025												
Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/1/2025	4128 Westchester Rd	21216	Rags, Grease, Trash	Wet	Gwynns Falls	458	Wastewater overflowing from two manholes and entered storm drain inlet	2290	Flushed mainline sewer using pressure truck	CCTV Inspection will be performed	1455663
2	7/3/2025	142 W Lanvale St	21217	Roots	Wet	—	—	Wastewater with roots	2	Relieved house connection choke with 45 feet of electric machine cable	CCTV Inspection was performed	1456389
3	7/4/2025	2040 Linden Ave	21217	Rags, Grease	Wet	—	—	Observed wastewater at rear house connection	1	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1456406
4	7/4/2025	Lawina Rd & Westchester Rd	21216	Rags, Roots	Wet	—	1608	Observed wastewater coming from manhole	3216	Placed on Bypass Pumping to stop overflow	Pressure Truck utilized along with CCTV performed to determine further steps to be taken.	1456417
5	7/5/2025	2415 W Franklin St	21223	Rags	Dry	—	—	Wastewater with rags	2	Relieved choke using machine with sawtooth	CCTV Inspection was performed	1456457
6	7/6/2025	5600 Fair Oaks Ave	21214	Rags, Grease, Trash	Dry	—	—	Observed wastewater at front house connection	1	Relieved house connection choke with 60 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1456532
7	7/10/2025	Hilton Parkway & Edmondson Ave	21229	Structural	Wet	Gwynns Falls	16005	Broken sewer pipe leaking into adjacent waterway	400125	Repairs have been completed to stop the overflow	Abatement of the overflow confirmed by DPW Office Of Research and Environmental Protection (OREP)	1458183
8	7/10/2025	Lawina Rd & Westchester Rd	21216	Structural	Wet	Gwynns Falls	11604	Subsurface mainline choke causing sewer overflow infiltrating into nearby storm drain	58020	Repairs were completed to stop the overflow	Abatement confirmed by DPW Office Of Research and Environmental Protection (OREP)	1457751
9	7/12/2025	3501 Gelston Dr	21229	Trash, Sand, Gravel, Rocks	Wet	Gwynns Falls	3677	Observed wastewater coming from manhole	18385	Relieved mainline choke flushed and cleaned and vacuumed with 200 ft pressure hose	Confirmed mainline is clear and overflow stopped after removal of rocks and debris	1458118
10	7/12/2025	3400 Erdman Ave	21213	Rags, Trash	Wet	—	—	Wastewater with rags and debris	4	Relieved choke using 50' of pressure hose	CCTV Inspection will be performed	1458134
11	7/12/2025	2741 Tivoly Ave	21218	Rags, Trash	Wet	Jones Falls	273	Observed wastewater coming from manhole	136.5	Relieved mainline choke flushed and cleaned with 350 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1458160
12	7/13/2025	3502 Beech Ave & Stony Run Trail	21211	Rags, Trash, Sand, Gravel, Rocks	Dry	—	610	Observed wastewater coming from manhole	610	Relieved mainline flushed and cleaned with 400 ft pressure hose	Placed on Bypass Pumping to stop overflow.. Turned over for repairs	1458192
13	7/14/2025	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	20	Sewer overflow out of manhole structure	4000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
14	7/14/2025	3900 Belair Rd	21206	Rain	Wet	Herring Run	85	Manhole adjacent to creek overflowed due to heavy rain.	570010	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
15	7/14/2025	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	25	Sewer overflowed out of manhole structure	13000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
16	7/14/2025	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	65	Sewer overflowed out of manhole structure	5005	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
17	7/14/2025	929 N Wolfe St	21205	Rags, Trash	Wet	Northwest Harbor	—	Observed wastewater coming from manhole	3	Relieved mainline choke, flushed and cleaned with 250 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1458518
18	7/15/2025	413 S Vincent St	21223	Rags	Wet	—	—	Observed wastewater coming from rear house connection	1	Relieved house connection choke with 15 ft electric cable machine	Confirmed house connection is clear at this time. CCTV was performed	1458722
19	7/15/2025	2345 Washington Blvd	21230	Rags, Trash	Wet	—	301	Observed wastewater coming from manhole	903	Relieved mainline choke with 200 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1458914
20	7/16/2025	1734 Poplar Grove St	21216	Rags, Grease, Trash	Wet	—	—	Observed wastewater coming from manhole	1	Relieved mainline choke, flushed and cleaned with 300 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV inspection	1459263

SSO Notification List												
July 2025												
21	7/18/2025	2260 Cecil Ave	21218	Rags, Roots	Wet	—	290	Observed wastewater coming from rear house connection	290	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1459955
22	7/18/2025	1700 E Cold Spring Ln	21251	Rags, Trash	Wet	—	—	Wastewater with rags and debris	50	Relieved choke using pressure hose	CCTV Inspection will be performed	1459996
23	7/19/2025	1031 W 36th St	21211	Rags	Wet	—	—	Observed wastewater coming from rear house connection	2	Relieved house connection choke with 30 ft electric machine cable	Confirmed house connection is clear at this time. CCTV was performed	1460173
24	7/20/2025	908 Chestnut Hill Ave	21218	Roots	Dry	—	—	Wastewater with tree roots	1	Relieved choke using electric machine	CCTV Inspection was performed	1460254
25	7/24/2025	2831 Parkwood Ave	21217	Other	Dry	—	—	Evidence of overflow at rear house connection	1	CCTV inspection was performed	CCTV confirmed house connection is clear at this time.	1461787
26	7/27/2025	6001 Pimlico Rd	21209	Rags	Dry	—	—	Wastewater with rags	0.5	Relieved choke using electric cable with expander cutter	CCTV Inspection will be performed	1462602
27	7/28/2025	1031 W 36th St	21211	Rags, Grease	Wet	—	—	Observed wastewater coming from rear house connection	2	Relieved house connection choke with 15 ft electric machine cable	Confirmed connection is clear at this time. CCTV was performed	1463009
28	7/31/2025	200 Penn St	21201	Rags, Grease, Trash	Dry	—	—	Observed wastewater debris at manhole	1	Relieved mainline choke flushed and cleaned with 200 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1464289
29	7/31/2025	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	15	Structure discharges to an outfall pipe and is monitored by metering equipment in the pipe.	2010	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
30	7/31/2025	3900 Belair Rd	21206	Rain	Wet	Herring Run	105	Manhole adjacent to creek overflowed due to heavy rain.	677040	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
31	7/31/2025	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	65	Structure discharges to an outfall pipe and is monitored by metering equipment in the pipe.	5005	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
				# WWO	24			TOTAL	1,760,118	UNDER 100 GALLONS	15	