

SSO Notification List

June 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/3/2019	1215 Cooksie St	21230	Rags	Dry	N/A	0	Gray water observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	
2	6/4/2019	W Northern Pkwy & Cylburn Ave	21209	Structural	Dry	Jones Falls	1,695	Sewage escaping mainline and entering storm drain.	11,144	Set up bypass pumping to abate the overflow.	Pipe will eventually be repaired to return to normal functionality.	
3	6/4/2019	3700 Gough St	21224	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout.	7	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection.	
4	6/7/2019	131 W Lanvale St	21217	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	
5	6/9/2019	3016 Parkside Dr	21214	Roots	Dry	N/A	0	Gray water and paper observed around the cleanout.	3	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	
6	6/12/2019	2432 Fait Ave	21224	Roots, Grease, Trash	Wet	Harbor	0	Gray water observed around the cleanout.	20	Relieved choke with electric cable.	Performed CCTV inspection.	
7	6/15/2019	1631 Gwynns Falls Pkwy	21216	Roots, Trash	Wet	N/A	0	Cloudy water and debris observed around the cleanout.	3	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	
8	6/19/2019	1439 Haubert St	21230	Unknown	Wet	N/A	0	Gray water observed around the sump pump.	4	Transferred responsibility to the Health Department.	Health Department will determine appropriate action.	
9	6/21/2019	1248 N Gay St	21213	Rags, Grease	Wet	N/A	0	Gray water observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	
10	6/24/2019	2513 Edmondson Ave	21223	Rags, Trash	Dry	N/A	0	Gray water observed on the property.	3	Left notice to have plumber remove older-style trap.	Plumber's actions should resolve the issue.	
11	6/24/2019	2611 Manhattan Ave	21215	Rags, Roots	Dry	N/A	0	Gray water and debris observed around the cleanout.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	
12	6/26/2019	E Cold Spring Ln & York Rd	21212	Trash, Structural	Wet	Jones Falls	125	Sewage escaping the mainline and entering a storm drain.	625	Flushed the mainline with pressure hose.	Performed CCTV inspection to determine potential structural damage.	
13	6/27/2019	2021 S Clinton St	21224	Trash, Other	Wet	N/A	0	Gray water observed that escaped from pumping station.	190	Pump was replaced in order to return to regular operations.	Confirmed restoration of pump station capabilities.	
14	6/28/2019	2217 Cross Country Blvd	21209	Rags, Trash	Wet	N/A	0	Cloudy water and debris observed around the cleanout.	3	Relieved house connection choke with 65 ft of electric cable.	CCTV inspection will be performed.	
15	6/28/2019	3500 Beech Ave	21211	Rags, Grease	Wet	N/A	0	Gray water and grease observed around the manhole.	6	Relieved mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	

SSO Notification List

June 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
16	6/29/2019	3902 Maine Ave	21207	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout.	4	Relieved house connection choke with 15 ft of electric cable.	A CCTV inspection will be performed.	
17	6/28/2019	1905 E 31st St	21218	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with electric cable.	Performed lateral CCTV inspection.	
18	6/30/2019	2000 Mount Royal Ter	21211	Rags, Grease	Dry	Jones Falls	0	Heavy gray water observed around the manhole.	20	Relieved mainline choke with 100 ft of pressure hose.	A mainline CCTV inspection will be performed.	736509
				# WWO	9			TOTAL	12,052	UNDER 100 GALLONS	15	