

SSO Notification List

June 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/2/2021	1120 Gorsuch Ave	21218	Structural	Dry	N/A	0	Gray water observed at the front of the property.	1	Ran 7 ft of electric cable through the lateral; determined structural damage exists.	Line will be repaired to restore house connection to regular functionality.	936397
2	6/3/2021	306 S Catherine St	21223	Rags, Grease, Trash, Sand, Gravel, Rocks	Dry	Gwynns Falls	83	Heavy gray water escaping the manhole in the street.	415	Relieved mainline choke with 350 ft of pressure hose.	Performed CCTV inspection; cleaned the manhole.	936590
3	6/4/2021	785 Yale Ave	21229	Rags, Roots, Grease, Trash	Wet	Gwynns Falls	325	Gray water escaping the manhole in the rear alley.	975	Relieved 10" mainline choke with 250 ft of pressure hose.	Confirmed mainline is now flowing freely; CCTV inspection will be performed.	936785
4	6/5/2021	212 Northway	21218	Roots	Wet	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and determined the lateral and mainline are clear.	936993
5	6/7/2021	3618 Gibbons Ave	21214	Rags, Roots	Wet	N/A	0	Gray water and debris observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and determined the lateral is clear at this time.	937253
6	6/9/2021	3205 Overland Ave	21214	Rags, Trash	Wet	Herring Run	119	Sewer overflowing into adjacent storm drain.	595	Relieved mainline choke with 285 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	937724
7	6/10/2021	Benson Ave & Joh Ave	21227	Rags, Trash	Wet	Gwynns Falls	74	Gray water escaping the manhole in the street.	740	Used 75 ft of pressure hose to relieve mainline choke in two sections.	CCTV inspection will be performed to determine if further action is needed.	937861
8	6/10/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	70	Structure monitored by metering equipment in the pipe. Not visually observed.	213,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
9	6/10/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	285	Structure monitored by metering equipment in the pipe. Not visually observed.	12,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
10	6/10/2021	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	220	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe.	117,000	SSO structure discharges to an outfall pipe; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
11	6/10/2021	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	60	Structure monitored by metering equipment in pipe.	39,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital projects.	
12	6/10/2021	3900 Belair Rd	21206	Rain	Wet	Herring Run	45	Manhole adjacent to creek overflowed due to heavy rain.	402,000	Overflow subsided following heavy rain event.	Overflow will be prevented after completion of capital improvement projects.	
13	6/10/2021	N Charles St & Lafayette Ave - SSO Site #154	21202	Rain	Wet	Jones Falls	195	Structure monitored by metering equipment in the pipe. Not visually observed.	164,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital project.	
14	6/11/2021	W Cold Spring Ln & Towanda Ave	21215	Rain, Grease	Wet	Gwynns Falls	175	Manhole surcharging in the street due to heavy rain event.	87,500	Flow returned to normal at the conclusion of the heavy rain event. Flushed mainline.	CCTV inspection will be performed to determine if further action is needed.	938145
15	6/11/2021	4111 Menlo Dr	21215	Rags, Rain, Grease, Trash	Wet	Gwynns Falls	207	Gray water surcharging from the manhole.	1,035	Overflow subsided following rain event. Flushed 8" mainline.	CCTV inspection will be performed to ensure all obstructions were removed.	938200
16	6/11/2021	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	80	Heavy gray water escaping the manhole.	41,000	Overflow subsided following heavy rain event.	Capital improvement projects are being implemented to prevent this overflow from reoccurring.	
17	6/11/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	440	Structure monitored by metering equipment in the pipe. Not visually observed.	1,658,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
18	6/11/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	525	Structure monitored by metering equipment in the pipe. Not visually observed.	5,112,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
19	6/11/2021	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	190	Structure discharges to an outfall pipe and is monitored by metering equipment in the pipe.	10,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
20	6/11/2021	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	65	Structure monitored by metering equipment in pipe.	3,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital projects.	
21	6/11/2021	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	200	Structure monitored by metering equipment in the pipe.	17,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
22	6/13/2021	605 S Paca St	21230	Roots, Grease, Trash	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral is now clear.	938300

SSO Notification List

June 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
23	6/13/2021	1120 Gorsuch Ave	21218	Roots, Grease, Trash	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 40 ft of electric cable.	Performed CCTV inspection and determined the lateral is clear at this time.	938338
24	6/15/2021	500 S Monroe St	21223	Rags, Grease, Trash	Wet	Gwynns Falls	320	Gray water escaping the manhole in the street.	1,600	Used pressure truck to relieve mainline choke.	CCTV inspection will be performed to determine if further action is needed.	938688
25	6/15/2021	3529 Gelston Dr	21229	Rags, Roots, Grease, Trash	Wet	Gwynns Falls	983	Gray water escaping the manhole.	983	Relieved mainline choke with 285 ft of pressure hose.	CCTV inspection will be performed to confirm all obstructions were removed from pipe.	938853
26	6/16/2021	5621 Belair Rd	21206	Rags, Grease	Wet	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	938984
27	6/16/2021	2418 Loyola Northway	21215	Rags, Roots, Trash	Wet	Jones Falls	115	Heavy gray water escaping the manhole.	1,150	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear at this time; CCTV inspection will be performed.	939008
28	6/19/2021	3303 Abell Ave	21218	Roots	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 35 ft of electric cable.	Location will be placed on routine cleaning due to intrusive large tree.	955362
29	6/21/2021	3128 Oakfield Ave	21216	Rags, Roots, Trash	Dry	Gwynns Falls	96	Heavy gray water escaping the manhole and entering nearby storm drain.	1,920	Relieved mainline choke with 150 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed.	955472
30	6/21/2021	306 Northfield Pl	21210	Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 90 ft of electric cable.	Performed CCTV inspection and results showed the lateral and mainline to be clear.	955651
31	6/23/2021	411 E Patapsco Ave	21225	Rags, Grease	Wet	N/A	0	Gray water observed around the manhole at the rear of the property.	3	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the mainline is now flowing freely; CCTV inspection will be performed.	955968
32	6/25/2021	2319 E Fairmount Ave	21224	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	956413
33	6/26/2021	2831 Waldorf Ave	21215	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the front cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	956619
34	6/26/2021	5616 Frankford Ave	21206	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection and results showed the line is clear.	956624
35	6/27/2021	1412 N Luzerne Ave	21213	Rags	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	956674
36	6/27/2021	2700 Cheswolde Rd	21209	Rags, Structural	Dry	N/A	0	Heavy gray water observed around the cleanout.	2	Relieved mainline and house connection chokes with 25 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	956726
37	6/28/2021	4110 Duane Ave	21225	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed to determine if further action is needed.	956761
38	6/29/2021	2700 Cheswolde Rd	21209	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the side of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed to confirm lateral is clear.	957389
				# WWO	27			TOTAL	7,884,941	UNDER 100 GALLONS	16	