

## SSO Notification List

June 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/1/2023	120 N Fremont Ave	21201	Rags, Grease	Dry	N/A	—	Gray water observed at the front of the property and storm drain.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed both lateral and mainline are clear at this time.	1228002
2	6/5/2023	5613 Force Rd	21206	Rags, Trash	Dry	N/A	—	Mainline choke causing house connection to overflow.	2	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the line is clear at this time; CCTV will be performed.	1228735
3	6/6/2023	5110 Frederick Ave	21229	Rags, Roots, Grease, Trash	Dry	Maidens Choice	361	Sewage escaping the manhole cover near the woods.	1805	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1229488
4	6/8/2023	1710 St Paul St	21202	Roots, Trash	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is clear.	1230275
5	6/12/2023	436 Kane St	21224	Sand, Gravel, Rocks	Dry	N/A	72	Gray water escaping the manhole.	36	Relieved mainline choke with 80 ft of pressure hose.	Confirmed the line is clear at this time.	1230793
6	6/13/2023	2607 Quantico Ave	21215	Rags, Roots	Wet	N/A	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV will be performed; flushed and cleaned the mainline.	1231412
7	6/18/2023	1713 Lancaster St	21231	Roots	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	CCTV confirmed the lateral and mainline are now clear.	1232323
8	6/18/2023	2736 E Baltimore St	21224	Rags, Grease	Dry	N/A	—	Gray water observed at the rear of the property.	1	Relieved choke with 150 ft of pressure hose.	Confirmed the line is now clear.	1232332
9	6/27/2023	862 Vine St	21201	Rags, Grease	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the line is now clear.	1238146
10	6/27/2023	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	25	Structure monitored by metered equipment in the pipe. Not visually observed.	500	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
11	6/27/2023	N Charles St & Lafayette Ave - SSO Site #154	21201	Rain	Wet	Jones Falls	25	Structure monitored by metering equipment in the pipe. Not visually observed.	5000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
12	6/30/2023	5950 Glen Falls Ave	21206	Rags, Roots	Wet	N/A	—	Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Location will be placed on routine cleaning to address roots found in lateral.	1239320
				# WWO	5			TOTAL	7,352	UNDER 100 GALLONS	9	