

SSO Notification List

March 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/1/2020	1200 N Franklinton Rd	21216	Rags, Grease, Trash	Wet	Gwynns Falls	41	Gray water escaping stacked manhole.	82	Relieved mainline choke with 25 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	849406
2	3/2/2020	5001 Frederick Ave	21229	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the mainline.	849790
3	3/2/2020	5621 Belair Rd	21206	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	9	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	849495
4	3/2/2020	2381 Flax Terr	21209	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	7	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	849604
5	3/3/2020	2622 Huron St	21230	Rags, Roots, Trash	Wet	Gwynns Falls	0	Heavy gray water and debris observed at the rear of the property.	2	Relieved 8" mainline choke with 100 ft of pressure hose.	Confirmed lines are clear; CCTV inspection will be performed.	849885
6	3/4/2020	4816 Richard Ave	21214	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	850664
7	3/4/2020	1501 E Madison St	21205	Structural	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Ongoing structural issue for this location. Long-term solution is being investigated.	Pumped the lateral to prevent immediate recurrence.	829816
8	3/4/2020	5108 Midwood Ave	21212	Trash, Structural	Wet	Herring Run	636	Gray water escaping the cleanout at the front of the property.	636	Ran 45 ft of electric cable to stop the overflow. Pipe will need to be repaired.	Pumped the lateral to give relief and prevent immediate recurrence.	851032
9	3/4/2020	1204 Cochran Ave	21239	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	850932
10	3/5/2020	5200 Beaufort Ave	21215	Rags, Roots, Trash	Wet	N/A	135	Gray water escaping the cleanout at the rear of the property.	68	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	851222
11	3/6/2020	1907 Brunt St	21217	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	5	Ran 32 ft of electric cable through the house connection. Lateral launch will be performed.	Performed CCTV inspection; flushed and cleaned 8" mainline.	851647
12	3/7/2020	4315 Lasalle Ave	21206	Rags, Roots, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	4	Relieved house connection choke with 100 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	851835
13	3/7/2020	4029 N Rogers Ave	21207	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the side of the property.	2	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed.	851856
14	3/7/2020	809 W Cross St	21230	Roots, Trash	Wet	Inner Harbor	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	851846
15	3/7/2020	4600 Briarcliff Rd	21229	Roots, Trash, Unknown	Wet	N/A	114	Water escaping the manhole and entering nearby stream.	570	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	851870
16	3/8/2020	1600 W 41st St	21211	Trash, Sand, Gravel, Rocks	Wet	Jones Falls	131	Heavy gray water escaping the manhole.	3,275	Relieved 8" mainline choke with 150 ft of pressure hose.	Confirmed mainline and manhole are clear.	851894
17	3/8/2020	102 Park Ln	21210	Rags, Trash	Wet	N/A	320	Gray water escaping the manhole in the street.	160	Relieved 8" mainline choke with 250 ft of pressure hose.	Confirmed mainline is clear.	851902
18	3/8/2020	810 N Hilton St	21229	Rags, Roots, Trash	Wet	Gwynns Falls	210	Gray water escaping the manhole and entering a nearby storm drain.	1,050	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	851917
19	3/9/2020	1514 Lester Morton Ct	21205	Trash, Structural	Wet	Inner Harbor	0	Gray water and paper discharged when engaging pump.	5	Ongoing structural issue for this location. Long-term solution is being investigated.	The lateral is being routinely pumped down to help prevent recurrence.	852111
20	3/9/2020	929 Montpelier St	21218	Roots	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Ran 90 ft of electric cable; roots remained in the house connection.	CCTV inspection, lateral launch, and bypass pumping will be implemented.	852129
21	3/9/2020	1248 N Gay St	21213	Rags, Trash	Wet	N/A	0	Gray water observed at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral choke was relieved; CCTV inspection will be performed.	852146

SSO Notification List

March 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	3/9/2020	3202 Bonnie Rd	21208	Rags, Roots, Trash	Dry	N/A	55	Sewage overflowing into adjacent storm drain.	275	Relieved 8" mainline choke with 250 ft of pressure hose.	Confirmed mainline is clear.	852173
23	3/9/2020	3701 Mactavish Ave	21229	Rags, Roots, Trash	Wet	Gwynns Falls	157	Gray water escaping the manhole and entering nearby storm drain.	471	Relieved 8" mainline choke with 25 ft of pressure hose.	Confirmed mainline is clear.	852038
24	3/10/2020	804 N Fulton Ave	21217	Rags, Grease	Dry	N/A	0	Gray water observed at the rear of the property.	4	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	852346
25	3/10/2020	4702 Wakefield Rd - Private	21207	Roots	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	852496
26	3/10/2020	4031 Fairview Ave	21216	Rags, Grease, Trash	Dry	Gwynns Falls	185	Choked sanitary sewer causing subsurface discharge into storm drain.	3,700	Relieved mainline choke with 125 ft of pressure hose.	Confirmed mainline is clear.	852488
27	3/11/2020	2325 Hollins St	21223	Rags	Dry	Gwynns Falls	53	Gray water escaping cleanout at the rear of the property.	106	Relieved 6" choke with sawtooth and 75 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	852843
28	3/11/2020	2211 Roslyn Ave	21216	Rags, Roots, Trash	Dry	N/A	0	Heavy gray water observed at the rear of the property.	40	Relieved choke with 125 ft of pressure hose.	Confirmed line is clear.	852920
29	3/11/2020	3309 Saint Ambrose Ave	21215	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	853004
30	3/11/2020	336 E Belvedere Ave	21212	Rags	Dry	N/A	0	Gray water observed at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	852789
31	3/11/2020	2501 Frederick Ave	21223	Rags, Trash	Dry	N/A	50	Gray water escaping from manhole.	100	Relieved mainline choke with 50 ft of pressure hose.	Confirmed line is clear.	852928
32	3/12/2020	4403 Liberty Heights Ave	21207	Roots	Dry	N/A	140	Gray water escaping the cleanout at the rear of the property.	70	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	853204
33	3/13/2020	1806 N Longwood St	21216	Rags, Grease	Wet	N/A	0	Gray water observed around the cleanout at the side of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	853801
34	3/14/2020	301 Edgevale Rd	21210	Rags, Roots	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	2	Relieved house connection choke with 15 ft electric cable.	Confirmed lateral is clear; mainline will be cleaned.	853899
35	3/15/2020	1518 Lester Morton Ct	21205	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout.	8	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	853988
36	3/16/2020	4818 Richard Ave	21214	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	6	Relieved house connection choke with 30 ft of electric cable and expander cutters.	Confirmed lateral and mainline are clear.	854039
37	3/16/2020	3309 Saint Ambrose Ave	21215	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	7	Relieved house connection choke with 9 ft of electric cable.	CCTV inspection will be performed. Left notice to have plumber inspect consumer's side.	854115
38	3/16/2020	2112 W North Ave	21217	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the manhole at the rear of the property.	4	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear.	854182
39	3/17/2020	1010 Myrtle Ave	21201	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	854608
40	3/18/2020	6501 Colgate Rd	21222	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; mainline will be cleaned.	854983
41	3/19/2020	1003 Woodson Rd	21212	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	855261
42	3/20/2020	3000 Chestnut Ave	21211	Rags, Roots, Trash	Wet	Jones Falls	144	Gray water escaping the manhole.	432	Relieved mainline choke with 150 feet of pressure hose.	Confirmed mainline is clear.	855357

SSO Notification List

March 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
43	3/20/2020	4029 N Rogers Ave	21207	Rags, Roots, Grease	Wet	N/A	0	Gray water observed around the cleanout at the side of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	855447
44	3/20/2020	3164 Lyndale Ave	21213	Grease, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Flushed and cleaned the mainline with 300 ft of pressure hose.	Confirmed line is clear.	855561
45	3/23/2020	2803 Elgin Ave	21216	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the side of the property.	8	Relieved house connection choke with 200 ft of pressure hose.	Performed CCTV inspection; confirmed lateral and mainline are clear.	855743
46	3/23/2020	2853 W North Ave	21216	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	3	Ran 30 ft of electric cable. Left notice to contact private plumber for consumer-side issue.	Confirmed City mainline and lateral are clear.	855992
47	3/24/2020	1250 N Gay St	21213	Rags, Trash	Wet	N/A	0	Gray water observed at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	855887
48	3/25/2020	1214 Homewood Ave	21202	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 15 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	856031
49	3/25/2020	2601 Springhill Ave	21215	Rags, Grease, Trash	Wet	N/A	944	Gray water observed in the rear alley.	236	Flushed and cleaned 8" mainline with 250 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	856142
50	3/26/2020	880 Park Ave	21201	Rags	Wet	N/A	85	Water escaping the cleanout at the front of the location.	17	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	856201
51	3/26/2020	2634 Miles Ave	21211	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Flushed the mainline. Alerted the consumer to have cap removed on cleanout.	Confirmed the mainline is clear. Remaining in contact with consumer.	856258
52	3/26/2020	810 N Hilton St	21229	Rags, Trash	Wet	Gwynns Falls	270	Gray water escaping the manhole at the rear of the property.	540	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear.	856298
53	3/26/2020	3013 Westfield Ave	21214	Rags, Grease, Trash, Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the manhole at the rear of the property.	15	Relieved mainline choke with 450 ft of pressure hose.	Confirmed line is clear.	856321
54	3/26/2020	2431 Arunah Ave	21216	Grease, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	2	Referred location to Housing Authority; issue is stemming from consumer's side.	Flushed and cleaned with mainline with 250 ft of pressure hose.	856289
55	3/26/2020	1419 Hollins St	21223	Roots	Wet	N/A	0	Gray water observed around the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	856283
56	3/27/2020	1701 Appleton St	21217	Rags, Grease, Trash	Wet	N/A	0	Gray water observed at the side of the property.	3	Relieved choke with 150 ft of pressure hose.	Performed CCTV inspection; consumer will have cleanout installed.	856443
57	3/30/2020	15 Edgevale Rd	21210	Rags, Roots, Other	Wet	Jones Falls	316	Gray water escaping the manhole in the street.	3,160	Relieved 8" mainline choke with pressure hose, rod, and hook.	Confirmed mainline is clear; CCTV inspection will be performed.	856614
58	3/30/2020	1326 N Broadway	21213	Rags, Grease, Trash	Wet	Inner Harbor	485	Gray water discharging from manhole.	1,455	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	856715
59	3/31/2020	2501 Maryland Ave	21218	Rags, Trash	Wet	N/A	0	Gray water escaping the lateral at the rear of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	856857
60	3/31/2020	3722 E Northern Pkwy	21206	Rags, Grease, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	856862
61	3/31/2020	1148 Steelton Ave - Private	21224	Rags, Trash	Wet	N/A	241	Gray water discharging from manhole.	2,410	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Confirmed mainline is clear.	856813
62	3/31/2020	616 Woodbourne Ave	21212	Rags, Roots, Trash	Wet	N/A	0	Gray water and paper observed at the front of the property.	5	Ran 45 ft of electric cable to remove blockage.	CCTV inspection will be performed to determine potential structural damage.	856756
				# WWO	47			TOTAL	16,603	UNDER 100 GALLONS	45	