SSO Notification List

March 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet- Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/1/2022	3529 Gelston Dr	21229	Rags, Roots, Grease	Dry	Gwynns Falls	335	Gray water escaping the manhole in the street.	3,350	Relieved mainline choke with 400 ft of pressure hose.	Mainline CCTV inspection will be performed.	1022277
2	3/1/2022	6107 Eastern Pkwy	21206	Rags, Infiltration, Trash	Dry	Moores Run	1660	Choked sanitary sewer overflowing into the adjacent storm pipe.	4,980	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	1022374
3	3/1/2022	2805 Bookert Dr	21225	Rags	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear at this time.	1022520
4	3/1/2022	3305 Burleith Ave	21215	Unknown	Dry	N/A		Gray water observed around the cleanout.	1	Ran 45 ft of electric cable through the lateral.	Advised consumer to have plumber inspect their side of the pipe.	1022530
5	3/2/2022	1308 W Lexington St	21223	Roots	Dry	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed; flushed and cleaned the mainline.	1022599
6	3/2/2022	100 Kane St	21224	Rags, Trash	Dry	N/A		Gray water observed around the manhole.	2	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is clear at this time.	1022668
7	3/3/2022	910 N Dukeland St	21216	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection was performed and showed the lateral to be clear.	1022862
8	3/3/2022	1602 N Milton Ave	21213	Rags, Trash	Dry	N/A		Gray water observed at the rear of the property.	2	Relieved mainline choke with 60 ft of pressure hose.	Confirmed the mainline is clear at this time.	1022901
9	3/3/2022	5916 York Rd	21212	Rags, Trash	Dry	Chinquapin Run	2912	Routine sampling discovered overflow into nearby storm drain.	58,240	Partially relieved choke with 200 ft of pressure hose.	Further investigation will take place at this location.	1023011
10	3/4/2022	4410 Frankford Ave	21206	Rags, Trash	Dry	N/A	101	Sewage escaping manhole and overflowing into nearby storm drain.	505	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to determine if further action is needed.	1023274
11	3/4/2022	251 S Morley St	21229	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are now clear.	1023276
12	3/4/2022	4720 York Rd	21212	Rags, Grease, Infiltration, Trash	Dry	Tiffany Run	1640	Routine sampling discovered wastewater infiltrating the storm drain.	328	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	1023291
13	3/4/2022	5916 York Rd	21212	Grease, Infiltration	Dry	Chinquapin Run	354	Mainline choke causing wastewater to infiltrate the storm drain.	7,080	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear at this time; CCTV will be performed.	1023316
14	3/6/2022	2 N Wheeler Ave	21223	Rags, Grease	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection and mainline chokes with pressure hose.	Confirmed lines are clear; CCTV will be performed.	1023453
15	3/7/2022	2121 E Chase St	21213	Sand, Gravel, Rocks	Dry	N/A		Gray water observed around the cleanout.	1	Ran 15 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will be performed.	1023552
16	3/7/2022	4222 Audrey Ave	21225	Rags, Roots	Dry	N/A		Gray water observed around the cleanout and sidewalk.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lines are clear; advised consumer to have lateral internally inspected.	1023603
17	3/7/2022	6212 Laurelton Ave	21214	Rags, Grease	Dry	Herring Run	82	Overflowing house connection cleanout flowing into storm inlet.	246	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	1023652
18	3/7/2022	1622 Moreland Ave	21216	Rags, Trash	Dry	N/A		Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are now clear.	1023682
19	3/8/2022	4720 York Rd	21212	Grease, Infiltration	Dry	Tiffany Run	238	Choked sanitary mainline causing subsurface infiltration into storm drain.	48	Relieved mainline choke with pressure hose.	CCTV inspection will be performed.	1023844
20	3/8/2022	534 N Payson St	21223	Rags, Sand, Gravel, Rocks	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection will be performed.	1023950

	SSO Notification List											
March 2022												
21	3/8/2022	147 N Streeper St	21224	Rags, Sand, Gravel, Rocks, Structural	Dry	N/A		Gray water observed around the cleanout.	1	Partially relieved house connection choke with 12 ft of electric cable.	Further investigation will take place to determine if repair is needed.	1024024
22	3/11/2022	251 N Monroe St	21223	Rags, Trash	Wet	N/A		Gray water observed around the cleanout.	1	Relieved choke with pressure hose.	Confirmed line is clear.	0
23	3/13/2022	2 N Wheeler Ave	21223	Rags, Grease, Unknown	Wet	N/A		Gray water observed around the cleanout.	1	Partially relieved house connection choke with 25 ft of electric cable.	CCTV inspection will determine if further action is needed.	1025060
24	3/14/2022	1939 E Lafayette Ave	21213	Rags, Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with electric cable.	Lateral CCTV inspection will be performed; cleaned the mainline.	1025172
25	3/15/2022	1105 N Wheeler Ave	21216	Rags, Trash	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	1026624
26	3/15/2022	4309 Frankford Ave	21206	Rags, Trash	Dry	N/A	322	Mainline choke overflowing into storm drain and waterway.	1,610	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear.	1026667
27	3/16/2022	W Cold Spring Ln & Keswick Rd	21210	Rags, Grease	Dry	N/A	199	Gray water escaping the manhole.	199	Relieved mainline choke with 275 ft of electric cable.	Performed mainline CCTV inspection and results showed the line is clear.	1026814
28	3/16/2022	3100 Batavia Ave	21214	Grease, Infiltration	Dry	Herring Run	92	Choked sanitary sewer overflowing into adjacent storm drain pipe.	460	Relieved mainline choke with 280 ft of pressure hose.	Confirmed the line is clear; CCTV will be performed.	1026939
29	3/16/2022	4705 Keswick Rd	21210	Rags, Rain	Dry	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with pressure hose and electric cable.	Confirmed the lateral and mainline are now clear.	1027042
30	3/17/2022	1720 N Register St	21213	Rags, Grease, Trash, Structural	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved choke with electric cable; structural damage is present.	CCTV inspection will be performed to determine future steps.	1027216
31	3/21/2022	1267 Riverside Ave	21230	Trash	Dry	N/A		Gray water observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; flushed and cleaned the mainline.	1027752

32

33

34

35

36

37

38

39

40

41

3/21/2022

3/22/2022

3/22/2022

3/23/2022

3/23/2022

3/23/2022

3/27/2022

3/28/2022

3/28/2022

3/29/2022

633 Gorsuch Ave

1412 N Luzerne Ave

301 Edgevale Rd

Woodlea Ave & Belair Rd

15 Edgevale Rd

323 1/2 S Collins Ave

S Filwood Ave & Boston St

430 E Lanvale St

5709 Chinquapin Pkwy

1412 N Luzerne Ave

21218

21213

21210

21206

21210

21229

21224

21202

21202

Roots

Trash

Roots

Structural

Rags, Roots, Trash

Roots

Rags, Grease

Rags, Roots

Rags, Trash

Rags, Grease

Dry

N/A

N/A

N/A

Biddison Run

Jones Falls

N/A

N/A

N/A

N/A

N/A

9070

1331

Gray water observed around the

cleanout.

Gray water observed at the front

of the property.

Gray water observed around the

cleanout.

Broken sewer pipe leaking into

the adjacent storm drain.

Gray water escaping the

manhole and reaching

waterway.

Gray water observed around the

cleanout.

Gray water observed around the

manhole.

Gray water observed around the

cleanout at the rear of the

property.

Gray water observed around the

cleanout.

Gray water observed around the

cleanout.

1

1,197

1,331

1

2

1

1

Lateral CCTV inspection will

determine if further action is

needed.

CCTV inspection showed the lateral

and mainline are now clear.

CCTV inspection confirmed the

lateral is now clear.

Abatement confirmed via dye

testing.

Confirmed the mainline is clear;

CCTV inspection will be performed

CCTV inspection showed the line is

now clear.

Confirmed the line is clear; CCTV

inspection will be performed.

Lateral CCTV inspection showed

the line is now clear.

CCTV inspection confirmed the

lateral is clear.

CCTV inspection confirmed the

lateral is now clear.

1028065

1028120

1028490

1028764

1028732

1028694

1030093

1030284

1030329

1030513

Relieved house connection choke

with 30 ft of electric cable.

Relieved house connection choke

with 60 ft of electric cable.

Relieved house connection choke

with 35 ft of electric cable.

Mainline was repaired to restore

system to regular functionality.

Relieved mainline choke with 200

ft of pressure hose.

Relieved house connection choke

Relieved mainline choke with 100

ft of pressure hose.

Relieved house connection choke

with 45 ft of electric cable.

Relieved house connection choke

with 30 ft of electric cable.

Relieved house connection choke

with 30 ft of electric cable.

with 60 ft of electric cable.

	SSO Notification List											
March 2022												
42	3/29/2022	532 Winston Ave	21212	Rags, Grease	Dry	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection confirmed the lateral is now clear.	1030645
43	3/30/2022	810 N Hilton St	21229	Rags, Roots, Grease, Trash	Dry	Gwynns Falls	384	Gray water escaping the manhole and reaching storm drain.	5,760	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is now clear; CCTV inspection will be performed.	1030888
44	3/30/2022	12 Beechdale Rd	21210	Roots, Trash	Dry	Jones Falls	350	Sewage overflowing from manhole into adjacent storm pipe.	8,750	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now flowing freely.	1031007
45	3/30/2022	4507 Wakefield Rd	21216	Grease, Structural, Unknown	Dry	N/A	10110	Overflowing cleanout due to choked pipes. Saturating the ground; not reaching waterway.	10,110	Contractor successfully installed a bypass pump to stop the SSO from occurring.	Two pipe segments will be replaced in order to correct persistent issues.	1031237
				# WWO	3			TOTAL	104,230	UNDER 100 GALLONS	30	