

SSO Notification List

March 2023

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/2/2023	5950 Glen Falls Ave	21206	Rags, Trash	Wet	N/A		Mainline choke causing cleanout to overflow.	2	Used high-pressure jet truck to relieve mainline choke.	CCTV inspection will determine what further steps need to be taken.	1201487
2	3/2/2023	3419 Elmley Ave	21213	Rags, Grease	Wet	N/A		Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1201620
3	3/3/2023	6202 Wirt Ave	21215	Rags, Grease, Trash	Dry	Western Run	190	Gray water escaping the manhole.	380	Relieved 6" mainline choke with 450 ft of pressure hose.	Confirmed line is now clear. Location will be routinely maintained.	1201800
4	3/3/2023	3900 Belair Rd	21206	Rain	Wet	Herring Run	60	Manhole adjacent to creek overflowed due to heavy rain.	170040	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	0
5	3/5/2023	1820 Spence St	21230	Rags, Roots, Grease	Wet	N/A		Heavy gray water observed around the manhole.	10	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	1202224
6	3/5/2023	3404 The Alameda	21218	Rags, Grease	Wet	Tiffany Run	71	Gray water escaping the manhole in the street and reaching storm drain.	213	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to determine further steps.	1202260
7	3/6/2023	131 S Loudon Ave	21229	Rags, Grease	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed both the lateral and mainline are clear.	1202394
8	3/6/2023	520 Loudon Ave	21229	Rags, Grease, Trash	Wet	Gwynns Falls	129	Gray water escaping the manhole and reaching storm drain.	387	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the mainline is now clear; CCTV inspection will be performed.	1202474
9	3/6/2023	5615 York Rd	21212	Rags, Roots, Grease	Wet	N/A		Gray water observed around the cleanout.	7	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1202468
10	3/6/2023	1901 Chesapeake Ave	21226	Rags, Trash	Wet	N/A		Sewage and rags observed around the cleanout.	2	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection.	1202553
11	3/6/2023	410 Hollen Rd	21212	Rags, Grease, Trash	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed to determine if future work is needed.	1202626
12	3/9/2023	3011 W Belvedere Ave	21215	Rags, Trash	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection, which confirmed the lateral is clear.	1204866
13	3/9/2023	2212 Lyndhurst Ave	21216	Rags, Roots, Grease	Dry	N/A		Gray water observed around the manhole cover.	5	Flushed and cleaned 8" mainline; ran 20 ft of electric cable through lateral.	Confirmed line is now clear and flowing freely.	1204945
14	3/12/2023	3408 Keene Ave	21214	Rags	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	1205305
15	3/13/2023	1204 Carroll St	21230	Rags, Grease	Wet	Gwynns Falls		Gray water observed at the rear alley and storm drain inlet.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed the lateral is now clear.	1205493
16	3/14/2023	1201 Cooksie St	21230	Rags, Roots, Grease	Dry	Northwest Harbor	123	Choked sanitary sewer overflowing into an adjacent storm drain.	369	Used high-pressure jet truck to relieve 8" mainline choke.	CCTV inspection will determine what further steps need to be taken.	1205736
17	3/14/2023	2403 Callow Ave	21217	Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1202394
18	3/14/2023	5615 York Rd	21212	Sand, Gravel, Rocks	Dry	N/A		Gray water observed around the cleanout.	1	Ran electric cable through the lateral; blockage remained.	Further investigation, including CCTV inspection, will take place.	1205883
19	3/15/2023	1203 Mosher St	21217	Rags, Grease	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed both the lateral and mainline are clear.	1206065
20	3/16/2023	2505 Queen Anne Rd	21216	Rags	Dry	N/A		Water and paper observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed line is clear.	1206542

SSO Notification List

March 2023

21	3/16/2023	820 N Broadway	21205	Rags	Dry	N/A	110	Gray water running in the rear alleyway.	11	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection to confirm line is clear.	1206577
22	3/19/2023	5208 Belair Rd	21206	Rags	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV confirmed the lateral is now clear.	1206961
23	3/22/2023	1204 Seminole Ave	21229	Structural	Dry	Dead Run	1462	Broken pipe discharging sewage into waterway.	73100	Mainline was repaired to stop the leak and restore system functionality.	CCTV inspection will be performed to gather further information.	1207871
24	3/26/2023	1601 E Madison St	21287	Rags, Trash	Wet	N/A		Gray water observed at the front of the property.	1	Relieved choke with 90 ft of electric cable.	CCTV inspection will be performed.	1208578
25	3/27/2023	615 N Wolfe St	21287	Rags, Grease, Sand, Gravel, Rocks	Wet	N/A		Gray water observed around the manhole in the street.	5	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed to determine if further action is needed.	1208930
26	3/29/2023	2524 Druid Hill Ave	21217	Rags, Trash	Dry	N/A		Gray water observed on the street.	4	Relieved mainline choke with 320 ft of pressure hose.	CCTV inspection will be performed.	1209638
27	3/30/2023	1910 N Pulaski St	21217	Rags, Grease	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved choke with 150 ft of pressure hose.	Confirmed line is clear at this time.	1209739
28	3/31/2023	216 Woodlawn Rd	21210	Rags, Roots	Dry	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 75 ft of electric cable.	Performed lateral CCTV inspection.	1210498
				# WWO	15			TOTAL	244,553	UNDER 100 GALLONS	22	