

## SSO Notification List

March 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/2/2024	105 Deepdene Rd	21210	Rags, Trash	Wet	—	320	Mainline choke causing cleanout to overflow.	32	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV will be performed.	1315744
2	3/4/2024	1122 N Central Ave	21202	Rags, Roots	Wet	—	—	Gray water observed near cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the line is now clear.	—
3	3/4/2024	1222 N Broadway	21213	Rags	Wet	—	—	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable and expander cutter.	Confirmed the lateral and mainline are both clear.	1316050
4	3/4/2024	2836 Winchester St	21216	Rags, Trash	Wet	—	—	Gray water observed near the manhole in the street.	5	Relieved mainline choke with 200 ft of pressure hose.	CCTV will be performed to ensure all obstructions were removed.	1316197
5	3/4/2024	423 E Hamburg St	21230	Rags, Trash	Wet	—	—	Gray water and debris observed near the cleanout.	1	Relieved choke with 30 ft of electric cable.	CCTV confirmed the lateral is clear.	1315943
6	3/6/2024	701 Reservoir St	21217	Rags, Trash	Wet	—	—	Gray water and debris observed near cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are both clear.	1317002
7	3/7/2024	113 N Fulton Ave	21223	Rags, Trash, Unknown	Wet	Gwynns Falls	301	Sewage and debris escaping the manhole.	1505	Flushed the mainline and pumped down the manhole to stop the SSO.	Further action will be needed to fully relieve the choke.	1317123
8	3/7/2024	726 N Carrollton Ave	21217	Roots	Wet	—	—	Gray water observed near the cleanout.	2	Relieved house connection choke with 60 ft of electric cable.	CCTV confirmed the lateral is now clear.	1317263
9	3/8/2024	1904 N Pulaski St	21217	Roots	Wet	—	—	Gray water and paper observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1317525
10	3/8/2024	1620 Edmondson Ave	21217	Rags, Roots, Trash	Dry	—	—	Gray water and debris observed near the manhole.	5	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is clear at this time.	1317590
11	3/8/2024	4205 N Charles St	21218	Rags, Trash	Dry	—	—	Gray water and debris observed near the manhole.	4	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the line is now flowing freely.	1317748
12	3/9/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	145	Manhole adjacent to creek overflowed due to heavy rain.	591020	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
13	3/9/2024	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	285	Structure monitored by metering equipment in the pipe. Not visually observed.	1645020	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
14	3/9/2024	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	195	Structure monitored by metering equipment in the pipe. Not visually observed.	691080	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
15	3/9/2024	1625 Stonewood Rd	21239	Rags, Trash	Wet	Chinquapin Run	1230	Gray water escaping the manhole in the street.	615	Relieved mainline choke with 250 ft of pressure hose.	CCTV will be performed to ensure all obstructions were removed.	1317823
16	3/10/2024	801 Saint Georges Rd	21210	Rags, Grease	Wet	Jones Falls	1378	Gray water escaping the manhole and entering nearby storm drain.	1378	Relieved mainline choke with 350 ft of pressure hose.	Confirmed the line is clear; CCTV will be performed.	—
17	3/11/2024	2432 Fait Ave	21224	Rags	Wet	—	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed lateral is now clear.	1318052
18	3/11/2024	1037 Wedgewood Rd	21229	Structural	Wet	—	—	Gray water observed near the cleanout.	1	Ran electric cable through the lateral; determined structural damage exists.	Lateral will be repaired to restore regular functionality.	1317949
19	3/11/2024	2825 E Chase St	21224	Rags, Unknown	Wet	—	—	Gray water observed at the rear of the property.	1	Ran 15 ft of electric cable; partially relieved choke.	CCTV will be performed to discover cause of further blockage.	1318282
20	3/12/2024	4903 Frankford Ave	21206	Rags, Grease	Wet	—	268	Gray water, paper, and sewage escaping the cleanout.	67	Ran 90 ft of electric cable through the lateral.	Mainline will be flushed and cleaned.	—

SSO Notification List

March 2024

21	3/12/2024	526 S Chapel Gate Ln	21229	Unknown	Wet	—	—	Gray water observed at the front of the property.	2	Attempted to relieve choke with 90 ft of electric cable; blockage remains.	Line will be flushed with pressure hose and CCTV performed.	1318693
22	3/13/2024	3106 Louise Ave	21214	Rags, Roots	Dry	Herring Run	42	Choked sanitary sewer pipe overflowing into adjacent storm pipe.	126	Relieved mainline choke with pressure hose.	Confirmed line is clear; CCTV will be performed.	1318976
23	3/14/2024	5306 Nuth Ave	21206	Structural	Dry	Biddison Run	9100	Broken house connection pipe leaking into storm pipe.	910	Contractor repaired the lateral to stop the SSO.	Dye test was performed to confirm the leak is no longer taking place.	1318976
24	3/14/2024	4401 Frankford Ave	21206	Rags, Roots, Grease	Dry	Biddison Run	559	Choked sanitary sewer manhole discharging into adjacent storm pipe.	559	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the line is clear; CCTV will be performed.	1319339
25	3/16/2024	2401 Edmondson Ave	21223	Rags, Roots	Dry	—	—	Gray water observed at the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	1319999
26	3/17/2024	1600 Kelly Ave	21209	Rags, Grease	Dry	Western Run	110	Heavy gray water escaping the manhole and reaching storm drain.	1100	Relieved mainline choke with 190 ft of pressure hose.	CCTV inspection will determine if further action is needed.	1320029
27	3/19/2024	4719 York Rd	21212	Rags, Trash	Dry	Tiffany Run	358	Choked sanitary sewer infiltrating into adjacent storm pipe.	358	Relieved mainline choke with 100 ft of pressure hose.	Confirmed line is clear; CCTV will be performed.	1320618
28	3/19/2024	1324 W Lombard St	21223	Rags, Trash	Dry	—	—	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	1320448
29	3/21/2024	4901 Frankford Ave	21206	Rags, Grease, Trash	Dry	Biddison Run	126	Overflowing cleanout running down curb into storm inlet.	126	Ran 90 ft of electric cable through the lateral. Flushed and cleaned the mainline.	CCTV inspection will be performed.	1321293
30	3/22/2024	2700 Cheswolde Rd	21209	Roots, Grease	Dry	—	—	Gray water observed from the side cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are clear at this time.	1321436
31	3/23/2024	3900 Belair Rd	21206	Rain	Wet	Herring Run	1575	Manhole adjacent to creek overflowed due to heavy rain.	4410000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
32	3/23/2024	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	1540	Structure monitored by metering equipment in the pipe. Not visually observed.	2109800	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
33	3/23/2024	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1615	Structure monitored by metering equipment in the pipe. Not visually observed.	2039745	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
34	3/25/2024	4901 Frankford Ave	21206	Rags, Grease	Wet	Biddison Run	70	Overflowing cleanout discharging into storm drain inlet.	35	Relieved house connection choke with electric cable.	CCTV inspection will be performed.	1322769
35	3/25/2024	406 Colleen Rd	21229	Unknown	Wet	—	—	Gray water observed at the front of the property.	2	Ran electric cable through lateral; determined structural damage exists.	House connection will be repaired to restore functionality.	1323010
36	3/26/2024	6503 Glenoak Ave	21214	Trash	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	1324030
37	3/29/2024	3033 Gwynns Falls Pkwy	21216	Rags, Roots	Wet	—	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection confirmed the lateral and mainline are clear.	1325095
38	3/30/2024	121 McMechen St	21217	Rags, Trash	Dry	Jones Falls	114	Sewage and water discharging from manhole.	114	Relieved mainline choke with 200 ft of pressure hose.	Confirmed line is now clear; CCTV will be performed.	1325154
39	3/31/2024	1807 W Rogers Ave	21209	Roots	Dry	—	—	Gray water observed near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	1325191
				# WWO	25			TOTAL	11,493,625	UNDER 100 GALLONS	23	