

SSO Notification List												
March 2025												
Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/1/2025	250 W Pratt St	21201	Trash	Dry	Northwest Harbor	289	Wastewater with debris	867	Set up bypass pumping to abate the overflow	CCTV Inspection will be performed	1423405
2	3/1/2025	4606 Schenley Rd	21210	Rags, Roots, Trash	Dry	—	—	Wastewater observed coming from front house connection	1	Relieved house connection choke with 75 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1423417
3	3/2/2025	1822 Park Ave	21217	Rags, Grease, Trash	Dry	Jones Falls	186	Wastewater with grease, rags and debris.	372	Relieved choke with 50' of pressure hose	CCTV inspection scheduled	1423508
4	3/2/2025	3300 W Forest Park Ave	21216	Trash	Dry	Gwynns Falls	—	Wastewater with trash	5	Relieved choke using 30' of electric cable and spearhead	CCTV Inspection will be scheduled	1423541
5	3/3/2025	816 N Fremont Ave	21217	Rags, Roots, Trash	Dry	—	170	Observed wastewater coming from rear house connection	85	Relieved house connection choke with 90 ft electric cable	Confirmed house connection is clear at this time. Referred for CCTV inspection	1423841
6	3/4/2025	309 Mosher St	21217	Rags, Grease, Trash	Dry	Jones Falls	132	Subsurface SSO infiltrating adjacent storm drain manhole underground.	396	Relieved choke using 300 ft. of pressure hose	CCTV Inspection will be scheduled	1423976
7	3/5/2025	1512 Poplar Grove St	21216	Rags, Trash	Wet	Gwynns Falls	—	Observed wastewater coming from rear house connection	1	Relieved house connection choke with 15 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1424245
8	3/5/2025	Lawina Rd & Westchester Rd	21217	Rags, Trash	Wet	Jones Falls	—	Observed wastewater coming from manhole	20	Relieved mainline choke with 300 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV inspection	1424347
9	3/6/2025	2651 Frederick Ave	21223	Rags, Trash	Wet	—	—	Wastewater with rags and debris	2	Relieved choke using 30 ft. of electric cable with spearhead	CCTV Inspection will be performed	1424353
10	3/6/2025	Elizabeth Ave & Harriet Ave	21230	Rags, Grease, Trash	Wet	—	—	Wastewater with grease, rags and debris	20	Relieved choke with 300 ft of pressure hose	CCTV Inspection will be performed	1424586
11	3/6/2025	2824 Rosalie Ave	21234	Rags, Trash	Wet	—	—	Observed wastewater coming from front house connection	1	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time	1424598
12	3/7/2025	4600 Hamilton Ave	21206	Trash, Structural	Wet	—	—	Wastewater with debris	6	Unable to relieve choke using pressure truck so, bypass pumping set up to stop overflow.	CCTV Inspection was performed	1424651
13	3/8/2025	1029 W 36th St	21211	Rags	Wet	Jones Falls	130	Observed wastewater coming from rear house connection	65	Relieved house connection choke with 30 ft electric cable	Confirmed house connection cleaned to the mainline and clear at this time. CCTV will be performed	1424887
14	3/10/2025	213 S Eden St	21231	Rags, Trash	Dry	—	86	Wastewater with rags, trash and fecal matter	172	Relieved choke using 60 ft of electric cable with saw teeth	CCTV Inspection was performed	1425176
15	3/10/2025	6107 Eastern Pkwy	21206	Rags, Roots, Trash	Dry	Moores Run	108	Observed wastewater overflow from manhole into nearby storm drain	2160	Relieved mainline choke with 300 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV Inspection	1425184
16	3/10/2025	3027 Wylie Ave	21215	Rags	Dry	—	—	Wastewater with rags	2	Relieved choke using electric cables with saw teeth	CCTV Inspection was performed	1425280
17	3/12/2025	1812 Braddish Ave	21216	Rags, Roots	Dry	—	—	Observed wastewater at rear house connection	1	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1425665
18	3/12/2025	3615 W Forest Park Ave	21216	Rags, Grease, Trash	Dry	Gwynns Falls	122	Wastewater with heavy grease deposits causing subsurface SSO infiltrating the adjacent storm drain	610	Relieved mainline choke using pressure hose	CCTV Inspection will be performed	1425707
19	3/14/2025	2500 Liberty Heights Ave	21215	Rags	Dry	—	—	Wastewater with rags	3	Relieved house connection choke with 60ft of electric machine cable	CCTV Inspection was performed	1427709
20	3/14/2025	2200 W Lexington St	21223	Rags	Dry	—	—	Wastewater with rags	5	Relieved rear house connection choke with 30ft of electric machine cable	CCTV Inspection will be performed	1427721

SSO Notification List												
March 2025												
21	3/18/2025	Edmondson Ave & Hilton Pkwy	21229	Trash	Wet	Gwynns Falls	1172	Wastewater escaping the manhole in the street.	5860	Relieved mainline choke with 100 ft of pressure hose.	CCTV inspection will be performed; confirmed line is now clear.	1428634
22	3/19/2025	1639 Northwick Rd	21218	Roots	Wet	—	—	Observed wastewater at front house connection	2	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1428965
23	3/19/2025	701 N Carey St	21217	Rags	Wet	—	—	Observed wastewater and debris coming from house connection	1	Relieved house connection choke with 60 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1429069
24	3/19/2025	1706 McCulloh St	21217	Rags	Wet	—	—	Wastewater with rags	3	Relieved choke with 30 ft. of electric cable with expander cutter	CCTV Inspection was performed	1429110
25	3/19/2025	905 W Fayette St	21223	Rags	Wet	—	—	Wastewater with rags	2	Relieved choke with 60 ft of electric machine cable with expander/cutter	CCTV Inspection was performed	1429134
26	3/20/2025	Ridgewood Ave & Granada Ave	21215	Rags, Trash	Dry	Gwynns Falls	338	Subsurface wastewater infiltrating into adjacent storm drain	1014	Relieved mainline choke with 300 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1429349
27	3/21/2025	2407 Arunah Ave	21223	Rags, Trash	Wet	—	—	Observed wastewater coming from rear house connection	1	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1429756
28	3/21/2025	2325 Druid Hill Ave	21217	Rags	Wet	—	—	Observed wastewater and debris at rear house connection	1	Ran 45 ft electric cable to relieve house connection	Confirmed house connection to mainline is clear at this time. CCTV was performed	1429810
29	3/23/2025	2121 Kentucky Ave	21218	Roots	Wet	—	—	Wastewater with tree roots	1	Relieved choke using 35 ft. of electric cable with expander	CCTV Inspection was performed	1429930
30	3/25/2025	3501 Taylor Ave	21234	Rags	Dry	Moores Run	488	Wastewater with rags.	9760	Relieved choke by flushing and cleaning 8" sewer main	CCTV will be performed	1430465
31	3/26/2025	618 N Carrollton Ave	21217	Roots	Dry	Gwynns Falls	—	Wastewater with roots	1	Relieved choke using electric cables with header/saw cutter	CCTV Inspection was performed	1430640
32	3/26/2025	5105 Roland Ave	21210	Unknown	Dry	—	—	Sewage water surcharging from ground next to sidewalk.	1	Bypass pumping	CCTV Inspection was performed	1425783
33	3/26/2025	4403 Frederick Ave	21229	Rags, Trash	Dry	—	1822	Observed wastewater coming from manhole	1822	Relieved mainline choke with 450 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV to be performed	1430795
34	3/30/2025	6214 Cross Country Blvd	21215	Rags, Trash	Dry	—	—	Observed wastewater coming from manhole	3	Relieved mainline choke with 100 ft of pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1431367
35	3/30/2025	1612 Westwood Ave	21217	Roots	Dry	—	100	Observed wastewater coming from rear house connection	50	Relieved house connection choke with 60 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1431406
36	3/30/2025	831 Harlem Ave	21201	Rags	Dry	—	—	Wastewater with rags	1	Relieved choke using 35 ft of electric cable with saw tooth	CCTV Inspection will be performed	1431403
37	3/30/2025	3435 Edmondson Ave	21229	Rags, Grease, Trash	Dry	—	170	Wastewater with grease, rags and debris	510	Relieved choke with 350 ft. of pressure hose	CCTV Inspection will be performed	1431413
38	3/31/2025	2300 St Paul St	21218	Rags, Roots, Unknown	Dry	—	—	Observed wastewater coming from rear house connection	2	Ran 30 ft electric cable to relieve house connection, brought back rag and roots.	Placed on bypass pumping for further investigation	1431455
39	3/31/2025	2510 E Strathmore Ave	21214	Trash	Dry	—	—	Wastewater with debris	1	Choke relieved at this location.	CCTV Inspection will be performed	1431518
40	3/31/2025	1920 Park Ave	21217	Trash	Wet	—	—	Wastewater with debris	2	Relieved choke using 250 of pressure hose	CCTV Inspection will be performed	1431734
				# WWO	16			TOTAL	23,832	UNDER 100 GALLONS	29	