

SSO Notification List

May 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/3/2019	623 N Grantley St	21229	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	735236
2	5/3/2019	607 S Beechfield Ave	21229	Rags, Roots, Grease	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	735273
3	5/3/2019	1822 N Payson St	21217	Trash, Sand, Gravel, Rocks, Structural	Dry	N/A	70	Heavy gray water escaping the cleanout at the rear of the property.	140	Bypass pump was installed to abate the overflow while repairs are made.	Repair of sanitary lateral will prevent further overflow.	735290
4	5/6/2019	4500 O'Donnell St	21224	Grease, Trash	Wet	N/A	223	Gray water escaping the manhole in the street.	4,460	Relieved mainline choke with 200 ft of pressure hose.	Performed CCTV inspection; confirmed flow has returned to normal.	736042
5	5/6/2019	800 S Caton Ave	21229	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout.	10	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral is clear.	736362
6	5/7/2019	4200 Falls Rd	21210	Rags, Roots	Wet	Jones Falls	60	Gray water escaping the manhole in the street.	120	Relieved mainline choke with 300 ft of pressure hose.	Performed CCTV inspection	0
7	5/9/2019	2600 Oswego Ave	21215	Structural	Dry	Jones Falls	7,350	Lateral leaking sewage into the storm drain.	1,838	Performed repair to the house connection.	Abatement confirmed via dye testing.	0
8	5/9/2019	2501 Shirley Ave	21215	Structural	Dry	Jones Falls	7,349	Sewage escaping a lateral due to structural damage.	7,349	Performed repair to the house connection.	Abatement confirmed via dye testing.	0
9	5/10/2019	3900 Bel Air Rd	21206	Rain	Wet	Herring Run	4,210	Manhole adjacent to creek overflowed due to heavy rain.	867,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	0
10	5/10/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	4,280	Structure monitored by metering equipment in the pipe. Not visually observed.	11,636,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital project.	0
11	5/10/2019	Queensbury Ave & W Garrison Ave - SSO Site #139	21215	Rain	Wet	Jones Falls	25	Structured overflow discharging to a nearby storm drain.	2,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital project.	0
12	5/10/2019	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	30	Structured overflow discharges to a storm drain pipe and is monitored by a meter.	12,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital project.	0
13	5/10/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	3,955	Structure monitored by metering equipment in the pipe. Not visually observed.	1,845,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital project.	0
14	5/12/2019	1900 Falls Rd	21120	Rags, Rain, Trash	Wet	Jones Falls	440	Gray water escaping manholes in the street.	11,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	0
15	5/12/2019	1800 E Eager St	21205	Rags, Rain, Grease, Trash	Wet	Harbor	290	Gray water escaping the manhole in the street.	1,450	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	0

SSO Notification List

May 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
16	5/12/2019	1731 E Chase St	21205	Rain	Wet	Harbor	306	Gray water escaping the manhole in the street.	30,600	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	0
17	5/12/2019	Wilkins Ave & Brunswick St	21223	Rain, Structural	Wet	Gwynns Falls	2,528	Heavy gray water flowing out of the manhole in the street.	6,490,000	Overflow subsided following heavy rain event.	Repairs being made to a pressure main reduced the line's capacity.	0
18	5/17/2019	1016 N Central Ave	21202	Structural	Dry	N/A	0	Gray water escaping the lateral.	10	Set up bypass pumping to stop the overflow.	Pipe will be scheduled for repair; CCTV inspection.	0
19	5/18/2019	5802 Eastern Ave	21224	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout.	7	Relieved house connection choke.	Performed CCTV inspection.	0
20	5/19/2019	522 W Preston St	21201	Trash, Structural	Wet	Jones Falls	615	Gray water escaping house connection and causing basement backup.	1,230	Set up bypass pumping to stop the overflow.	Investigating options for long-term solution at this location.	0
21	5/20/2019	1313 Southview Rd	21218	Rags, Roots, Grease	Wet	Herring Run	180	Gray water escaping the manhole.	1,800	Relieved mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	0
22	5/20/2019	Cylburn Ave & Greenspring Ave	21215	Rags, Roots, Grease	Wet	Jones Falls	150	Heavy gray water escaping the manhole.	3,750	Relieved 12" mainline choke with 285 ft of pressure hose.	Performed mainline CCTV inspection.	0
23	5/22/2019	935 Montpelier St	21218	Structural	Dry	N/A	0	Gray water escaping the lateral.	3	Ran 4 ft of electric cable.	Left plumber's notice to have pipe repaired on consumer's side.	0
24	5/24/2019	5518 Fernpark Ave	21207	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout.	5	Relieved 6" house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	0
25	5/25/2019	1147 Monroe Cir	21225	Rags, Roots	Wet	N/A	0	Gray water and paper observed around the cleanout.	3	Relieved choke with 35 ft of electric cable.	Performed CCTV inspection.	0
26	5/27/2019	4908 Chalgrove Ave	21215	Rags, Trash	Dry	N/A	60	Gray water and debris escaping the cleanout.	10	Relieved the choke.	Performed CCTV inspection.	0
27	5/29/2019	1248 N Gay St	21213	Rags	Wet	N/A	38	Gray water escaping the manhole.	570	Relieved choke with pressure hose.	Performed CCTV inspection.	0
28	5/30/2019	2208 Fleet St	21231	Trash	Dry	N/A	0	Gray water observed around the cleanout.	2	Relieved choke with electric cable.	Performed CCTV inspection.	0
29	5/31/2019	4823 Keswick Rd	21210	Rags, Roots, Sand, Gravel, Rocks	Wet	Jones Falls	97	Gray water escaping the manhole.	970	Relieved mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	0
				# WWO	19			TOTAL	20,917,334	UNDER 100 GALLONS	10	