

SSO Notification List

May 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/1/2022	1717 Chilton St	21218	Roots, Grease	Dry	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed the mainline.	1089548
2	5/1/2022	1619 Gwynns Falls Pkwy	21217	Roots	Wet	N/A	84	Gray water escaping the cleanout.	21	Relieved house connection choke with 45 ft of electric cable.	Lateral CCTV inspection confirmed the line is now clear.	1092066
3	5/2/2022	1512 Poplar Grove St	21216	Rags, Trash	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear at this time.	1097406
4	5/4/2022	1704 N Regester St	21213	Rags, Roots	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the mainline and lateral are now clear.	1101056
5	5/5/2022	12 Beechdale Rd	21210	Rags, Roots, Trash	Wet	Jones Falls	154	Choked sewer overflowing into adjacent storm pipe.	3,850	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is now clear; CCTV will be performed.	1101647
6	5/5/2022	1801 N Caroline St	21213	Rags, Rain	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection and mainline cleaning will be performed.	1101902
7	5/5/2022	3405 W Strathmore Ave	21215	Rags	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are now clear.	1101950
8	5/7/2022	2508 Queen Anne Rd	21216	Rags, Grease, Sand, Gravel, Rocks	Wet	N/A		Gray water observed around the cleanout and sidewalk.	5	Relieved choke with 60 ft of pressure hose; investigation will take place for possible break.	CCTV inspection will be performed to determine next steps.	1102241
9	5/8/2022	1820 Spence St	21230	Roots	Wet	N/A		Gray water observed at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the line is now clear.	1102272
10	5/9/2022	2734 W North Ave	21216	Rags, Grease	Wet	Gwynns Falls	131	Gray water escaping the manhole.	655	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1102337
11	5/10/2022	1107 Slater Rd	21225	Rags, Grease	Wet	N/A	102	Gray water escaping manhole and entering nearby storm drain.	1,530	Relieved 8" mainline choke with 250 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1102673
12	5/11/2022	317 E North Ave	21202	Rags, Trash	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral is now clear.	1103250
13	5/13/2022	2512 Southdene Ave	21230	Rags, Roots	Wet	N/A		Gray water observed around the cleanout.	1	Relieved choke with electric cable and pressure hose.	Confirmed the lateral and mainline are now clear.	1103919
14	5/13/2022	527 S Luzerne Ave	21205	Rags	Wet	N/A		Gray water observed around the cleanout.	1	Ran 45 ft of electric cable through the lateral; cleaned the mainline.	CCTV inspection will be performed.	1103804
15	5/14/2022	1520 Clipper Rd	21211	Grease, Trash	Wet	N/A		Gray water observed around the sidewalk.	2	Relieved house connection choke with 65 ft of electric cable.	Confirmed line is clear. Advised consumer to install grease trap.	1104003
16	5/14/2022	4315 Lasalle Ave	21206	Rags, Trash	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 120 ft of electric cable.	CCTV confirmed the lateral and mainline are clear.	1104016
17	5/14/2022	510 N Chester St	21205	Rags	Wet	N/A		Gray water observed at the front of the property.	1	Ran 75 ft of electric cable through the lateral.	CCTV inspection and mainline cleaning will be performed.	1104027
18	5/15/2022	1214 Homewood Ave	21202	Rags	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection confirmed the line is clear.	1104113
19	5/16/2022	1605 Popland St	21226	Rags, Grease	Wet	N/A		Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1104426
20	5/17/2022	1628 Braddish Ave	21216	Roots, Grease	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Confirmed the lateral and mainline are both clear.	1104767

SSO Notification List

May 2022

21	5/18/2022	318 Joplin St	21224	Roots	Dry	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection to confirm the lateral is clear.	1105046
22	5/21/2022	2621 Talbot Rd	21216	Rags, Sand, Gravel, Rocks, Unknown	Dry	N/A		Gray water observed around the cleanout.	1	Flushed the line with 25 ft of pressure hose.	Further investigation will take place to see if repairs are necessary.	1105781
23	5/23/2022	3600 O'Donnell St	21224	Rags, Grease	Wet	N/A		Gray water observed around the manhole.	2	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed the mainline is clear at this time.	1106072
24	5/23/2022	4101 Pulaski Hwy	21224	Rags, Roots, Trash	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection and results showed the line is clear.	1106096
25	5/23/2022	1528 N Caroline St	21213	Structural, Unknown	Wet	N/A		Gray water observed at the front of the property.	1	Ran 15 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will take place.	1106170
26	5/24/2022	3111 Southern Ave	21214	Structural	Wet	Herring Run	20451	Sanitary pipe leaking into underdrain and discharging into the adjacent storm pipe.	27,404	Stopped the SSO by having contractor successfully set up bypass pumping.	Line will eventually be repaired to restore system to regular functionality.	1106176
27	5/26/2022	4803 York Rd	21212	Rags, Infiltration, Trash	Wet	Tiffany Run	1218	Subsurface overflow infiltrating nearby storm drain system; discovered during routine sampling.	6,090	Relieved 85 ft of blockage by way of pressure truck.	Turned over for CCTV inspection to determine if further action is needed	1107079
28	5/28/2022	209 E Lafayette Ave	21202	Rags, Roots	Wet	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	1107414
29	5/29/2022	1910 Eastern Ave	21231	Rags, Roots	Wet	N/A		Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the lateral and mainline are now clear.	1107448
30	5/31/2022	3500 The Alameda	21218	Rags, Infiltration, Trash	Dry	Tiffany Run	182	Choked mainline overflowing into storm drain system.	546	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the mainline is no longer infiltrating the storm drain at this time.	1107618
31	5/31/2022	1058 W Fayette St	21223	Rags, Unknown	Dry	N/A		Gray water observed around the cleanout.	1	Ran electric cable through the lateral.	Further investigation, including a CCTV inspection, will take place.	1107626
32	5/31/2022	448 S Augusta Ave	21229	Roots, Trash	Dry	N/A		Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear at this time.	1107733
33	5/31/2022	2512 Southdene Ave	21230	Structural	Dry	N/A		Gray water observed around the cleanout.	1	Ran 30 ft of electric cable through the lateral; discovered structural damage.	House connection will need repair. Bypass pumping may be required while repairs take place.	1104339
				# WWO	25			TOTAL	40,129	UNDER 100 GALLONS	27	