

SSO Notification List												
May 2025												
Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/1/2025	2775 W North Ave	21216	Rags, Grease	Dry	Gwynns Falls	—	Observed wastewater coming from rear house connection	10	Relieved house connection choke with 30 ft electric cable	Confirmed house connection and mainline clear at this time. CCTV will be performed	1439763
2	5/1/2025	5621 Belair Rd	21206	Rags, Grease	Dry	—	—	Wastewater with grease and rags	1	Relieved choke using electric cables with saw teeth	CCTV Inspection was performed	1439779
3	5/5/2025	1904 N Pulaski St	21217	Roots, Trash	Wet	—	—	Observed wastewater coming from rear house connection	1	Relieved house connection choke with 15 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1440239
4	5/6/2025	5501 Frenpark Ave	21207	Rags	Wet	—	—	Wastewater with rags	3	Relieved choke using electric cable with expander cutter	CCTV Inspection will be performed	1441640
5	5/6/2025	4238 Roland View Ave	21215	Rags, Structural	Wet	—	—	Wastewater with rags	5	Performed CCTV Inspection to access choked feature	Repair house connection on city side.	1441711
6	5/7/2025	3303 Chesley Ave	21234	Structural	Wet	Moores Run	10080	Broken house connection causing leakage into storm drain	2520	Open cut point repair was performed	CCTV Inspection was performed	1441956
7	5/7/2025	2627 Wegworth Ln	21230	Rags, Grease, Trash	Wet	Gwynns Falls	1638	Observed wastewater coming from manhole connected to City sewer main	8190	Relieved mainline choke with 300 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV	1442000
8	5/7/2025	2000 N Howard St	21218	Rags	Wet	—	—	Observed wastewater coming from side house connection	2	House connection choke was relieved by plumber	Confirmed house connection clear after speaking with consumer. CCTV will be performed	1442031
9	5/8/2025	5204 Liberty Heights Ave	21207	Rags, Trash	Wet	Gwynns Falls	282	Wastewater with rags and debris. Subsurface SSO infiltrating the storm drain system.	564	Relieved choke using 300ft pressure hose.	CCTV Inspection will be performed	1442131
10	5/8/2025	821 W Lake Ave	21210	Rags	Dry	—	—	Observe wastewater coming from cleanout	2	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1442287
11	5/8/2025	1129 N Fulton Ave	21217	Rags, Trash	Dry	—	—	Wastewater with rags and debris	1	Relieved choke using electric machine with spearhead and cutter	CCTV Inspection scheduled	1442290
12	5/11/2025	5944 Green Meadow Pkwy	21209	Rags, Roots	Wet	—	—	Wastewater with roots and rags	2	Relieved choke using electric machine cable with sawtooth and spearhead	CCTV Inspection will be performed	1442592
13	5/12/2025	2711 Ruscombe Ln	21215	Rags, Trash	Dry	—	—	Wastewater with rags and debris	0.1	Relieved choke using pressure hose	CCTV Inspection scheduled	1442940
14	5/12/2025	1906 Ramblewood Rd	21239	Sand, Gravel, Rocks, Other	Dry	—	—	Observed wastewater coming from front house connection	3	Relieved house connection choke with 30 ft electric cable	Confirmed house connection relieved after removing debris. CCTV was performed	1442980
15	5/13/2025	2606 Chelsea Terrace	21216	Structural	Wet	—	—	Observed wastewater coming from cleanout	1	Attempt to relieve house connection choke with 25 ft electric cable. Partially relieved	CCTV was performed confirmed break in pipe, Turned over for repair	1443411
16	5/14/2025	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	70	Structure monitored by metering equipment in the pipe. Not visually observed.	112000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
17	5/14/2025	4403 Frederick Ave	21229	Rags, Grease, Trash	Wet	—	—	Observed wastewater coming from manhole	2	Relieved mainline choke flushed and cleaned with 527 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV	1443595
18	5/16/2025	2500 Liberty Heights Ave	21215	Rags	Wet	—	—	Wastewater with rags	0.2	Relieved choke using 45ft of electric machine with cutter	CCTV Inspection was performed	1444158
19	5/19/2025	500 W University Pkwy	21210	Rags, Grease, Trash	Wet	Stony Run	173	Observed wastewater from manhole flowing into adjacent stream	8650	Relieved mainline choke with 330 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV inspection	1444425
20	5/19/2025	31 S Washington St	21231	Rags, Roots	Wet	—	—	Observed wastewater coming from rear house connection	2	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV will be performed	1444467

SSO Notification List												
May 2025												
21	5/25/2025	2119 Kentucky Ave	21218	Rags, Roots, Trash	Wet	—	45	Observed wastewater coming from rear house connection	4.5	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1445864
22	5/25/2025	3116 N Calvert St	21218	Rags, Trash	Wet	—	—	Observed wastewater at rear house connection	1	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1445868
23	5/25/2025	2415 W Franklin St	21223	Rags	Dry	—	—	Observed wastewater coming from front house connection	2	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1445878
24	5/26/2025	Eastern Ave & S Eden St	21231	Rags, Grease, Trash	Dry	—	—	Wastewater with rags, grease and debris	3	Relieved choke using pressure hose	CCTV Inspection will be performed	1445909
25	5/27/2025	Clifton Rd & Mondawmin Ave	21216	Rags, Trash	Dry	—	—	Wastewater with rags and debris	5	Relieved choke using pressure hose	CCTV Inspection will be performed	1446031
26	5/27/2025	5944 Green Meadow Pkwy	21209	Rags	Dry	—	—	Observed wastewater at rear house connection	2	Relieved house connection choke with 75 ft electric cable and help from pressure truck	Confirmed connection and mainline is clear at this time. CCTV will be performed	1446182
27	5/29/2025	1819 Appleton St	21217	Trash, Other	Wet	—	166	Wastewater with mud and debris	498	Used electric machine with cutter/spearhead	CCTV Inspection will be performed	1446973
28	5/30/2025	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	130	Structure monitored by metering equipment in the pipe. Not visually observed.	23010	SSO structure; overflow due to heavy rain	SSO structure will be closed upon completion of capital improvement projects	—
29	5/30/2025	N Charles St & W Lanvale St - SSO Site #152	21201	Rain	Wet	Jones Falls	15	Structure discharges to an outfall pipe and is monitored by metering equipment in the pipe.	1005	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
30	5/30/2025	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	125	Structure monitored by metering equipment in the pipe. Not visually observed.	445875	SSO structure; overflow due to heavy rain	SSO structure will be closed upon completion of capital improvement projects.	—
31	5/30/2025	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	20	Manhole overflowed due to heavy rain event.	2000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
32	5/30/2025	3900 Belair Rd	21206	Rain	Wet	Herring Run	145	Manhole adjacent to creek overflowed due to heavy rain.	476035	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	—
33	5/31/2025	Wabash Ave & Dorchester Rd	21215	Rags, Trash	Wet	Gwynns Falls	430	Observed wastewater coming from manhole	430	Relieved mainline choke flushed and cleaned with 350 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1447752
				# WWO	23			TOTAL	1,080,830	UNDER 100 GALLONS	21	