

SSO Notification List

November 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/1/2021	642 Harvey St	21230	Rags	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear at this time.	989241
2	11/1/2021	2033 E Preston St	21213	Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Ran 15 ft of electric cable through the lateral; flushed and cleaned the mainline.	CCTV inspection will be performed to ensure line is clear.	989335
3	11/1/2021	221 E 33rd St	21218	Roots	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed the lateral is clear at this time.	989398
4	11/1/2021	2816 Christopher Ave	21214	Trash	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 15 ft of electric cable.	Lateral CCTV inspection will be performed.	989418
5	11/2/2021	4104 Buena Vista Ave	21211	Rags, Roots	Dry	Jones Falls	0	Gray water observed at the front of the property.	2	Relieved choke with 40 ft of electric cable and 150 ft of pressure hose.	Confirmed the lateral and mainline are clear.	989694
6	11/3/2021	251 S Morley St	21229	Rags, Roots	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection and mainline chokes with pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	991023
7	11/3/2021	1041 Saint Paul St	21202	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 75 ft of electric cable.	CCTV inspection will be performed; flushed and cleaned the mainline.	991634
8	11/4/2021	4517 Schenley Rd	21210	Rags	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 90 ft of electric cable.	Lateral CCTV inspection will be performed.	991834
9	11/6/2021	W Cold Spring Ln & Keswick Rd	21210	Rags, Grease, Trash	Dry	Jones Falls	71	Gray water escaping the manhole and entering nearby storm drain.	142	Relieved mainline choke with 375 ft of pressure hose.	Confirmed the mainline is now clear; CCTV inspection will be performed.	992104
10	11/9/2021	4800 Falls Rd	21210	Rags, Roots, Grease, Trash	Dry	Jones Falls	171	Heavy gray water escaping the manhole.	2,565	Relieved mainline choke with 480 ft of pressure hose.	Confirmed the mainline is now clear; CCTV inspection will be performed.	996116
11	11/9/2021	4250 Greenspring Ave	21215	Rags, Roots, Grease	Dry	Jones Falls	95	Manhole overflowing into street and storm drain inlet.	1,900	Relieved mainline choke with 100 ft of pressure hose.	Confirmed line is now clear; CCTV inspection will be performed.	996223
12	11/9/2021	2700 W North Ave	21216	Rags, Grease, Trash	Dry	N/A	162	Gray water escaping the manhole in the street.	81	Relieved mainline choke with 300 ft of pressure hose.	Mainline is clear at this time; CCTV inspection will be performed.	996275
13	11/10/2021	4000 Buena Vista Ave	21211	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 100 ft of pressure hose.	Confirmed the lateral is now clear. Mainline will be cleaned.	996488
14	11/11/2021	1531 Edmondson Ave	21223	Rags	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection and results showed the line is clear.	996561
15	11/12/2021	1503 Edmondson Ave	21223	Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are now clear.	996659
16	11/14/2021	1200 N Franklinton Rd	21216	Rags, Roots, Grease, Trash	Wet	Gwynns Falls	1008	Gray water escaping the manhole.	2,016	Relieved mainline choke with 50 ft of electric cable.	Confirmed the mainline is clear; CCTV inspection will be performed.	996981
17	11/15/2021	2325 Hollins St	21223	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	3	Relieved choke with 35 ft of pressure hose.	Confirmed all nearby lines are now clear.	997135
18	11/15/2021	1613 E Fairmount Ave	21231	Rags, Roots, Trash	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	997281
19	11/17/2021	6201 Fortview Way - Private	21224	Rags, Grease, Trash	Dry	Inner Harbor	122	Gray water escaping private manhole.	1,220	DPW assisted by relieving private mainline choke with 275 ft of pressure hose.	Sewer lines are owned by Housing Authority.	997645
20	11/17/2021	2775 W North Ave	21216	Rags, Roots	Dry	N/A	0	Gray water and rags observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral and mainline are both clear.	997679
21	11/17/2021	6301 Boston St - Private	21224	Grease, Trash	Dry	Inner Harbor	49	Gray water escaping private manhole.	1,470	DPW assisted by relieving private mainline choke with 150 ft of pressure hose.	Sewer lines are owned by Housing Authority.	997728
22	11/18/2021	5512 Park Heights Ave	21215	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear at this time. Cleaned the mainline.	998006

SSO Notification List

November 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
23	11/21/2021	4101 Stokes Dr	21229	Rags, Roots, Grease	Dry	Gwynns Falls	176	Gray water escaping the manhole.	176	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the line is now clear at this time.	998381
24	11/21/2021	N Bentalou St & Walbrook Ave	21216	Rags, Trash	Dry	N/A	0	Gray water observed around a sump pump.	1	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is clear at this time.	998398
25	11/22/2021	301 E 22nd St	21218	Rags, Grease	Dry	Jones Falls	88	Gray water escaping the sump pump at the rear of the property.	440	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	998518
26	11/22/2021	3704 Bayonne Ave	21206	Rags	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed both the lateral and mainline are clear at this time.	998564
27	11/22/2021	1541 N Broadway	21213	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed both the lateral and mainline are now clear.	998594
28	11/23/2021	3611 Gwynn Oak Ave	21207	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the manhole.	3	Relieved 8" mainline choke with 400 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	998796
29	11/24/2021	29 N Franklinton Rd	21223	Rags, Grease, Trash	Dry	Gwynns Falls	98	Gray water escaping the manhole. Discovered during routine sampling.	490	Relieved mainline choke with 150 ft of pressure hose.	Confirmed the line is now clear. CCTV inspection will be performed.	998990
30	11/25/2021	3632 Beech Ave	21211	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and determined the line is now clear.	999137
31	11/26/2021	4217 Rokeby Rd	21229	Structural	Dry	N/A	1608	Sewage discharging from broken mainline.	48,240	Construction crew repaired the break to restore line to normal functionality.	SSO abatement confirmed by the Office of Compliance and Research.	999246
32	11/26/2021	2800 Rosalind Ave	21215	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 200 ft of pressure hose.	Performed CCTV inspection and confirmed the lateral is clear.	999218
33	11/26/2021	1026 N Payson St	21217	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear at this time.	999256
34	11/29/2021	2518 Druid Park Dr	21215	Rags, Roots, Trash	Dry	Jones Falls	155	Gray water escaping the manhole and running down alley.	1,550	Relieved 8" mainline choke with 150 ft of pressure hose.	Confirmed the line is clear at this time. CCTV inspection will be performed.	999464
35	11/29/2021	231 N Gilmor St	21223	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole in the street.	2	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed.	999620
36	11/30/2021	1412 N Luzerne Ave	21213	Rags	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Confirmed the lateral and mainline are now flowing freely.	999797
37	11/30/2021	2931 Whittington Ave	21230	Rags	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is now clear.	999812
38	11/30/2021	1026 N Payson St	21217	Grease	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 40 ft of electric cable.	CCTV inspection will be performed to determine if structural damage exists.	999824
				# WWO	7			TOTAL	57,635	UNDER 100 GALLONS	27	