

SSO Notification List

November 2024

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/1/2024	Erdman Ave & Annetta Ave	21213	Rags, Roots, Infiltration	Dry	Herring Run	143	Mainline choke is causing a subsurface SSO to infiltrate the nearby storm drain.	715	Relieved mainline choke with 200 ft of pressure hose.	Abatement confirmed via Office of Research & Environmental Protection.	1388104
2	11/3/2024	1520 Clipper Rd	21211	Grease	Dry	—	95	Gray water and toilet tissue	19	Relieved house connection choke with 60 ft of electric cable.	Advised restaurant not to pour grease down the drain.	1388306
3	11/6/2024	4503 Maine Ave	21207	Rags	Dry	—	—	Rags found at cleanout location	1	Relieved mainline choke with pressure hose	Recommended for CCTV Inspection	1388843
4	11/7/2024	2323 W Patapsco Ave	21230	Trash, Structural	Dry	—	—	Wastewater observed coming from front house connection	1	Relieved house connection choke and advised consumer to have their portion investigated	Further investigation will take place.	1388972
5	11/8/2024	1415 N Longwood St	21216	Roots	Dry	—	—	Wastewater observed coming from rear house connection	2	Relieved house connection choke with 30 ft electric machine	Confirmed house connection is clear. CCTV will be performed	1389182
6	11/8/2024	6001 Pimlico Rd	21209	Rags	Dry	—	—	Observed wastewater coming from rear house connection	2	Relieved house connection choke with 30 ft electric machine cable	CCTV confirmed house connection is clear	1389288
7	11/11/2024	2510 Southdene Ave	21230	Rags, Other	Wet	—	—	Front house connection choke with evidence of sewer water overflow.	1	Used 30 ft of electric machine cable to relieve choke.	No further action taken at this time.	1389411
8	11/12/2024	5422 York Rd	21212	Rags, Other	Wet	—	—	Gray water along with rags, and debris.	2	Mainline choke relieved using 200' Pressure Hose.	CCTV Inspection will be scheduled	1389684
9	11/13/2024	2603 Talbot Rd	21216	Trash	Wet	—	—	Evidence of overflow observed at front house connection	1	Relieved house connection choke with 90 ft electric cable	Confirmed house connection is clear at this time	1389942
10	11/13/2024	3100 Batavia Ave	21214	Rags, Grease, Infiltration	Wet	Herring Run	124	Choked mainline causing wastewater to infiltrate the storm drain.	620	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1389966
11	11/16/2024	208 E Eager St	21202	Trash	Wet	—	—	Gray water and debris observed near the cleanout	1	Ran electric machine cable for 30' to relieve choke	CCTV inspection will be performed	1390742
12	11/17/2024	N Ellamont St & Gwynns Falls Pkwy	21216	Rags, Trash	Wet	—	129	Wastewater observed coming from manhole	129	Relieved mainline choke with 200 ft pressure hose	Confirmed mainline is clear at this time	1390759
13	11/17/2024	1820 Spence St	21230	Rags, Trash	Wet	—	—	Rags and trash exposed in overflow	3	Relieved mainline choke with 300' of Pressure Hose	CCTV inspection initiated.	1390788
14	11/18/2024	828 Cedarcroft Rd	21212	Rags, Roots, Trash	Dry	Chinquapin Run	1293	Sump pump discharging sewage water into the street.	1293	Pressure jet relieved blockage in mainline	Roots will be cut by contractor to prevent future sewer overflows	1390973
15	11/19/2024	613 S Paca St	21230	Rags, Roots	Dry	—	—	Wastewater observed near the cleanout	1	Relieved house connection choke with 45 ft electric cable	CCTV confirmed house connection is clear at this time	1391229
16	11/20/2024	1303 Orleans St	21202	Rags, Grease, Trash	Dry	Northwest Harbor	120	Subsurface SSO infiltrating storm drain system due to mainline choke.	12	Relieved mainline choke with 400 ft of pressure hose.	Confirmed mainline is clear at this time. CCTV will be performed.	1391996
17	11/21/2024	3900 Greenspring Ave	0	Rags, Grease	Wet	—	210	Grey water overflowing from manhole	630	Relieved mainline choke with pressure hose	CCTV inspection will be performed	1393335
18	11/22/2024	307 N Chapel Gate Ln	21229	Rags, Trash	Wet	Maidens Choice	4385	Wastewater observed overflowing from manhole	43850	Relieved mainline choke with 200 ft pressure hose	Confirmed that mainline is clear at this time. CCTV will be performed for next steps	1393418
19	11/23/2024	3701 Clarenell Rd	21229	Rags, Trash	Wet	Maidens Choice	85	Sewer water coming from manhole	1700	Relieved mainline choke with 200 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1394110
20	11/24/2024	2031 N Bentalou St	21216	Roots	Wet	—	130	Grey water overflowing from house connection in the rear	13	Ran 30' of electric cable with cutters to relieve choked house connection	CCTV inspection will be performed and reviewed	1394157

SSO Notification List

November 2024

21	11/27/2024	4101 Raspe Ave	21206	Rags, Other	Wet	Moores Run	212	Mainline choke causing wastewater to infiltrate the nearby subsurface storm drain.	53	Relieved mainline choke with 450 ft of pressure hose.	Performed mainline CCTV inspection.	1394761
				# WWO	12			TOTAL	49,049	UNDER 100 GALLONS	14	