

SSO Notification List

October 2020

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet-Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|--------------------|------------------------------|----------|--|------------------------------|-----------------|----------------|--|--------------------------------------|--|---|--------------|
| 1 | 10/1/2020 | 2661 Wilkens Ave | 21223 | Unknown | Wet | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 1 | Unable to service cleanout located in rear of property due to older-style trap. | Advised consumer to get a licensed plumber to replace cleanout and/or snake the line. | 884837 |
| 2 | 10/5/2020 | 6321 Green Meadow Pkwy | 21209 | Roots | Dry | N/A | 0 | Gray water observed around the cleanout at the front of property. | 3 | Relieved house connection choke with 45 ft of electric cable and various cutters due to heavy roots. | Performed CCTV inspection; confirmed lateral is clear. | 885307 |
| 3 | 10/7/2020 | 2015 Rayner Ave | 21217 | Roots | Dry | N/A | 0 | Gray water and debris observed around the cleanout. | 3 | Relieved house connection choke with 30 ft of electric cable. | Performed CCTV inspection; confirmed lateral is clear. | 886030 |
| 4 | 10/7/2020 | 211 Allendale St | 21229 | Roots, Grease | Dry | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 8 | Relieved house connection choke with 30 ft of electric cable. | Performed CCTV inspection; confirmed lateral is clear. | 885969 |
| 5 | 10/8/2020 | 2023 Etting St - Private | 21217 | Other | Dry | N/A | 0 | Gray water and paper observed at the rear of the property. | 4 | Ran 30 ft of electric cable through lateral; confirmed City side of pipe is clear. | Performed CCTV inspection and informed consumer to contact a private plumber. | 886137 |
| 6 | 10/9/2020 | 242 N Monroe St | 21223 | Rags, Roots, Grease, Trash | Dry | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 2 | Relieved house connection choke with 30 ft of electric cable. | Performed CCTV inspection; confirmed line is clear. | 886230 |
| 7 | 10/9/2020 | 203 N Central Ave | 21231 | Rags, Grease, Trash | Dry | Inner Harbor | 173 | Mainline choke causing subsurface wastewater infiltration into nearby storm drain. | 4,325 | Relieved mainline choke with 200 ft of pressure hose. | Confirmed mainline is clear; CCTV inspection will be performed. | 886228 |
| 8 | 10/9/2020 | 2411 Harriet Ave | 21230 | Sand, Gravel, Rocks, Structural | Dry | N/A | 0 | Gray water observed at the front of the property. | 2 | Ran 63 ft of electric cable through the lateral; some blockage remained. | CCTV inspection will be performed to determine the next steps. | 886280 |
| 9 | 10/10/2020 | 117 Beechdale Rd | 21210 | Rags, Roots, Trash | Dry | Jones Falls | 266 | Gray water escaping the manhole in at the front of the property. | 5,320 | Relieved mainline choke with 300 ft of pressure hose. | CCTV inspection will be performed; confirmed line is clear. | 886316 |
| 10 | 10/11/2020 | 1600 W 41st St | 21211 | Rags, Grease, Trash, Sand, Gravel, Rocks | Dry | Jones Falls | 121 | Heavy gray water escaping the manhole and entering nearby stream. | 9,680 | Relieved mainline choke with 150 ft of pressure hose and removed large rock. | CCTV inspection will be performed. | 886368 |
| 11 | 10/11/2020 | 3553 Newland Rd | 21218 | Rags, Roots, Trash | Dry | Jones Falls | 56 | Gray water escaping manhole at the front of the property. | 840 | Relieved mainline choke with 400 ft of pressure hose. | CCTV inspection will be performed. | 886360 |
| 12 | 10/12/2020 | 2119 McCullough St - Private | 21217 | Unknown | Wet | N/A | 0 | Gray water and debris observed at the rear of the property. | 1 | Ran electric cable through the lateral; no issues found on the City-side of pipe. | Informed consumer to contact a plumber to address internal problem. | 886430 |
| 13 | 10/12/2020 | 416 S Augusta Ave | 21229 | Rags, Trash | Wet | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 1 | Relieved house connection choke with 45 ft of electric cable. | Performed CCTV inspection; confirmed lateral is clear. | 886460 |
| 14 | 10/12/2020 | 2030 Eagle St | 21223 | Rags | Wet | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 1 | Relieved house connection choke with 45 ft of electric cable. | Performed CCTV inspection; confirmed lateral and mainline are clear. | 886436 |
| 15 | 10/13/2020 | 261 W 31st St | 21211 | Roots | Wet | N/A | 0 | Gray water observed at the rear of the property. | 2 | Relieved house connection choke with 30 ft of electric cable. | Performed CCTV inspection; confirmed lateral is clear. | 886536 |
| 16 | 10/16/2020 | 4300 Parkmont Ave | 21206 | Roots, Trash | Dry | N/A | 0 | Gray water and debris observed at the front of the property. | 1 | Relieved house connection choke with 45 ft of electric cable. | Performed CCTV inspection; confirmed lateral and mainline are clear. | 887857 |
| 17 | 10/16/2020 | 2001 W Cold Spring Ln | 21209 | Rags, Roots, Trash | Wet | N/A | 0 | Gray water observed around the manhole. | 10 | Relieved mainline choke with 100 ft of pressure hose. | Confirmed line is clear; CCTV inspection will be performed. | 887911 |
| 18 | 10/16/2020 | 3455 Wilkins Ave - Private | 21229 | Rags, Grease, Trash | Dry | N/A | 0 | Gray water observed around a private manhole in parking lot. | 2 | Relieved mainline choke with 300 ft of pressure hose. | Confirmed mainline is clear. | 887907 |
| 19 | 10/18/2020 | 1041 St Paul St | 21202 | Rags, Roots, Trash | Dry | N/A | 0 | Gray water observed around the cleanout at the side of the property. | 2 | Relieved house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 888053 |
| 20 | 10/19/2020 | 2814 Mohawk Ave | 21207 | Roots | Dry | N/A | 0 | Gray water observed around the cleanout at the front of the property. | 3 | Relieved house connection choke with 60 ft of electric cable. | Performed CCTV inspection; confirmed lateral is clear. | 888093 |
| 21 | 10/19/2020 | 1820 Spence St | 21230 | Rags, Trash | Dry | Gwynns Falls | 229 | Gray water escaping the manhole. | 458 | Relieved mainline choke with 300 ft of pressure hose. | Confirmed mainline is clear; CCTV inspection will be performed. | 888134 |

SSO Notification List

October 2020

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet-Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|--------------------|---------------------------------------|----------|---------------------------|------------------------------|-----------------|----------------|--|--------------------------------------|---|---|--------------|
| 22 | 10/19/2020 | 2135 N Smallwood St | 21217 | Rags, Trash | Dry | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 1 | Relieved house connection choke with 30 ft of electric cable. | Performed CCTV inspection; confirmed line is clear. | 888141 |
| 23 | 10/20/2020 | 609 Denison St | 21229 | Rags, Trash | Dry | N/A | 0 | Gray water observed at the rear of the property. | 1 | Relieved house connection choke with 75 ft of electric cable. | Confirmed lateral and mainline are clear. | 888294 |
| 24 | 10/20/2020 | 5015 Boxhill Ln | 21210 | Rags, Infiltration, Trash | Dry | N/A | 125 | Surcharged manhole infiltrating nearby storm drain. Found during routine sampling. | 13 | Relieved the choke using hand tools at location, and flushed the mainline. | Mainline was cleaned. CCTV inspection will be performed. | 888259 |
| 25 | 10/21/2020 | 4117 Massachusetts Ave | 21229 | Roots, Trash | Dry | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 1 | Relieved house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 888468 |
| 26 | 10/22/2020 | 1214 Homewood Ave | 21202 | Rags, Trash | Dry | N/A | 0 | Gray water observed around the cleanout. | 2 | Relieved house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 888586 |
| 27 | 10/22/2020 | 1633 N Milton Ave | 21213 | Rags | Dry | N/A | 0 | Gray water observed around the cleanout. | 2 | Relieved house connection choke with 15 ft of electric cable. | Performed CCTV inspection. | 888612 |
| 28 | 10/23/2020 | 5713 Edgepark Rd | 21239 | Rags, Grease, Trash | Dry | N/A | 0 | Gray water observed around the manhole. | 3 | Relieved mainline choke with 400 ft of pressure hose. | Confirmed line is clear. | 888874 |
| 29 | 10/24/2020 | 1611 Gwynns Falls Pkwy | 21217 | Rags, Trash, Unknown | Dry | Gwynns Falls | 0 | Gray water observed at the rear of the property. | 2 | Unable to service cleanout due to access issue. Flushed and cleaned 8" mainline with 200 ft of pressure hose. | Left door notice for consumer to install cleanout in accessible location. | 888966 |
| 30 | 10/25/2020 | 5616 Force Rd | 21206 | Rags, Trash | Dry | N/A | 0 | Gray water observed around the manhole. | 10 | Relieved mainline choke with 250 ft of pressure hose. | Confirmed line is clear. | 889052 |
| 31 | 10/26/2020 | 4617 Walter Ave | 21214 | Rags, Trash | Dry | Herring Run | 0 | Gray water observed around the sidewalk and storm drain. | 10 | Relieved mainline choke with 400 ft of pressure hose. | Confirmed line is clear. | 889206 |
| 32 | 10/26/2020 | 5616 Force Rd | 21206 | Rags, Grease, Trash | Dry | Moores Run | 347 | Gray water escaping the manhole. | 694 | Relieved mainline choke with 300 ft of pressure hose. | CCTV inspection will be performed. | 889240 |
| 33 | 10/27/2020 | 2803 Elgin Ave | 21216 | Rags, Grease, Trash | Dry | Gwynns Falls | 75 | Heavy gray water escaping the cleanout. | 225 | Relieved house connection choke with 100 ft of pressure hose. | Lateral CCTV inspection will be performed. | 889302 |
| 34 | 10/27/2020 | 240 S Kresson St | 21224 | Infiltration, Unknown | Dry | N/A | 0 | Gray water observed around the manhole. | 5 | Flushed and cleaned the mainline; no choke cause determined. | Further investigation will take place, including a CCTV inspection. | 889454 |
| 35 | 10/29/2020 | Saint Paul St & E Centre St | 21202 | Rags, Rain | Wet | N/A | 0 | Gray water observed around the manhole. | 7 | Relieved mainline choke with 45 ft of pressure hose. Replaced manhole cover. | Performed CCTV inspection; cleaned the mainline. | 889736 |
| 36 | 10/29/2020 | 1731 E Chase St | 21205 | Rain | Wet | Inner Harbor | 175 | Gray water escaping the manhole in the street. | 1,063,000 | Overflow subsided following heavy rain event. | Location is equipped with an Event Notification System meter. | 889738 |
| 37 | 10/29/2020 | 3900 Belair Rd | 21206 | Rain | Wet | Herring Run | 160 | Gray water escaping the manhole near the stream. | 1,030,000 | Overflow subsided following heavy rain event. | Capital improvement projects will reduce occurrences. | 889740 |
| 38 | 10/29/2020 | 2121 Wicomico St | 21230 | Rain | Wet | Gwynns Falls | 150 | Gray water escaping the manhole. | 55,000 | Overflow subsided following heavy rain event. | Future capital improvement projects will reduce occurrences. | 889732 |
| 39 | 10/29/2020 | 428 E Preston St - SSO Site #72 | 21202 | Rain | Wet | Jones Falls | 425 | Structure monitored by metering equipment in the pipe. Not visually observed. | 846,852 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 40 | 10/29/2020 | 1901 Falls Rd | 21218 | Rain | Wet | Jones Falls | 425 | Overflow discharging from a bypass pump construction pit due to heavy rain. | 1,150,000 | Overflow subsided following heavy rain event. | Capital improvement projects are being implemented to prevent this overflow from reoccurring. | |
| 41 | 10/29/2020 | 1901 Falls Rd - Streetcar Museum Site | 21218 | Rain | Wet | Jones Falls | 425 | Overflowing manhole due to heavy rain. | 470,000 | Overflow subsided following heavy rain event. | CIP projects are being implemented to prevent this overflow from reoccurring. | |
| | | | | # WWO | 12 | | | TOTAL | 4,636,489 | UNDER 100 GALLONS | 25 | |