

SSO Notification List

October 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	10/5/2021	2912 Keswick Rd	21211	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and confirmed the line is clear.	978755
2	10/6/2021	5070 Wabash Ave	21215	Unknown	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran 90 ft of electric cable through the lateral.	Left notice that cleanout is installed too far from property line to have work fully performed.	979164
3	10/9/2021	2860 Lake Ave	21213	Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is clear.	979704
4	10/12/2021	1727 E 33rd St	21218	Rags, Roots	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is clear.	980031
5	10/13/2021	4009 Elderon Ave	21215	Rags, Trash	Dry	N/A	0	Heavy gray water observed at the front of the property.	2	Relieved house connection choke with electric cable.	Spoke with consumer; confirmed mainline and lateral are clear.	980221
6	10/13/2021	4800 Roland Ave	21210	Rags, Grease, Trash	Dry	Jones Falls	689	Gray water escaping the manhole in the street.	689	Relieved mainline choke with 300 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is now clear.	980364
7	10/14/2021	Ashland Ct & Stirling St	21202	Rags, Roots, Grease	Dry	N/A	0	Gray water observed in the street near manhole.	2	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to ensure line is clear.	980486
8	10/14/2021	323 S Washington St	21231	Rags, Grease	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection confirmed the lateral is now clear.	980598
9	10/16/2021	400 E 22 1/2 St	21218	Rags, Grease, Trash	Wet	Jones Falls	225	Gray water entering nearby storm drain.	225	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear at this time; CCTV inspection will be performed.	981058
10	10/18/2021	3030 Poplar Terr	21216	Roots, Trash	Wet	Gwynns Falls	216	Gray water escaping the cleanout at the rear of the property.	108	Relieved house connection choke with 45 ft of electric cable.	Confirmed that the lateral and mainline are both clear at this time.	981293
11	10/19/2021	4800 Falls Rd	21210	Rags, Grease, Structural	Wet	Jones Falls	148	Heavy gray water escaping the manhole and entering nearby stream.	3,700	Relieved mainline choke with 150 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	981381
12	10/21/2021	1032 Wedgewood Rd	21229	Rags, Grease, Trash	Dry	Gwynns Falls	179	Manhole overflowing and sewage entering nearby storm drain.	895	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	985624
13	10/21/2021	3820 Fernhill Ave	21215	Roots, Grease	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV found sewer lateral is clear.	985677
14	10/21/2021	5246 Harford Rd	21214	Rags, Grease	Dry	N/A	0	Gray water and debris observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are clear at this time.	987280
15	10/23/2021	2040 Linden Ave	21217	Rags	Dry	N/A	0	Gray water and paper observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Advised consumer not to flush sanitary wipes down the drain.	987554
16	10/25/2021	4119 Roland Ave	21211	Rags, Grease, Trash	Dry	N/A	0	Heavy gray water observed around the manhole.	2	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is now clear. CCTV inspection will be performed.	987818
17	10/25/2021	2219 Madison Ave	21217	Rags, Grease	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear. Advised consumer to have plumber inspect their side of the pipe.	987837
18	10/25/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	25	Structure monitored by metering equipment in the pipe. Not visually observed.	2,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
19	10/25/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	165	Structure monitored by metering equipment in the pipe. Not visually observed.	444,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
20	10/25/2021	3900 Belair Rd	21206	Rain	Wet	Herring Run	65	Manhole adjacent to creek overflowed due to heavy rain.	89,000	Overflow subsided following heavy rain event.	SSOs will be prevented here after completion of capital improvement projects.	

SSO Notification List

October 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	10/26/2021	2931 Whittington Ave	21230	Rags	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection to confirm the line is now clear.	988009
22	10/26/2021	1805 Park Ave	21217	Rags, Grease, Trash	Wet	Jones Falls	630	Gray water escaping the manhole in the street.	630	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is now clear and flowing freely.	988206
23	10/26/2021	221 E 33rd St	21218	Unknown	Wet	N/A	0	Gray water observed at the front of the property.	1	Spoke with consumer to have cleanout cap removed in order to perform work.	Electric cable will be run through the lateral once access is granted.	988222
24	10/27/2021	542 N Payson St	21223	Trash, Unknown	Wet	N/A	0	Gray water observed at the rear of the property.	1	Advised consumer to replace older-style cleanout trap so that work can be performed.	Checked the mainline to confirm it is flowing freely.	988248
25	10/28/2021	200 Deepdene Rd	21210	Rags, Roots, Trash	Wet	Jones Falls	167	Heavy gray water escaping the mainline.	2,505	Relieved mainline choke with 50 ft of pressure hose.	Confirmed the mainline is now clear; CCTV inspection will be performed.	988531
26	10/29/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	515	Structure monitored by metering equipment in the pipe. Not visually observed.	3,983,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
27	10/29/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	245	Structure monitored by metering equipment in the pipe. Not visually observed.	1,248,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	
28	10/29/2021	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Gwynns Falls	65	Structure monitored by metered equipment in the pipe. Not visually observed.	7,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
29	10/29/2021	1200 N Franklinton Rd	21216	Rain	Wet	Gwynns Falls	40	Heavy gray water escaping the manhole.	1,000	Overflow subsided following heavy rain event.	Capital improvement projects are being implemented to prevent this overflow from reoccurring.	988970
30	10/29/2021	3900 Belair Rd	21206	Rain	Wet	Herring Run	375	Manhole adjacent to creek overflowed due to heavy rain.	700,000	Overflow subsided following heavy rain event. Location is equipped with an ENS meter.	SSOs will be prevented at this location after completion of capital improvement projects.	
31	10/30/2021	422 N Streeper St	21224	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the line is now clear.	989030
32	10/30/2021	4100 Alto Rd	21216	Rags	Wet	N/A	0	Heavy gray water and rags observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed both the lateral and mainline are clear at this time.	989032
33	10/31/2021	1910 Eastern Ave	21231	Rags, Trash	Wet	N/A	0	Gray water observed on the sidewalk at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is now clear.	989055
				# WWO	19			TOTAL	6,482,775	UNDER 100 GALLONS	18	