

SSO Notification List

October 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	10/2/2022	3828 W Bay Ave	21225	Grease, Sand, Gravel, Rocks, Structural	Wet	N/A	—	Gray water observed around the manhole and street.	10	Flushed 8" mainline with pressure hose; determined structural damage exists.	Pipe will be repaired to restore line to regular functionality.	1143555
2	10/4/2022	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	210	Structure monitored by metering equipment in the pipe. Not visually observed.	653,100	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
3	10/4/2022	1901 Falls Rd - SSO Site #67	21217	Rain	Wet	Jones Falls	75	Structure monitored by metering equipment in the pipe. Not visually observed.	30,000	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
4	10/6/2022	1701 Sulgrave Ave	21209	Rags, Trash	Wet	N/A	—	Mainline choke causing discharge from cleanout.	1	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is clear at this time.	1144813
5	10/6/2022	4215 Belmar Ave	21206	Rags, Trash	Wet	N/A	—	Gray water observed around the manhole.	3	Relieved mainline choke with 400 ft of pressure hose.	Confirmed the mainline is now clear.	1144807
6	10/11/2022	2808 Keyworth Ave	21215	Roots, Trash	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is now clear.	1145598
7	10/12/2022	3202 W North Ave	21216	Rags, Roots, Trash	Dry	Gwynns Falls	67	Mainline choke causing subsurface SSO and infiltrating the nearby storm drain system.	335	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	1145807
8	10/13/2022	321 S Augusta Ave	21229	Structural	Wet	N/A	—	Gray water observed around the cleanout.	1	Ran 15 ft of electric cable through the lateral; issue remained.	Further investigation, including lateral launch, will take place to determine next steps.	1146165
9	10/14/2022	3901 Curtis Ave	21226	Structural	Dry	N/A	135360	Sanitary sewer is leaking into storm drain subsurface.	13,536	Contractor lined the pipe to stop the subsurface overflow.	Regular functionality has been restored to the system at this location.	1146490
10	10/15/2022	2017 W Baltimore St	21223	Rags, Grease	Wet	N/A	200	Gray water slowly escaping the cleanout at the rear of the property.	2	Relieved house connection choke with electric cable.	Performed lateral CCTV inspection.	1146656
11	10/17/2022	1011 W 37th St	21211	Rags	Dry	N/A	—	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is now clear at this time.	1147026
12	10/18/2022	2663 W Lafayette Ave	21216	Rags, Rain, Sand, Gravel, Rocks	Dry	Gwynns Falls	48	Mainline choke causing sewage to enter storm drain subsurface.	480	Relieved 8" mainline choke with 200 ft of pressure hose.	Abatement confirmed via the Office of Compliance and Research.	1147286
13	10/19/2022	4720 York Rd	21212	Structural	Dry	Tiffany Run	89390	Sanitary sewer infiltrating the storm drain subsurface.	8,939	Contractor lined the pipe to stop the overflow.	Normal flow has returned to the system at this location.	1147690
14	10/25/2022	400 E 22nd St	21218	Rags, Roots, Grease, Trash	Wet	Jones Falls	—	Gray water observed around the manhole and storm drain.	10	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now clear; CCTV inspection will be performed.	1149727
15	10/26/2022	6802 Gough St	21224	Rags, Grease, Trash	Dry	Inner Harbor	705	Heavy gray water escaping the manhole and entering storm drain.	1,410	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed the mainline is clear; CCTV inspection will be performed.	1150092
16	10/28/2022	732 E 35th St	21218	Rags, Roots	Dry	Jones Falls	44	Gray water escaping the cleanout at the front of the property.	22	Relieved house connection choke with 30 ft of electric cable.	Location placed on routine root control. Advised resident to not flush sanitary wipes.	1150628
17	10/29/2022	202 S Athol Ave	21229	Rags, Roots, Grease, Trash	Dry	N/A	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Lateral CCTV inspection will be performed; mainline was cleaned.	1150724
				# WWO	8			TOTAL	707,852	UNDER 100 GALLONS	10	