

SSO Notification List												
October 2025												
Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	10/2/2025	1901 Chesapeake Ave	21226	Rags	Dry	—	—	Observed wastewater coming from front house connection	1	Relieved house connection choke with 120 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1483439
2	10/6/2025	1021 Winding Way	21210	Rags, Roots, Grease	Dry	—	—	Observed wastewater coming from manhole	1	Relieved mainline choke flushed and cleaned to stop the overflow	CCTV will be performed after completion of ongoing work.	1484484
3	10/7/2025	6309 Eunice Way	21214	Rags, Trash	Dry	Herring Run	297	Mainline choked with rags and debris causing wastewater to infiltrate into the storm drain	297	Relieved choked mainline using 300' of pressure hose	CCTV Inspection will be performed	1484822
4	10/10/2025	3307 Taney Rd	21215	Rags	Wet	—	—	Observed wastewater at front house connection	1	Relieved house connection choke with 60 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1485705
5	10/12/2025	2418 Baker St	21216	Rags, Trash	Wet	—	—	Wastewater with rags and debris	5	Relieved choke with pressure truck	CCTV Inspection scheduled	1485889
6	10/16/2025	1708 W Rogers Ave	21209	Rags, Trash	Wet	Jones Falls	376	Wastewater with rags and debris	1880	Relieved choke using pressure truck	CCTV Inspection performed	1486570.00
7	10/17/2025	2437 Madison Ave	21217	Rags, Roots, Trash	Dry	—	—	Wastewater with rags, roots and trash	2	Relieved choke using electric cable and saw tooth	CCTV Inspection will be performed	1487096
8	10/19/2025	5118 Norwood Rd	21212	Rags, Roots	Dry	—	90	Observed wastewater coming from front house connection	90	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1487216
9	10/20/2025	2504 Marbourne Ave	21230	Rags, Roots	Wet	—	112	Observed wastewater coming from front house connection	112	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1487385
10	10/20/2025	2209 W North Ave	21216	Rags	Wet	—	—	Observed wastewater at rear house connection	1	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1487535
11	10/21/2025	713 Cooks Ln	21229	Rags, Trash	Wet	—	—	Observed wastewater coming from rear house connection	4	Relieved house connection choke with 45 ft electric cable.	Confirmed house connection is clear at this time. CCTV was performed	1487919
12	10/23/2025	227 Chancery Rd	21218	Rags, Trash	Dry	Jones Falls	111	Mainline choke causing wastewater to infiltrate nearby storm drain	55.5	Relieved mainline choke with 250 ft pressure hose	Confirmed mainline is clear at this time. CCTV will be performed	1488320
13	10/24/2025	3013 Westfield Ave	21214	Rags, Grease, Trash	Dry	Herring Run	241	Sewer mainline choke causing wastewater to infiltrate storm drain	60.25	Relieved mainline choke with 450 ft pressure hose	Confirmed mainline is clear at this time. Referred for CCTV	1488685
14	10/25/2025	1275 Park Ave	21217	Roots	Dry	—	—	Wastewater with roots	0.5	Relieved choke using 60 ft of electric cable with spearhead cutter	CCTV Inspection will be performed	1488778
15	10/26/2025	2717 Hollins Ferry Rd	21230	Trash	Dry	—	—	Wastewater with trash	0.5	Inspected using utility location device for assessment.	None	1488873
16	10/27/2025	3612 Hickory Ave	21211	Roots	Dry	—	—	Observed wastewater at rear house connection	1	Relieved house connection choke with 30 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1488933
17	10/27/2025	3506 Seven Mile Lane	21208	Rags, Roots, Trash	Dry	—	—	Wastewater with rags, roots and debris	1	Relieved choke using electric cable with expander cutters	CCTV Inspection will be performed	1489156
18	10/29/2025	304 Broadmoor Rd	21212	Grease, Sand, Gravel, Rocks	Dry	Stony Run	679	Mainline choke caused by broken pipe overflowing into adjacent storm pipe.	2037	Unable to relieve mainline choke. Sewer manhole level pump down and bypass pumping was installed instead.	Bypass Pumping was installed to stop the SSO, and location turned over to contractor for repair.	1489096
19	10/29/2025	3647 Park Heights Ave	21215	Rags	Dry	—	—	Observed wastewater coming from rear house connection	1	Relieved house connection choke with 45 ft electric cable	Confirmed house connection is clear at this time. CCTV was performed	1489657
20	10/30/2025	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	135	Manhole structure overflowed due to heavy rain.	152010	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
				# WWO	7			TOTAL	156,561	UNDER 100 GALLONS	15	