

## SSO Notification List

April 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/1/2017	301 Scott St	21230	Rags	Wet		0	Gray water observed around cleanout at the rear of the property.	8	Relieved 6" house connection choke with 30 ft of electric cable and h-cutter.	House lateral CCTV inspection performed.	398717
2	4/1/2017	1063 Cameron Rd (Private)	21212	Rags, Roots, Trash	Wet		0	Grey water observed around manhole of mainline.	12	Relieved 8" mainline choke with 100 ft of pressure hose to remove rags, roots, and debris.	Performed mainline CCTV inspection.	398786
3	4/2/2017	3322 James St	21230	Rags, Roots	Wet		83	Water flowing from the cleanout.	83	Relieved house connection choke with 300 ft of pressure machine.	Performed CCTV inspection and cleaned the mainline.	398872
4	4/2/2017	2202 E Fairmount Ave	21231	Roots	Wet		0	Gray water on the sidewalk near the cleanout.	10	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Performed CCTV inspection.	398886
5	4/3/2017	1020 N Payson St	21217	Rags	Wet		0	Heavy gray water near the cleanout at the rear of the property.	11	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	398952
6	4/3/2017	5600 Roxbury Pl	2120	Structural	Wet	Jones Falls	14,342	Water leaking from crack in the pipe.	1,147	The section of broken pipe was replaced by contractor and a new one was installed.	Performed CCTV inspection.	399016
7	4/3/2017	1910 Ramblewood Rd	21239	Rags, Grease, Trash	Wet		316	Toilet paper and debris observed at the cleanout in the front of the property.	316	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection and cleaned the mainline.	399115
8	4/4/2017	619 N Calhoun St	21217	Rags	Wet		0	Heavy gray water observed near cleanout.	10	Relieved 6" house connection choke with 30 ft of electric cable and h-cutter.	Performed house lateral CCTV inspection.	399319
9	4/5/2017	600 W Patapsco Ave	21225	Rags, Grease, Trash	Wet		232	Water coming out of the manhole.	464	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	399777
10	4/6/2017	N Charles St & W Lanvale St - SSO #152	21202	Rain	Wet	Jones Falls	175	Structure monitored by metering equipment in the pipe.	134,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
11	4/6/2017	W Garrison Ave & Queensberry Rd - SSO #139	21215	Rain	Wet	Jones Falls	110	Structure monitored by metering equipment in the pipe.	73,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
12	4/6/2017	1901 Falls Rd - SSO #67	21218	Rain	Wet	Jones Falls	310	Structure monitored by metering equipment in the pipe.	745,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
13	4/6/2017	428 E Preston St - SSO #72	21202	Rain	Wet	Jones Falls	455	Structure monitored by metering equipment in the pipe.	2,158,000	SSO structure; not applicable.	The SSO will be closed upon completion of necessary capital project.	
14	4/7/2017	2780 Wilkens Ave	21223	Rags, Trash	Wet		0	Gray water observed around dislodged manhole cover.	2	Reset manhole cover in place.	Performed CCTV inspection.	400206
15	4/8/2017	424 Font Hill Ave	21223	Rags, Grease, Trash	Wet		90	Gray water observed overflowing from manhole.	270	Relieved 8" mainline choke with 275 ft of pressure hose.	Mainline CCTV inspection will be performed.	400292
16	4/8/2017	W Franklin St & N Payson St	21223	Rags, Trash	Wet		0	Gray water and debris observed around manhole.	12	Relieved 8" mainline choke with 200 ft of pressure hose.	Mainline CCTV inspection will be performed.	400369
17	4/9/2017	2700 Rittenhouse Ave	21230	Rags	Wet		0	Gray water observed around cleanout.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	400462
18	4/10/2017	6303 Lincoln Ave	21209	Rags, Roots	Dry		146	Water flowing out of the cleanout at the front of the property.	146	Relieved 6" house connection choke with 45 ft of electric cables and expander.	Performed house lateral CCTV inspection.	400754
19	4/10/2017	3404 Mueller St	21224	Rags, Trash	Dry		0	Water observed around the manhole.	18	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	400782

## SSO Notification List

April 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	4/10/2017	1126 Shields Pl	21201	Rags	Dry		0	Heavy gray water around the cleanout at the rear of the property.	11	Relieved 6" house connection choke with 30 ft of electric cables and washed the area.	Performed house lateral CCTV inspection and cleaned the mainline.	400509
21	4/11/2017	Edmondson Ave & Hilton Pkwy	21229	Rags, Grease, Trash	Dry	Gwynns Falls	137	Manhole overflowing into the street.	3,425	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	401057
22	4/11/2017	3801 Greenmount Ave	21218	Roots, Trash	Dry		0	Gray water around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable and H-cutter.	Performed CCTV inspection and cleaned the mainline.	401102
23	4/12/2017	3222 Lyndale Ave	21213	Rags, Roots	Dry		0	Gray water around the cleanout at the front of the property.	12	Relieved house connection choke with 45 ft of electric cable and H-cutter.	Performed CCTV inspection and took a sample from meter vault for lab testing.	410229
24	4/12/2017	6104 Ivymount Rd	21209	Roots, Grease, Vandalism	Dry		899	Heavy gray water escaping the manhole into the street.	1,798	Relieved 8" mainline choke with 175 ft of pressure hose.	Performed mainline CCTV inspection.	401392
25	4/13/2017	4803 Lindsay Rd	21229	Roots, Grease, Trash	Dry		0	Gray water observed around the cleanout at the front of the property.	5	Relieved 6" house connection choke with 45 ft of electric cable and H-cutter.	Performed house lateral CCTV inspection.	401544
26	4/14/2017	3025 Oakley Ave	21215	Rags, Roots, Trash	Dry		11	Water coming out of the cleanout at the rear of the property.	11	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Performed CCTV inspection.	401652
27	4/15/2017	2725 Jefferson St	21224	Rags, Trash	Wet		97	Heavy gray water at the cleanout in the rear of the property.	194	Relieved 6" house connection choke with 5 ft of rods.	Washed down the area with hose.	401694
28	4/18/2017	2800 Forest View Ave	21214	Rags, Roots	Wet		0	Water observed around the cleanout at the front of the property.	15	Ran 60 ft of electric cable with H-cutter. House connection repair was needed and completed.	Performed CCTV inspection.	402332
29	4/18/2017	604 Venable Ave	21218	Sand, Gravel, Rocks, Structural	Wet		92	Gray water coming from the cleanout at the rear of the property.	92	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Performed house lateral CCTV inspection.	402340
30	4/21/2017	6303 Clearspring Rd	21212	Rags, Roots, Trash	Wet		0	Dampness in the area around the cleanout and mainline.	20	Relieved 8" mainline choke with 250 ft of pressure hose, and relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspections and cleaned the house connection.	403047
31	4/21/2017	2429 Ashland Ave	21205	Rags, Trash, Sand, Gravel, Rocks	Wet		0	Gray water in the alleyway behind the property.	35	Relieved 8" mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection.	402903
32	4/21/2017	E Cold Spring Ln & Old York Rd	21212	Rags, Grease	Wet	Herring Run	93	Gray water overflowing from the manhole.	465	Relieved 8" mainline choke with 50 ft of pressure hose.	Performed mainline CCTV inspection.	402941
33	4/24/2017	3705 Everett St	21225	Rags, Grease, Trash	Wet		140	Heavy gray water running from a manhole into the street.	420	Relieved 8" mainline choke with 25 ft of pressure hose.	Performed mainline CCTV inspection.	403373
34	4/25/2017	4611 Briarclift Rd	21229	Rags, Roots, Trash	Wet		56	Heavy gray water overflowing from manhole.	1,400	Relieved 12" mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection.	403757
35	4/25/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	Wet	Jones Falls	25	Structure discharges to a storm drain and is monitored by metering equipment in the pipe. Not visually observed.	413	SSO Structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
36	4/26/2017	2829 Presstman St	21216	Rags, Trash, Sand, Gravel, Rocks	Wet		0	Gray water near the terminal manhole at the side of the property.	2	Relieved 6" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	403919
37	4/26/2017	N Smallwood St & Presstman St	21216	Rags, Trash, Sand, Gravel, Rocks	Wet		0	Heavy gray water observed around the manhole and the sidewalk.	6	Relieved 8" mainline choke with 60 ft of pressure hose.	Performed mainline CCTV inspection.	403897
38	4/27/2017	2733 Rayner Ave	21216	Rags, Grease, Trash	Wet		0	Heavy gray water observed around the manhole.	12	Relieved 10" mainline choke with 100 ft of pressure hose.	Cleaned the mainline and performed a CCTV inspection.	404139
39	4/29/2017	202 Longwood Rd (Private)	21210	Rags, Roots, Grease, Trash	Dry		279	Murky colored water overflowing from cleanout at the rear of the property.	1,395	Ran 175 ft of electric cable and H-cutter at private house connection. Flushed and cleaned City 8" mainline using 400 ft of pressure hose.	Performed CCTV inspection and washed the area.	404641
				# WWO	37			TOTAL	3,122,149	UNDER 100 GALLONS	20	