

SSO Notification List

APRIL 2018

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet-Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|--------------------|---------------------|----------|----------------------------|------------------------------|-----------------|----------------|---|--------------------------------------|--|--|--------------|
| 1 | 4/2/2018 | 1745 E Preston St | 21213 | Trash, Structural | Dry | N/A | 0 | Gray water observed at the rear of the property. | 4 | Ran 15 ft of electric cable and performed CCTV inspection. | Pipe is already scheduled for repair. | 536890 |
| 2 | 4/3/2018 | 1831 W Saratoga St | 21223 | Rags, Grease, Trash | Dry | N/A | 0 | Gray water observed at the rear of the property. | 40 | Relieved 8" mainline choke with 300 ft of pressure hose. | Performed mainline CCTV inspection; flushed 6" house connection. | 537179 |
| 3 | 4/5/2018 | 1703 Sulgrave Ave | 21209 | Rags, Trash | Dry | N/A | 0 | Gray water and debris observed around the cleanout at the front of the property. | 7 | Relieved 6" house connection choke with 30 ft of electric cable. | Flushed and cleaned 2 sections of 10" mainline; confirmed clear. | 537553 |
| 4 | 4/5/2018 | 5503 Peerless Ave | 21207 | Roots, Trash | Dry | N/A | 0 | Heavy gray water observed around the cleanout. | 7 | Relieved 6" house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 537736 |
| 5 | 4/5/2018 | 1001 Arion Park Rd | 21229 | Rags, Roots, Trash | Dry | N/A | 98 | Heavy gray water escaping the manhole. | 490 | Relieved 8" mainline choke with 275 ft of pressure hose. | Performed mainline CCTV inspection. | 537726 |
| 6 | 4/5/2018 | 4121 Falls Rd | 21211 | Rags, Roots | Dry | N/A | 0 | Dampness observed around cleanout at the front of the property. | 4 | Relieved house connection choke with 35 ft of electric cable. | Flushed and cleaned 8" mainline. | 537805 |
| 7 | 4/5/2018 | 4300 Hayward Ave | 21215 | Rags, Trash | Dry | N/A | 0 | Gray water surrounding the manhole. | 15 | Relieved 8" mainline choke with 250 ft of pressure hose. | Performed mainline CCTV inspection. | 537842 |
| 8 | 4/9/2018 | 3128 Northway Dr | 21234 | Trash | Dry | N/A | 0 | Gray water and debris observed around the cleanout. | 4 | Relieved house connection choke with 30 ft of electric cable. | Performed house lateral CCTV inspection. | 538341 |
| 9 | 4/9/2018 | 300 N Hilton St | 21229 | Rags, Roots, Trash | Dry | N/A | 89 | Gray water escaping manhole. | 890 | Flushed and cleaned 10" mainline with 500 ft of pressure hose. | Confirmed choke is relieved and mainline clear. | 538605 |
| 10 | 4/10/2018 | 3300 The Alameda | 21218 | Rags, Roots, Trash | Dry | N/A | 0 | Water observed near the cleanout. | 7 | Relieved house connection choke with 60 ft of electric cable. | Confirmed lateral and mainline are clear. | 538740 |
| 11 | 4/10/2018 | 3906 Maine Ave | 21207 | Rags, Roots | Dry | N/A | 324 | Heavy gray water escaping the cleanout at the rear of the property. | 648 | Relieved house connection choke with 60 ft of electric cable. | Flushed and cleaned 8" mainline; left door notice for plumber. | 538959 |
| 12 | 4/11/2018 | 3601 Keystone Ave | 21211 | Rags, Trash | Dry | Jones Falls | 252 | Dye test confirms wastewater is entering the storm drain system and conduit vaults underground. Found as a result of OCAL routine monitoring. | 756 | Relieved 8" mainline choke with 200 ft of pressure hose. | Confirmed mainline is clear. | 539044 |
| 13 | 4/11/2018 | 59 N Catherine St | 21223 | Rags, Grease, Trash | Dry | N/A | 131 | Heavy gray water escaping manhole in alleyway. | 393 | Relieved 8" mainline choke with 250 ft of pressure hose. | Performed mainline CCTV inspection. | 539121 |
| 14 | 4/12/2018 | 1901 Chesapeake Ave | 21226 | Rags, Trash | Dry | N/A | 433 | Gray water escaping cleanout. | 217 | Relieved house connection choke with 55 ft of electric cable. | Cleaned 10" mainline. | 539584 |
| 15 | 4/13/2018 | 4022 Pulaski Hwy | 21224 | Rags, Grease, Trash | Dry | Harbor | 50 | Colored water overflowing from cleanout at the front of the property. | 50 | Relieved house connection choke with 30 ft of electric cable. | Confirmed connection and mainline are clear. | 539666 |
| 16 | 4/13/2018 | 1822 N Payson St | 21217 | Rags, Trash | Dry | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 4 | Relieved 6" house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 539678 |
| 17 | 4/13/2018 | 2213 Roslyn Ave | 21216 | Rags, Roots, Grease, Trash | Dry | N/A | 0 | Heavy gray water and debris observed around the cleanout. | 6 | Relieved house connection choke with 60 ft of electric cable. | Confirmed lateral is clear; cleaned mainline. | 539687 |
| 18 | 4/13/2018 | 1831 W Saratoga St | 21223 | Rags, Trash | Dry | N/A | 0 | Gray water observed near the cleanout and alley. | 20 | Relieved choke with 120 ft of pressure hose. | Confirmed mainline is clear; left plumber notice for issue on consumer side. | 538839 |
| 19 | 4/13/2018 | 3302 The Alameda | 21218 | Rags, Roots, Trash | Dry | N/A | 0 | Water observed around the cleanout. | 8 | Relieved house connection choke with 90 ft of electric cable. | Confirmed lateral is clear; left notice to install closer cleanout. | 539808 |

SSO Notification List

APRIL 2018

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet-Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|--------------------|---|----------|----------------------------|------------------------------|-----------------|----------------|---|--------------------------------------|---|--|--------------|
| 20 | 4/14/2018 | 1806 Druid Hill Ave | 21217 | Rags, Trash | Dry | N/A | 0 | Dampness observed around the cleanout. | 5 | Relieved house connection choke with 30 ft of electric cable. | Flushed and cleaned 12" mainline; confirmed lateral and mainline are clear. | 539860 |
| 21 | 4/16/2018 | 1901 Falls Rd - SSO Site #67 | 21217 | Rain | Wet | Jones Falls | 250 | Structure monitored by metering equipment in the pipe. | 402,000 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 22 | 4/16/2018 | 428 E Preston St - SSO Site #72 | 21202 | Rain | Wet | Jones Falls | 380 | Structure monitored by metering equipment in the pipe. Not visually observed. | 3,707,000 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 23 | 4/16/2018 | N Charles St & W Lanvale St - SSO Site #152 | 21202 | Rain | Wet | Jones Falls | 30 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 4,000 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 24 | 4/16/2018 | E 32nd St & St Paul St - SSO Site #157 | 21218 | Rain | Wet | Jones Falls | 15 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 2,500 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 25 | 4/18/2018 | 3316 Bancroft Rd | 21215 | Rags, Roots, Structural | Dry | N/A | 0 | Sanitary pipe leaking into adjacent storm drain pipe. | 0 | Flushed mainline with 300 ft of pressure hose. Performed CCTV inspection on mainline and storm drain. | Scheduled for repair to address structural damage to pipe. | 540898 |
| 26 | 4/18/2018 | 3004 Gibbons Ave | 21214 | Structural | Wet | Herring Run | 1773 | Choked and damaged mainline found through routine sampling. | 8,865 | Repaired damage to the mainline. | Office of Compliance and Laboratories performed test to confirm abatement. | 540914 |
| 27 | 4/18/2018 | 1609 Gwynns Falls Pkwy | 21217 | Rags, Grease, Trash | Wet | N/A | 0 | Heavy gray water observed at the rear of the property. | 4 | Relieved house connection choke with 45 ft of electric cable. | Confirmed choke is relieved; cleaned mainline. | 540987 |
| 28 | 4/18/2018 | 508 E Preston St | 21202 | Structural, Other | Wet | N/A | 0 | Sewage was overflowing from manhole due to bypass pump mechanical failure. | 300 | Bypass pump was repaired. | Proper maintenance measurements have been established to prevent bypass pump from re-breaking again. | |
| 29 | 4/19/2018 | 1516 E Biddle St | 21213 | Rags, Grease, Trash | Wet | N/A | 0 | Gray water and debris observed around the cleanout at the rear of the property. | 6 | Relieved house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 541086 |
| 30 | 4/19/2018 | 3408 Keene Ave | 21214 | Rags, Roots, Trash | Dry | N/A | 0 | Dampness observed around the cleanout at the front of the property. | 3 | Relieved house connection choke with 45 ft of electric cable. | Performed house lateral CCTV inspection. | 541334 |
| 31 | 4/22/2018 | 2202 Linden Ave | 21217 | Rags, Grease | Dry | N/A | 0 | Gray water observed near the manhole and alley. | 60 | Relieved 8" mainline choke with 200 ft of pressure hose. | Performed mainline CCTV inspection. | 541730 |
| 32 | 4/22/2018 | 4319 Walther Ave | 21214 | Rags, Roots | Dry | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 4 | Relieved house connection choke with 30 ft of electric cable. | Confirmed connection is clear; flushed and cleaned 8" mainline. | 541739 |
| 33 | 4/22/2018 | 25 N Caroline St | 21231 | Grease, Trash | Dry | N/A | 85 | Gray water and debris escaping cleanout on the sidewalk. | 9 | Relieved house connection choke with 45 ft of electric cable. | Performed house lateral CCTV inspection, confirmed connection is clear. | 541762 |
| 34 | 4/24/2018 | 2304 Tioga Pkwy | 21215 | Rags, Grease | Dry | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 6 | Relieved house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 545695 |
| 35 | 4/25/2018 | 4014 Linkwood Rd | 21210 | Rags, Roots, Rain | Wet | N/A | 0 | Heavy gray water observed around the manhole in parking lot. | 60 | Relieved 8" mainline choke with 250 ft of pressure hose. | Confirmed mainline is clear. | 547911 |
| 36 | 4/25/2018 | 1503 Hazel St | 21226 | Trash, Sand, Gravel, Rocks | Wet | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 5 | Relieved house connection choke with 30 ft of electric cable. | Left notice for plumber to repair bottom of cleanout. | 548013 |
| 37 | 4/26/2018 | 3405 Holmes Ave | 21217 | Rags, Grease, Trash | Wet | N/A | 0 | Heavy gray water observed around the cleanout at the rear of the property. | 7 | Relieved 6" house connection choke with 30 ft of electric cable. | Confirmed lateral and mainline are clear. | 548206 |
| 38 | 4/26/2018 | Linnard St & Gelston Dr | 21229 | Rags, Grease, Trash | Wet | N/A | 134 | Gray water escaping the manhole in the street. | 268 | Relieved 8" mainline choke with 200 ft of pressure hose. | Performed mainline CCTV inspection. | 548487 |
| 39 | 4/27/2018 | 513 W Mulberry St | 21201 | Rags, Trash | Wet | N/A | 0 | Heavy gray water observed around the cleanout. | 7 | Relieved 6" house connection choke with 75 ft of electric cable. | Confirmed lateral and mainline are clear. | 548729 |
| 40 | 4/30/2018 | 247 N Bruce St | 21223 | Rags | Wet | N/A | 0 | Gray water observed around the cleanout at the rear of the property. | 5 | Relieved 6" house connection choke with 45 ft of electric cable. | Confirmed lateral is clear; performed mainline CCTV inspection. | 549076 |

SSO Notification List

APRIL 2018

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet-Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|--------------------|--------------------|----------|-------------------------|------------------------------|-----------------|----------------|--|--------------------------------------|--|---|--------------|
| 41 | 4/30/2018 | 2711 Round Rd | 21225 | Rags | Wet | N/A | 0 | Heavy gray water observed around the cleanout at the rear of the property. | 6 | Relieved 6" house connection choke with 45 ft of electric cable. | Confirmed lateral is clear. | 549093 |
| 42 | 4/30/2018 | 222 N Calverton Rd | 21223 | Rags, Trash, Structural | Wet | N/A | 227 | Heavy gray water escaping manhole. | 454 | Relieved 8" mainline choke with 100 ft of pressure hose. | Performed CCTV inspection; scheduled pipe repair. | 549027 |
| 43 | 4/30/2018 | 5615 York Rd | 21212 | Rags, Grease, Trash | Wet | N/A | 0 | Gray water escaping cleanout. | 15 | Relieved house connection choke with 60 ft of electric cable. | Confirmed lateral is clear. | 549167 |
| | | | | | | | | | | | | |
| | | | | # WWO | 17 | | | TOTAL | 4,129,158 | UNDER 100 GALLONS | 29 | |