

SSO Notification List

August 2017

| Serial No. | Date of Occurrence | Location | Zip Code | Reason | Dry or Wet-Weather Overflow? | Stream Affected | Duration (Min) | Description of Discharge | Est. Quantity of Discharge (gallons) | Measures taken to Minimize Discharge | Preventive Action to Stop Recurrence | Work Order # |
|------------|--------------------|--|----------|---------------------|------------------------------|-----------------|----------------|---|--------------------------------------|--|---|--------------|
| 1 | 8/1/2017 | Wyndholme Cir & Wyndholme Way (Private) | 21228 | Rags, Grease, Trash | WWO | N/A | 22 | Water overflowing from the manhole in the street. | 66 | Relieved mainline choke with 145 ft of pressure hose. | Performed CCTV inspection. | 441689 |
| 2 | 8/1/2017 | N Charles St & W Lanvale St - SSO #152 | 21201 | Rain | WWO | Jones Falls | 95 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 229,000 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 3 | 8/3/2017 | 119 S Augusta St | 21229 | Roots | WWO | N/A | 45 | Cloudy water around the cleanout at the rear of the property. | 45 | Relieved house connection choke with 30 ft of electric cable. | Cleaned 200 ft of 8" mainline. | 442277 |
| 4 | 8/3/2017 | N Charles St & W Lanvale St - SSO #152 | 21201 | Rain | WWO | Jones Falls | 35 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 6,593 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 5 | 8/6/2017 | 2820 W North Ave | 21216 | Rags, Roots | DWO | N/A | 56 | Gray water flowing from the cleanout at the rear of the property. | 280 | Relieved house connection choke with 45 ft of electric cable. | Performed house lateral CCTV inspection. | 442951 |
| 6 | 8/7/2017 | N Charles St & W Lanvale St - SSO #152 | 21201 | Rain | WWO | Jones Falls | 25 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 4,550 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 7 | 8/8/2017 | 1303 Belt St | 21230 | Trash | WWO | N/A | 0 | Gray water observed around the manhole and in the street. | 15 | Relieved 8" mainline choke with 400 ft of pressure hose. | Pumped down the water valve vault at location. | 443493 |
| 8 | 8/9/2017 | 851 Braddish Ave | 21216 | Rags, Grease, Trash | WWO | N/A | 61 | Heavy grey water flowing out of the manhole | 305 | Relieved 8" mainline choke with 75 ft of pressure hose | Performed mainline CCTV inspection | 443663 |
| 9 | 8/12/2017 | 1901 Falls Rd - SSO #67 | 21217 | Rain | WWO | Jones Falls | 20 | Structure is monitored by metering equipment in the pipe. | 3,000 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital projects. | |
| 10 | 8/12/2017 | 428 E Preston St - SSO #72 | 21202 | Rain | WWO | Jones Falls | 85 | Structure is monitored by metering equipment in the pipe; not visually observed. | 264,000 | SSO structure; not applicable. | SSO structure will be closed upon completion of necessary capital projects. | |
| 11 | 8/12/2017 | W Garrison Ave & Queensberry Rd - SSO #139 | 21215 | Rain | WWO | Jones Falls | 25 | Structure is monitored by metering equipment in the pipe. Not visually observed. | 1,500 | SSO structure. Not applicable. | The SSO structure will be closed upon completion of necessary capital projects. | |
| 12 | 8/12/2017 | N Charles St & W Lanvale St - SSO #152 | 21201 | Rain | WWO | Jones Falls | 60 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 164,500 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital projects. | |
| 13 | 8/15/2017 | 428 E Preston St - SSO #72 | 21202 | Rain | WWO | Jones Falls | 130 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 464,500 | SSO Structure. Not applicable. | The SSO structure will be closed upon completion of necessary capital project. | |
| 14 | 8/15/2017 | 1901 Falls Rd - SSO #67 | 21217 | Rain | WWO | Jones Falls | 35 | Structure monitored by metering equipment in the pipe. Not visually observed. | 2,000 | SSO structure; not applicable. | The SSO Structure will be closed upon completion of necessary capital project. | |
| 15 | 8/15/2017 | N Charles St & W Lanvale St - SSO #152 | 21201 | Rain | WWO | Jones Falls | 65 | Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed. | 103,500 | SSO structure; not applicable. | The SSO structure will be closed upon completion of necessary capital project. | 0 |
| 16 | 8/16/2017 | Broening Hwy & O'Donnell St | 21224 | Rags, Grease, Trash | WWO | N/A | 75 | Water flowing from the manhole in the sidewalk. | 750 | Relieved 8" mainline choke with 210 ft of pressure hose. | Performed mainline CCTV inspection. | 444968 |
| 17 | 8/16/2017 | 3014 Frisby St | 21218 | Rags, Roots, Trash | WWO | N/A | 0 | Water observed around the cleanout and sidewalk at the front of the property. | 11 | Relieved house connection choke with 45 ft of electric cable and H-cutter. | Performed house lateral CCTV inspection. | 445304 |
| 18 | 8/16/2017 | 600 N Bradford St | 21205 | Rags, Grease | WWO | N/A | 1464 | Grey water around the manhole and in the street. | 1,464 | Relieved 8" mainline choke with 200 ft of pressure hose and replaced broken manhole. | Performed mainline CCTV inspection. | 445313 |
| 19 | 8/17/2017 | 3349 Falls Rd | 21211 | Rags | WWO | Jones Falls | 153 | Wastewater and paper flowing from front yard onto sidewalk. Dye test of cleanout confirmed house connection leak. | 3 | Relieved 6" house connection choke with 14 ft of electric cable and pressure hose. | Performed CCTV inspection and cleaned the mainline. | 445398 |

