

SSO Notification List

AUGUST 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	8/2/2018	2601 N Hilton St	21216	Rags, Roots, Grease	Wet	Gwynns Falls	49	Choked mainline causing sewage to escape out of the sewer line.	980	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	594079
2	8/3/2018	2617 Woodland Ave	21215	Rags, Roots, Trash	Wet	N/A	170	Gray water escaping the cleanout.	340	Relieved house connection choke with 45 ft of electric cable.	Confirmed mainline and lateral are clear.	595653
3	8/3/2018	1505 Woodbourne Ave	21239	Rags, Roots	Wet	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 45 ft of electric cable.	Confirmed mainline and lateral are clear.	595796
4	8/3/2018	3602 Cottage Ave	21215	Rags, Roots, Trash	Wet	N/A	242	Gray water and debris escaping the cleanout.	242	Relieved house connection choke with 60 ft of electric cable and expander cutter.	Performed CCTV inspection.	595838
5	8/3/2018	1719 W Lexington St	21223	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	595888
6	8/3/2018	629 E 38th St	21218	Rags, Roots, Trash	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	3	Relieved 6" house connection choke with 35 ft of electric cable.	Confirmed connection is clear.	595891
7	8/6/2018	644 S Lakewood Ave	21224	Trash, Sand, Gravel, Rocks, Structural	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Ran 11 ft of electric cable and auger. Removed debris but there is hard blockage in the lateral.	Performed CCTV inspection to determine obstruction or possible damage.	597672
8	8/8/2018	E 29th St & Guilford Ave	21218	Sand, Gravel, Rocks, Structural	Wet	N/A	0	Gray water observed around the manhole.	5	Relieved mainline choke with 300 ft of pressure hose and vacuum.	Performed CCTV inspection. Planning for mainline repair due to structural damage.	600059
9	8/8/2018	4700 N Franklinton Rd	21207	Trash	Wet	N/A	0	Debris observed around a manhole that had its cover blown off.	5	Replaced manhole cover and cleaned surrounding debris.	A large rock is in the manhole, obstructing some of the flow. This will be removed.	598120
10	8/10/2018	1525 Edmondson Ave	21223	Rags, Trash	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	600490
11	8/10/2018	1412 N Luzerne Ave	21213	Grease	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	600775
12	8/11/2018	3018 Virginia Ave	21215	Trash	Dry	N/A	0	Heavy water observed in the street.	10	Flushed and cleaned 8" mainline; removed debris.	Performed mainline CCTV inspection and dye test.	600991
13	8/11/2018	3216 Piedmont Ave	21216	Rags, Trash	Dry	N/A	227	Gray water escaping manhole.	1,135	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	600978
14	8/13/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	115	Structure monitored by metering equipment in pipe.	208,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
15	8/13/2018	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	195	Structure monitored by metering equipment in pipe.	106,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of capital projects.	
16	8/13/2018	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	20	Structure monitored by metered equipment in the pipe. Not visually observed.	1,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
17	8/13/2018	Queensberry Ave & W Garrison Ave - SSO Site #139	21215	Rain	Wet	Jones Falls	145	Structure monitored by metering equipment in pipe.	92,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of capital projects.	
18	8/13/2018	W Cold Spring Ln & Ayrdale Ave - SSO Site #138	21215	Rain	Wet	Jones Falls	155	Structure monitored by metering equipment in pipe.	69,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
19	8/13/2018	2311 Allendale Rd	21216	Rags, Roots	Wet	N/A	0	Heavy water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed mainline and lateral are clear.	601959
20	8/13/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	70	Structure monitored by metering equipment in pipe.	71,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	

SSO Notification List

AUGUST 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	8/13/2018	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	40	Structure monitored by metering equipment in pipe.	27,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
22	8/13/2018	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	40	Structure monitored by metering equipment in pipe.	19,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
23	8/14/2018	428 E Preston St	21202	Rags, Trash	Wet	N/A	163	Gray water escaping the cleanout at the front of the property.	815	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; mainline and lateral are clear.	602130
24	8/15/2018	1600 E Clement St	21230	Rags, Trash	Dry	N/A	39	Toilet paper and some water observed around the cleanout. Cleanout cap is missing.	39	Relieved house connection choke with 15ft of electric cable.	Confirmed mainline and lateral are clear. Performed CCTV analysis.	602984
25	8/16/2018	436 Kane St	21224	Rags, Grease	Dry	N/A	0	Water observed around the manhole.	5	Relieved 8" mainline choke with 80 ft of pressure hose.	Performed mainline CCTV inspection.	603133
26	8/17/2018	2303 Windsor Ave	21216	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved 6" house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	603420
27	8/20/2018	3408 Keene Ave	21214	Rags, Roots	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	10	Relieved house connection choke with 60 ft of electric cable.	Confirmed connection is clear; cleaned mainline.	604328
28	8/20/2018	3500 Chestnut Ave	21211	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	604330
29	8/21/2018	428 E Preston St	21202	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	20	Relieved choke with electric cable and pressure hose.	Confirmed connection is clear.	604614
30	8/22/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	105	Structure monitored by metering equipment in pipe.	564,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
31	8/22/2018	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	30	Structure monitored by metering equipment in pipe.	7,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of capital projects.	
32	8/22/2018	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	35	Structure monitored by metering equipment in pipe.	2,000	SSO structure. Not applicable.	he SSO structure will be closed upon completion of capital projects.	
33	8/22/2018	320 E 33rd St	21218	Rags, Roots, Trash	Wet	N/A	197	Gray water escaping the cleanout at the front of the property.	99	Relieved house connection choke with 45 ft of electric cable and cleaned surrounding area.	Performed CCTV inspection.	605023
34	8/22/2018	2552 Marbourne Ave	21230	Rags, Trash	Wet	N/A	0	Water observed around the manhole and sidewalk.	2	Relieved mainline choke with pressure hose.	Performed CCTV inspection.	605037
35	8/22/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	200	Structure monitored by metered equipment in the pipe. Not visually observed.	2,386,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
36	8/22/2018	1901 Falls Rd	21211	Rain	Wet	N/A	40	Water escaping manhole in the street.	6,000	Checked the area; overflow stopped after heavy rain event.	Location is equipped with an Event Notification System meter.	604736
37	8/22/2018	1731 E Chase St	21213	Rain	Wet	N/A	65	Water escaping manhole.	155,000	Checked the area; overflow stopped after heavy rain event.	Location is equipped with an Event Notification System meter.	604741
38	8/24/2018	835 Allendale St	21229	Rags, Roots, Trash, Sand, Gravel, Rocks	Dry	N/A	938	Heavy gray water escaping manhole.	9,380	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed CCTV inspection.	605928
39	8/28/2018	1200 N Franklinton Rd	21229	Rags, Roots, Trash	Dry	Gwynns Falls	97	Heavy sewage discharge from a hole in the ground under Hilton Parkway bridge.	2,425	Relieved 12" mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection. Confirmed line is clear.	607067
40	8/28/2018	4021 Belle Ave	21207	Rags, Trash, Structural	Dry	N/A	0	Gray water observed around the cleanout.	3	Relieved choke with electric cable; flushed and cleaned 8" mainline.	Marked location for further investigation for potential structural damage.	607106
41	8/29/2018	3700 Gough St	21224	Rags, Trash	Dry	N/A	0	Water and debris observed at the front of the property.	3	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	607854

