

SSO Notification List

December 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	12/1/2015	429 Westgate Rd	21229	Rags, Grease	WWO	N/A	57	Sewage and toilet paper overflowing from the clean out	285	Relieved house connection choke with 45' of electric machine	CCTV	282039
2	12/1/2015	836 Herndon Ct	21225	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Curtis Bay	155	Sewage and toilet paper overflowing from manhole	1,550	Relieved mainline choke with 75 ft of pressure truck on 8" line	CCTV	282112
3	12/2/2015	402 Key Hwy	21202	Grease	WWO	N/A	88	Water overflowing from sanitary line	440	Relieved mainline choke with pressure truck, SSO has been abated	CCTV	282310
4	12/2/2015	1412 N Luzerne Ave	21213	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Debris visible on top of and around clean out	Evidence of Overflow	Relieved house connection choke with electric machine.	CCTV	282229
5	12/3/2015	316 E Lafayette Ave	21202	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Paper and sewage noticeable around the clean out	Evidence of Overflow	Relieved house connection choke with H-cutter, removed trash and debris	CCTV	282422
6	12/3/2015	6100 The Alameda	21239	Roots, Grease	WWO	Herring Run	35	Sewage overflowing from manhole and running into the storm drain	175	Jetted line with 127 ft of pressure hose, relieved mainline choke with vactor truck	Line to be tved ASAP	282366
7	12/4/2015	142 S Monastery Ave	21229	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Toilet paper and debris visible around the house connection	Evidence of Overflow	Relieved house connection choke with 45' of electric machine	CCTV	282498
8	12/5/2015	2325 Arunah Ave	21216	Rags	DWO	N/A	Not Witnessed	Gray water and evidence visible around the house connection	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	282622
9	12/5/2015	7604 Bagley Ave	21234	Trash, Sand, Gravel, Rocks	DWO	N/A	126	Sewage overflowing from the front house connection	630	Used large auger and expanding cutter to relieve house connection choke	Damaged house connection, turned over for repairs	282611
10	12/5/2015	853 W University Pkwy	21210	Rags, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	85	A light but constant flow of sewage from the eyes of the man hole cover	85	Relieved mainline choke with pressure truck	CCTV	282632
11	12/5/2015	825 E Fort Ave	21230	Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	497	Grease and debris overflowing from manhole	1,988	Relieved mainline choke with 100' of pressure machine hose	CCTV	282643
12	12/5/2015	3723 Clarenell Rd	21229	Roots	DWO	N/A	179	Overflowing from the front house connection	1,790	Relieved house connection choke by using x cutter to remove roots	CCTV	282627
13	12/7/2015	3923 Boarman Ave	21215	Roots	DWO	N/A	Not Witnessed	Evidence of overflow, front house connection choke	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	282747
14	12/7/2015	3325 Northern Pkwy	21215	Rags	DWO	N/A	Not Witnessed	Evidence of overflow, front house connection choke	Evidence of Overflow	House connection choked, relieved tuner connection by initiating bypass pumping	CCTV	282802
15	12/7/2015	6541 Eastern Ave	21224	Rags, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	95	Sewer water overflowing from manhole	2,375	Relieved mainline choke with 150 ft of pressure truck on 15" line	CCTV	282881
16	12/7/2015	1805 Park Ave	21217	Rags, Grease	DWO	Jones Falls	194	Heavy gray water overflowing from the manhole on the sidewalk	970	Relieved mainline choke with 10 ft of pressure truck on 8" line	CCTV	282900

SSO Notification List

December 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	12/10/2015	Bonnie View Dr & Western Run Dr	21209	Rags, Pipe Break	DWO	Jones Falls	Not Witnessed	Sewage and gray water visible in wooded area	Evidence of Overflow	Relieved house connection choke with 50 ft of pressure truck on 6" line	CCTV, notified construction for repair	283279
18	12/10/2015	2730 W Lafayette Ave	21216	Rags, Roots	DWO	N/A	Not Witnessed	Sewage and debris around the clean out, wall, and alley	Evidence of Overflow	Relieved house connection choke with 30' of Electric Machine	CCTV	283281
19	12/11/2015	501 Hawthorn Rd	21210	Rags, Roots	DWO	N/A	Not Witnessed	Toilet paper and debris visible around the clean out	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	283423
20	12/12/2015	2800 Glen Ave	21215	Rags, Roots	DWO	N/A	229	Heavy gray water	1,145	Relieved mainline choke with 150 ft of pressure truck on 10" line	CCTV	283538
21	12/12/2015	1023 W Lombard St	21223	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Light paper around the clean out	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	283530
22	12/14/2015	2806 Roselawn Ave	21214	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Toilet paper and other evidence noticeable around the cleanout	Evidence of Overflow	Relieved house connection choke with electric machine and H-Cutter	CCTV	283731
23	12/14/2015	2900 Waterview Ave & Cherry Hill Rd	21230	Pipe Break	DWO	Patapsco River	249	Sewer line was damage by contractor causing a significant amount of sewage to escape the system	12,450	Bypass pumping was initiated to abate this overflow	Sewer line will be repaired, CCTV	283673
24	12/14/2015	1815 N Register St	21213	Rags	DWO	N/A	Not Witnessed	Evidence of overflow around the rear house connection.	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" line	House connection cleaned and flowing freely	283746
25	12/16/2015	2131 W Mulberry St	21223	Trash, Sand, Gravel, Rocks, Pipe Break	WVO	N/A	Not Witnessed	Heavy thick debris on the sidewalk and around the cleanout which is inside a water meter vault	Evidence of Overflow	Cleaned line with 3 ft of electric machine to relieve house connection choke	CCTV	284283
26	12/16/2015	2705 Steele Rd	21209	Rags, Roots	WVO	N/A	Not Witnessed	A large amount of sewage (black in color) in rear around the cleanout and yard	Evidence of Overflow	Pressure truck relieved choke with 150 ft of pressure hose	CCTV	284235
27	12/16/2015	2911 Waterview Ave	21230	Rags	WVO	Patapsco River	15	Sewage running from pump onto ground then into storm inlet	15	Sewage leaking from hose connected to pump, hose was redirected to sewer manhole	Moved hose so sewage is no longer running into inlet	289317
28	12/16/2015	5113 Falls Rd	21210	Pipe Break	DWO	Jones Falls	131,195	Sewage overflowing into storm drain At this location. Verified by dye testing. (Ongoing since 9/16/2015)	32,798	Construction repaired mainline and manhole, SSO is no longer ongoing	SSO is no longer ongoing, manhole and pipe have been repaired.	271658
29	12/18/2015	802 W Saratoga Ave	21201	Rags, Grease	DWO	N/A	57	A low volume of sewer water coming from around the sanitary manhole	285	Relieved mainline choke with 175 ft of pressure truck on 8 inch line	CCTV	284769
30	12/19/2015	200 S Ballou Ct	21231	Rags, Roots, Grease	WVO	Inner Harbor	227	Heavy gray water flowing out of the manhole due to mainline choke	2,270	Relieved mainline choke with 300 ft of pressure truck on 8" line	CCTV	284923
31	12/21/2015	1307 W Northern Pkwy	21210	Rags, Roots	DWO	N/A	Not Witnessed	Evidence of overflow around the rear house connection. There is a choke	Evidence of Overflow	Relieved rear house connection choke with 45' of electric machine	CCTV	285030

SSO Notification List

December 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
32	12/22/2015	Edmondson Ave and N Hilton St	21229	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	70	Sewage overflowing from sewer manhole at this location	350	Relieved mainline choke with 300' of pressure machine hose	CCTV	285117
33	12/23/2015	1142 Shields Pl	21201	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	196	Heavy gray water flowing from manhole	980	Relieved mainline choke with 110 ft of pressure truck on 8" line	CCTV	285305
34	12/24/2015	207 S Smallwood Rd	21223	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Toilet paper and sewage visible around the clean out at this location	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	285418
35	12/24/2015	2700 Boston St	21231	Rags, Grease	WWO	Inner Harbor	159	Gray water and grease overflowing from manhole	636	Relieved mainline choke with 500 ft of pressure machine hose	CCTV	285431
36	12/25/2015	2804 Belmont Ave	21216	Rags, Roots	WWO	N/A	79	Heavy gray water	395	Relieved mainline choke with 200 ft of pressure truck on 8" line	CCTV	285484
37	12/25/2015	1700 Chase St	21213	Rags, Rain, Trash, Sand, Gravel, Rocks	WWO	Inner Harbor	168	Heavy gray water overflowing from manhole in center of street	16,800	Affected area was cleaned, public notification signs were placed by manhole and affected area	No CCTV / Will monitor location during heavy rains	285492
38	12/25/2015	1500 Orleans St	21231	Grease	WWO	N/A	Not Witnessed	Sewage and debris visible around the manhole	Evidence of Overflow	Area around manhole was cleaned, sewage and debris no longer present	Will monitor location during wet weather events	285509
39	12/28/2015	1201 Woodington Rd	21229	Pipe Break	WWO	Dead Run	389	Gray sewage from break in sewer line crossing stream. Found during routine sampling by OCAL	3,890	Sewer mainline break, capped the end of leaking pipe. Turned over to construction for repairs	CCTV	285766
40	12/28/2015	4210 Anntana Ave	21206	Rags, Roots	WWO	N/A	Not Witnessed	Heavy debris	Evidence of Overflow	Relieved house connection choke with 45 ft of pressure truck on 6" line	CCTV	285806
41	12/28/2015	1800 Falls Rd	21201	Rags, Rain, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Heavy gray debris	Evidence of Overflow	Affected area was cleaned and signs were placed to alert public of overflow	No CCTV / Will monitor during heavy rain events	285724
42	12/29/2015	1201 Woodington Rd	21229	Pipe Break	WWO	Dead Run	181	Heavy gray water	905	Construction repaired mainline	CCTV	285766
43	12/29/2015	709 N Rosedale St	21216	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Heavy gray debris	Evidence of Overflow	Evidence of an overflow. Manhole needs repair, 24" manhole	No CCTV / Will monitor during heavy rain events	285906
44	12/29/2015	3517 Oakmont Ave	21215	Rags, Roots, Grease	WWO	N/A	128	Sewage overflowing	640	Relieved house connection choke with 30 ft of electric machine on 6" line	CCTV	285933
45	12/29/2015	1109 N Carey St	21217	Pipe Break	WWO	N/A	Not Witnessed	Evidence of overflow at location	Evidence of Overflow	Ran 12 ft of Electric Machine to relieve house connection choke	CCTV	285945

SSO Notification List

December 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
46	12/30/2015	709 N Rosedale St	21216	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Heavy debris	Evidence of Overflow	Evidence of overflow, debris visible around the manhole	No CCTV	286080
47	12/30/2015	710 N Payson St	21217	Rags	WWO	N/A	Not Witnessed	Heavy debris	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" line	CCTV	286082
48	12/31/2015	2419 Ken Oak Rd	21209	Rags, Roots	WWO	N/A	Not Witnessed	Toilet Paper	Evidence of Overflow	Relieved house connection choke with 75 ft of electric machine cable	CCTV	286271
49	12/31/2015	1300 Parkman Ave	21230	Rags, Roots	WWO	N/A	Not Witnessed	Rags & Roots	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine	CCTV	286305
				# WWO	29			TOTAL	83,847	EVIDENCE ONLY	25	