

**SSO Notification List**

**December 2017**

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	12/1/2017	3902 Maine Ave	21207	Rags, Grease	Dry	N/A	135	Heavy gray water escaping the cleanout at the rear of the property.	270	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection; flushed and cleaned 8" mainline.	473834
2	12/1/2017	430 Ilchester Ave	21218	Rags, Grease, Trash	Dry	N/A	42	Grey water and grease flowing from the cleanout.	84	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	473839
3	12/4/2017	2204 W Lexington St	21223	Rags, Roots	Dry	N/A	205	Gray water coming out of the cleanout at the rear of the property.	410	Relieved house connection choke with 60 ft of electric cable, expander, and auger.	Performed house lateral CCTV inspection; flushed and cleaned 8" mainline.	474329
4	12/6/2017	2211 Clifton Ave	21216	Rags, Roots, Trash	Wet	N/A	0	Heavy gray water and debris observed around the cleanout.	6	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	474742
5	12/6/2017	6608 Danville Ave	21224	Rags, Trash	Wet	N/A	0	Water observed near cleanout.	4	Relieved house connection choke with 30 ft of electric cable and expander.	Performed house lateral CCTV inspection.	474834
6	12/7/2017	6301 Brook Ave	21206	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout and street at the front of the property.	11	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline is clear.	475477
7	12/7/2017	410 Brunswick St	21223	Rags, Grease, Trash	Wet	Gwynns Falls	194	Gray water discharging from manhole into stream.	5,820	Relieved mainline choke with pressure hose.	Performed CCTV inspection.	475493
8	12/7/2017	2801 Frederick Ave	21223	Rags, Grease, Trash, Sand, Gravel, Rocks, Structural	Wet	N/A	276	Gray water overflowing from manhole.	5,520	Relieved mainline choke with pressure hose.	Performed CCTV inspection; began repair for structural damage.	475637
9	12/7/2017	428 E Preston St	21202	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout and sidewalk at the front of the property.	15	Relieved house connection choke with pressure hose.	Performed house lateral CCTV inspection; flushed and cleaned 8" mainline.	475578
10	12/7/2017	1745 E Preston St	21213	Rags, Trash	Wet	N/A	0	Gray water observed near the cleanout.	6	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection; cleaned the mainline.	475588
11	12/8/2017	2611 Fairview Ave	21215	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	9	Ran 75 ft of electric cable in lateral; flushed and cleaned 8" mainline.	Left notice for possible issue on the consumer's side.	476012
12	12/11/2017	150 N Monastery Ave	21229	Rags, Grease, Trash	Wet	Gwynns Falls	121	Gray water overflowing from manhole into storm drain.	605	Relieved 8" mainline choke with 50 ft of pressure hose.	Performed mainline CCTV inspection.	476302
13	12/11/2017	2303 James St	21230	Rags, Roots, Trash	Wet	N/A	1,193	Heavy gray water escaping the manhole.	1,193	Relieved mainline choke with 155 ft of pressure hose.	Performed mainline CCTV inspection and dye test.	480498
14	12/11/2017	2822 Round Rd	21225	Rags, Grease, Trash	Wet	N/A	157	Heavy gray water escaping the manhole.	785	Relieved 8" mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	481329
15	12/11/2017	Hillen Rd & Lydonlea Way	21239	Roots, Grease	Wet	Herring Run	83	Gray water escaping manhole in the street.	166	Relieved 10" mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection.	476328
16	12/11/2017	4315 Lasalle Ave	21206	Rags, Grease, Trash	Wet	N/A	455	Heavy gray water discharging from cleanout.	910	Relieved house connection choke with 105 ft of electric cable; flushed and cleaned 8" mainline with 250 ft of pressure hose.	Performed CCTV inspection; abatement confirmed by Office of Compliance and Laboratories.	481358
17	12/12/2017	410 Brunswick St	21223	Rags, Trash, Sand, Gravel, Rocks	Wet	Gwynns Falls	248	Gray water overflowing from manhole under bridge.	1,240	Relieved mainline choke with pressure hose; scheduled contractor for location.	Performed CCTV inspection.	481652
18	12/13/2017	5622 Frankford Ave	21206	Rags, Roots, Grease	Dry	Herring Run	0	Gray water observed around the cleanout and alley at the rear of the property.	18	Relieved house connection choke with 45 ft of electric cable; flushed and cleaned 8" mainline.	Performed house lateral and mainline CCTV inspections.	481856
19	12/16/2017	102 W Jeffrey St	21225	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	490518

## SSO Notification List

December 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	12/17/2017	5098 Orville Ave	21205	Rags, Grease, Trash	Wet	N/A	720	Heavy gray water flowing from manhole in the street.	3,600	Relieved 15" mainline choke with 175 ft of pressure hose.	Performed mainline CCTV inspection.	490612
21	12/19/2017	5024 Denview Way	21206	Rags, Trash	Dry	N/A	0	Gray water observed on the property.	25	Relieved 8" mainline choke using pressure hose.	Performed mainline CCTV inspection.	501448
22	12/20/2017	16 E 23rd St	21218	Trash, Structural	Dry	Jones Falls	172	Gray water discharging from cleanout at the rear of the property.	344	Relieved choke with 13 ft of electric cable. Water turned off at property while construction repairs small damage to lateral.	Performed CCTV inspection; flushed and cleaned 8" mainline.	501658
23	12/20/2017	4501 Penhurst Ave	21215	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV connection.	501583
24	12/20/2017	5311 Catalpha Rd	21214	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the rear of the property.	35	Relieved 8" mainline choke with 285 ft of pressure hose.	Performed mainline CCTV inspection.	502761
25	12/21/2017	Chesterfield Ave & Kavon Ave	21213	Structural	Dry	Herring Run	0	Sanitary sewer mainline joint is leaking wastewater into adjacent storm drain.	0	Flushed mainline and performed CCTV inspection.	Performed dye test and scheduled repairs on storm drain and pipe.	502961
26	12/21/2017	2548 Aisquith St	21218	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout.	4	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	503058
27	12/22/2017	428 Arsan Ave	21225	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout.	6	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV connection.	503264
28	12/23/2017	2922 E Northern Pkwy	21234	Rags	Wet	N/A	0	Heavy gray water and rags observed around the cleanout at the front of the property.	11	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection; confirmed mainline is clear.	503327
29	12/23/2017	102 W Jeffrey St	21225	Rags	Wet	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	7	Relieved 6" house connection choke with 45 ft of electric cable.	Performed house lateral CCTV connection; cleaned 8" mainline.	503309
30	12/26/2017	1402 Woodall St	21230	Rags, Grease, Trash	Wet	Harbor	0	Water observed near the cleanout at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral and mainline CCTV inspections.	503461
31	12/26/2017	726 E 36th St	21218	Rags, Roots, Trash	Wet	N/A	0	Water observed around cleanout and sidewalk at the front of the property.	7	Relieved house connection choke with 50 ft of electric cable; flushed 8" mainline.	Performed house lateral and mainline CCTV inspections.	504112
32	12/27/2017	2410 St Paul St	21218	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 18 ft of electric cable.	Confirmed connection and mainline are clear.	504364
33	12/28/2017	1412 Darley Ave	21218	Rags, Roots, Trash	Dry	N/A	0	Gray water observed at the rear of the property in the alley.	25	Ran 15 ft of electric cable through house connection.	Performed CCTV inspection; cleaned mainline.	504582
34	12/30/2017	3748 Old York Rd	21218	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	20	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	504951
35	12/30/2017	1525 Edmondson Ave	21223	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	20	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	504956
36	12/31/2017	402 Key Hwy	21230	Rags, Grease, Trash	Dry	N/A	44	Gray water escaping the manhole in the street.	880	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	505132
				# WWO	20			TOTAL	22,071	UNDER 100 GALLONS	30	