

SSO Notification List

DECEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	12/1/2018	2800 Rosalind Ave	21215	Rags, Roots, Grease, Trash	Wet	N/A	0	Heavy gray water observed at the rear of the property.	10	Relieved choke with 200 ft of pressure hose.	Confirmed lines are clear.	645301
2	12/5/2018	1011 N Hilton St	21229	Rags, Grease, Sand, Gravel, Rocks	Wet	Gwynns Falls	192	Sewage surcharging from manhole in woods next to stream.	4,800	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	646200
3	12/5/2018	320 W 29th St	21211	Rags	Wet	N/A	109	Heavy gray water observed around the cleanout.	218	Relieved house connection choke with 10 ft of electric cable.	Performed lateral CCTV inspection.	646283
4	12/5/2018	Joh Ave & Benson Ave	21227	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	5	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	646421
5	12/6/2018	2701 Spelman Rd	21225	Rags, Roots, Trash	Dry	N/A	0	Heavy gray water observed around the manhole in the street.	15	Relieved 8" mainline choke with 250 ft of pressure hose.	Performed mainline CCTV inspection.	646459
6	12/6/2018	428 E Preston St	21202	Rags, Grease, Trash	Dry	Jones Falls	405	Water escaping the cleanout and entering a nearby storm drain.	810	Relieved house connection and mainline chokes with 45 ft of electric cable.	Confirmed lines are clear.	646639
7	12/6/2018	3202 Windsor Ave	21216	Rags, Roots	Dry	N/A	0	Water observed around the cleanout.	5	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	646717
8	12/6/2018	5115 Saint Georges Ave	21212	Rags, Roots, Trash	Dry	N/A	0	Water observed around the cleanout.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned mainline.	646691
9	12/7/2018	2920 Norfolk Ave	21215	Rags, Roots, Grease	Dry	N/A	78	Heavy gray water escaping the manhole.	390	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed CCTV inspection.	646778
10	12/10/2018	810 N Hilton St	21229	Rags, Grease, Trash	Dry	Gwynns Falls	130	Surcharging manhole flowing into storm inlet.	3,900	Relieved 8" mainline choke with 75 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	647360
11	12/10/2018	2716 Saint Paul St	21218	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	5	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	647796
12	12/11/2018	505 W University Pkwy	21210	Rags, Roots	Dry	N/A	91	Heavy gray water escaping the manhole.	2,275	Relieved mainline choke with 200 ft of pressure hose.	Performed CCTV inspection.	647888
13	12/13/2018	1525 Edmondson Ave	21223	Rags, Trash	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	30	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	648608
14	12/14/2018	2032 E 30th St	21218	Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	8	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	649692
15	12/15/2018	1901 Falls Rd	21211	Rain, Trash	Wet	Jones Falls	660	Heavy gray water escaping manholes.	33,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	650340
16	12/15/2018	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	35	Structure monitored by metered equipment in the pipe. Not visually observed.	1,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
17	12/15/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	1,320	Structure monitored by metered equipment in the pipe. Not visually observed.	3,644,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
18	12/15/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1,535	Structure monitored by metered equipment in the pipe. Not visually observed.	16,087,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
19	12/15/2018	3900 Belair Rd	21206	Rain	Wet	Herring Run	1,160	Manhole adjacent to creek overflowed due to heavy rain.	455,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
20	12/16/2018	1901 Falls Rd	21218	Rain, Trash	Wet	Jones Falls	225	Gray water escaping manholes.	5,625	Conditions returned to normal following heavy rain event.	Location is equipped with an Event Notification System meter.	650426

SSO Notification List

DECEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	12/17/2018	3100 Chestnut Ave	21211	Rags, Trash	Wet	N/A	0	Gray water observed around the manhole.	20	Relieved mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	650484
22	12/18/2018	1628 Braddish Ave	21216	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	650968
23	12/18/2018	101 Kane St	21224	Rags	Wet	N/A	0	Water observed around the cleanout at the rear of the property.	4	Ran 110 ft of electric cable.	Confirmed mainline is clear.	650984
24	12/19/2018	3000 Shannon Dr	21213	Rags, Grease, Trash	Wet	Herring Run	58	Gray water escaping manhole.	1,450	Relieved 8" mainline choke with 385 ft of pressure hose.	Performed mainline CCTV inspection.	651213
25	12/19/2018	4803 Lindsay Rd	21229	Rags	Wet	N/A	0	Heavy gray water observed around the cleanout.	6	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	651242
26	12/20/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	810	Structure monitored by metering equipment in the pipe. Not visually observed.	7,040,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
27	12/20/2018	3900 Belair Rd	21206	Rain	Wet	Herring Run	200	Manhole adjacent to creek overflowed due to heavy rain.	2,113,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
28	12/21/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	205	Structure monitored by metering equipment in the pipe.	503,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
29	12/21/2018	3404 Glen Ave - SSO Site #155	21215	Rain	Wet	Jones Falls	110	Structure monitored by metered equipment in the pipe. Not visually observed.	2,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
30	12/21/2018	1901 Falls Rd	21218	Rain	Wet	Jones Falls	15	Heavy gray water escaping manholes.	8,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	651656
31	12/21/2018	6 Hillside Rd	21210	Rags, Roots, Grease	Wet	N/A	183	Gray water escaping the manhole.	4,575	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed CCTV inspection; confirmed line is clear.	651755
32	12/23/2018	1829 Penrose Ave	21223	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	652042
33	12/25/2018	200 E 32nd St	21218	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout.	45	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	652333
34	12/26/2018	1906 Ramblewood Rd	21239	Rags, Grease	Dry	N/A	0	Water observed around the cleanout at the front of the property.	50	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	652567
35	12/27/2018	5000 Division St	21207	Rags, Roots, Rain, Trash	Dry	N/A	1,054	Gray water escaping the manhole.	5,270	Relieved 8" mainline choke with 400 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	652963
36	12/28/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	405	Structure monitored by metering equipment in the pipe. Not visually observed.	1,392,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
37	12/28/2018	4904 Woodside Rd	21229	Sand, Gravel, Rocks, Structural	Wet	N/A	0	Gray water observed around the cleanout.	5	Ran electric cable through lateral; identified structural damage.	Set up bypass pump to prevent backups while repairs are made to the lateral.	653278
38	12/29/2018	808 N Hilton St	21229	Rags, Roots, Grease	Wet	Gwynns Falls	310	Gray water escaping the manhole.	3,100	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	653381
39	12/30/2018	1211 W Northern Pkwy	21210	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	15	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	653471
40	12/30/2018	200 E 32nd St	21218	Rags, Roots	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	30	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	653481
41	12/31/2018	1043 W Lanvale St	21217	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	25	Relieved 6" house connection choke with 60 ft of electric cable.	Confirmed mainline and lateral are clear.	653498

