

SSO Notification List

February 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/3/2019	3903 8th St	21225	Rags, Roots, Grease, Trash	Dry	Harbor	67	Colored water escaping the cleanout at the front of the property.	134	Flushed and cleaned 8" mainline with 25 ft of pressure hose.	Performed CCTV inspection to determine possible damage to the pipe.	667583
2	2/4/2019	428 E Preston St	21218	Rags, Grease, Trash	Dry	N/A	246	Gray water escaping the cleanout at the front of the property.	123	Relieved 6" line choke with 75 ft of pressure hose.	Performed CCTV inspection.	667821
3	2/4/2019	504 S Clinton St	21224	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout.	10	Relieved house connection choke with 35 ft of electric cable.	Confirmed connection is clear.	667883
4	2/5/2019	436 Kane St	21224	Rags, Trash	Dry	N/A	1,503	Gray water escaping the manhole in the street.	752	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Performed mainline CCTV inspection.	668241
5	2/5/2019	3738 Manchester Ave	21215	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	8	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed the mainline.	668179
6	2/6/2019	6714 Holabird Ave	21222	Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	10	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	668427
7	2/6/2019	4252 Shamrock Ave	21206	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	668564
8	2/7/2019	6500 E Lombard St	21224	Trash	Wet	Herring Run	297	Gray water escaping the manhole and entering a storm drain.	7,425	Relieved mainline choke with pressure hose.	Performed CCTV inspection.	668774
9	2/8/2019	5924 Smith Ave	21209	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	7	Relieved house connection choke with 60 ft of electric cable; flushed 8" mainline.	Performed CCTV inspection; confirmed lateral and mainline are clear.	669231
10	2/9/2019	1248 N Gay St	21213	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	669382
11	2/12/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	735	Structure monitored by metering equipment in pipe.	2,987,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
12	2/12/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	190	Structure monitored by metering equipment in pipe.	207,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
13	2/14/2019	2850 Round Rd (Private)	21225	Rags, Trash	Wet	N/A	0	Water observed around the manhole.	2	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	671242
14	2/15/2019	3822 Ferndale Ave	21207	Roots	Wet	N/A	0	Water and debris observed around the cleanout at the front of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned mainline.	671350
15	2/15/2019	1820 Spence St	21230	Rags, Roots, Grease, Trash	Wet	Gwynns Falls	61	Heavy gray water escaping the manhole in the street.	610	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	671532
16	2/16/2019	110 S Clinton St	21224	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the rear cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	671713
17	2/16/2019	3708 7th St	21225	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	6	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	671741
18	2/17/2019	6011 Falls Rd	21209	Rags, Trash, Structural	Dry	Jones Falls	3,150	Heavy gray water running in the street.	6,300	Relieved choke with pressure hose. Investigating potential structural damage to pipe.	Performed CCTV inspection.	671768
19	2/18/2019	2529 Oswego Ave	21215	Rags, Grease, Trash, Other	Wet	N/A	117	Gray water escaping the manhole.	936	Relieved 8" mainline choke with 400 ft of pressure hose.	Performed mainline CCTV inspection.	671825
20	2/18/2019	5108 The Alameda	21239	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the manhole in the street.	20	Relieved 8" mainline choke with 425 ft of pressure hose.	Performed mainline CCTV inspection.	671835

SSO Notification List

February 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	2/18/2019	6309 Eunice Ave	21214	Rags, Roots	Wet	N/A	0	Cloudy gray water observed around the cleanout.	7	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	671842
22	2/18/2019	2724 Wilkens Ave	21223	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	5	Relieved house connection choke with 2 ft of electric cable.	Confirmed mainline and lateral are clear.	671851
23	2/18/2019	4213 Menlo Dr	21215	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout.	9	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; flushed the mainline.	671866
24	2/19/2019	436 Kane St	21224	Grease, Trash	Wet	N/A	119	Gray water escaping the manhole in the street.	2,975	Flushed and cleaned 8" mainline with 180 ft of pressure hose.	Performed CCTV inspection.	671881
25	2/19/2019	659 E 25th St	21218	Structural	Wet	Jones Falls	0	Sanitary lateral leaking into an adjacent storm drain pipe.	0	Determining extent of structural damage and plan for long-term solution.	Eventual lining of the pipe will prevent any further escape of sewage into the storm drain.	
26	2/19/2019	2001 Broening Hwy	21224	Grease, Trash, Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the manhole.	57	Relieved 8" mainline choke with pressure hose.	Performed CCTV inspection.	672206
27	2/19/2019	4123 Roland Ave	21211	Rags, Roots, Grease	Wet	N/A	1,801	Heavy gray water escaping the manhole.	9,005	Relieved mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	672249
28	2/21/2019	201 N Central Ave	21231	Rags, Trash	Wet	Harbor	94	Gray water escaping the cleanout and entering the storm drain.	1,410	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; cleaned the mainline.	673149
29	2/22/2019	1703 S Clinton St	21224	Rags, Trash	Wet	N/A	128	Gray water escaping the cleanout.	512	Relieved house connection choke with 60 ft of electric cable.	Confirmed mainline and lateral are clear.	673361
30	2/22/2019	6218 Woodcrest Ave	21209	Rags, Roots, Trash	Wet	N/A	228	Gray water escaping the manhole.	456	Relieved 8" mainline choke with 400 ft of pressure hose.	Confirmed mainline is clear.	673543
31	2/22/2019	2731 N Calvert St	21218	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	10	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Confirmed mainline is clear.	673538
32	2/23/2019	708 Glen Allen Dr	21229	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	6	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	673604
33	2/24/2019	2200 N Forest Park Ave	21207	Trash, Other	Wet	Gwynns Falls	61	Gray water escaping the manhole.	610	Removed blockage from storm drain area, allowing flow to return to normal.	Performed CCTV inspection.	673714
34	2/24/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	225	Structure monitored by metering equipment in the pipe. Not visually observed.	71,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
35	2/25/2019	1707 Brunt St	21217	Rags, Trash	Wet	N/A	121	Gray water escaping the manhole.	242	Relieved mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	674004
36	2/26/2019	2107 E Lombard St	21231	Trash	Wet	N/A	0	Gray water observed around the rear of the property.	10	Ran electric cable, equipment broke in the pipe, bypass set up to prevent further overflow.	Pipe will eventually be cleared of all obstructions.	674092
37	2/26/2019	432 Kane St	21224	Rags, Grease, Trash	Wet	N/A	335	Gray water escaping the manhole in the street.	670	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed CCTV inspection.	674347
38	2/27/2019	6320 Wirt Ave	21215	Structural	Wet	N/A	0	Sanitary Sewer pipe leaking into adjacent storm drain.	0	Determining extent of structural damage and plan for long-term solution.	Eventual lining of the pipe will prevent any further escape of sewage into the storm drain.	
39	2/27/2019	200 Font Hill Ave	21223	Rags, Roots, Grease, Trash	Wet	Gwynns Falls	249	Heavy gray water escaping the manhole.	2,490	Relieved 8" mainline choke with 400 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	674495
40	2/27/2019	3500 Parkdale Ave	21211	Other	Wet	Jones Falls	1,350	Sewage ejector pump stopped working. Pump basin overflowing sewage into storm drain.	1,350	Bypass pump was maintained and brought back to normal operation.	Long-term solution is being designed. Bypass pump is preventing SSO.	
				# WWO	31			TOTAL	3,301,180	UNDER 100 GALLONS	19	